Rico 60 Auto Services Pte Ltd . Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875 , Email: claims@rico60.com
Tel: 6286 6060 , FAX: 6286 7060

RICO60 AUTO SERVICES

VECHICLE NUM:	SMA 6377 P
MAKE & MODEL:	HONDA SHUTTLE
MILEAGE:	
TYRE:	
CHASSIS NUM:	

ATTN:

NO.	DESCRIPTION - PARTS	QTY	PRICE
1	FRONT BUMPER DO/DE ✓	1	
2	FRONT BUMPER RETAINER L+R As Req 4C	2	
3	FRONT BUMPER BRACKET L+R 11 X	2	
4	FRONT BUMPER GRILLE 11 X	1	
5	FRONT BUMPER FOG LAMP LH 11 X	1	
6	FRONT BUMPER FOG LAMP GRILLE LH 11 X	1	
7	FRONT BUMPER REINFORCEMENT BAR 11 X	1	
8	FRONT BUMPER SPONGE 11 X	1	
9	FRONT BUMPER UNDERCOVER 11 X	1	
10	HEADLAMP LH 11 X	1	
11	HEADLAMP BRACKET LH 11 X	1	
	SUBTOTAL		$ -
	LESS 20%		$ -
	PARTS TOTAL		$ -
	SPECIAL NETT	**QTY**	**PRICE**
1	FRONT BUMPER CLIPS Nett 50	10	$ 100.00
	SPECIAL NETT TOTAL		$ 100.00
	LABOUR	**QTY**	**PRICE**
1	TO RNR ACCIDENT DAMAGE PARTS,CUT/WELD ,KNOCK&REALIGN 150	1	$ 500.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA 200	1	$ 500.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA 11 X	1	$ 120.00
4	TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS 20 L	1	$ 120.00
5	TO CHECK WIRING LAYOUT AND FOG LAMP FUNCTION	1	$ 120.00
	LABOUR TOTAL		$ 1,360.00
	GRAND TOTAL COST		$ 1,460.00

Not Approved
29/1/19 @ 11am.
Take 3rd. After repair
2 day.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: