Rico 60 Auto Services Pte Ltd . Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875 , Email: claims@rico60.com
Tel: 6286 6060 , FAX: 6286 7060

RICO60 AUTO SERVICES

VECHICLE NUM:	GBC 3722 R
MAKE & MODEL:	NISSAN CABSTAR
MILEAGE:	
TYRE:	
CHASSIS NUM:	

ATTN:

NO.	DESCRIPTION - PARTS	QTY	PRICE
	TAILLAMP RH		$ 780.00
	TAILLAMP BRACKET RH		$ 242.80
	REAR NUMBER PLATE BRACKET		$ 131.20
	REAR FLOOR PANEL		$ 1,918.50
	REAR FLOOR PANEL END PANEL		$ 890.00
	FRONT CABIN REAR PANEL		$ 2,140.00
	SUBTOTAL		$ 6,102.50
	LESS 10%		$ 610.25
	PARTS TOTAL		$ 5,492.25
	SPECIAL NETT	**QTY**	**PRICE**
	REAR NUMBER PLATE		$ 80.00
	REAR DOOR ASSY RH		$ 3,500.00
	REAR DOOR HINGE RH		$ 400.00
	REAR DOOR PILLAR COMPLETE SET - ALLUMINIUM PLATE		$ 8,000.00
	REAR DOOR LOCK RH		$ 350.00
	REAR DOOR CATCH RH		$ 150.00
	REAR FLOOR BOARD		$ 1,200.00
	REAR CABIN SEALANT		$ 500.00
	REAR STEP BAR		$ 1,600.00
	REVERSE SENSOR SET		$ 250.00
	SPECIAL NETT TOTAL		$ 16,030.00
	LABOUR	**QTY**	**PRICE**
	TO RNR ACCIDENT DAMAGE PARTS,CUT/WELD ,KNOCK&REALIGN		$ 1,800.00
	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA		$ 1,600.00
	TO RUST PROOF ACCIDENT AFFECTED AREA		$ 150.00
	TO RNR REVERSE SENSOR AND CHECK FUNCTION		$ 80.00
	TO CHECK WIRING LAYOUT AND TAILLAMP FUNCTION		$ 80.00
	LABOUR TOTAL		$ 3,710.00
	GRAND TOTAL COST		$ 25,232.25

K Auto Consultants Pte Ltd notify
o Repairer of the following:
o resurvey/colour/underspray/painting
o display damaged part(s) during resurvey
Parts prices are subject to confirmation
Third party survey is on a "Without Prejudice" basis
No illegal modification(s) is allowed
Supplementary item(s) must be resurveyed and
s subject to final approval from Insurance Company

knowledged by Repairer
gnature:
ate: