MY CAR CONSULTANT PTE LTD

MYCAR CONSULTANT

Reg no.: 201605878Z

Address: 53 Ubi Ave 1 #01-33 Paya Ubi Industrial Park Singapore 408934

HP: 98888885

LKK Auto Consultants hence notify the Repairer of the following:
- To resume [illegible] after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimate

Date: 12 February 2019

Vehicle: SKT5827M

Make / Model: MAZDA 3

Chassis: JM6BM42A8G0311801

No.	Description	Unit	Unit Price	Amount	
	Parts Replacement:				
1	BOOTLID X repair.	1		$ 1,026.70	X
2	BOOTLID EMBLEM LOGO	1		$ 65.80	/
3	BOOTLID EMBLEM-MAZDA } MCC.	1		$ 44.40	/
4	BOOTLID EMBLEM-3	1		$ 32.50	/
5	BOOTLID LAMP X	2		$ 597.10	X
6	BOOTLID LOCK X	1		$ 256.40	X
7	BOOTLID LOCK CATCH X } NN	1		$ 112.90	X
8	BOOTLID HINGE X	2		$ 113.80	X
9	BOOTLID DAMPER X	2		$ 171.40	X
10	BOOTLID RUBBER X	1		$ 130.60	X
11	END PANEL ? / DMC	1		$ 548.10	447.6 /
12	END PANEL TOP GANRISH ? / RC	1		$ 179.45	/
13	REAR BUMPER / RC.	1		$ 1,074.80	/
14	REAR BUMPER REFLECTOR X	2		$ 154.90	X
15	REAR BUMPER SIDE RETAINER X } NN	2		$ 134.30	X
16	REAR BUMPER BRACKET INNER X	2		$ 121.10	X
17	REAR BUMPER REINFORCEMENT ? / RT	1		$ 591.70	541.7 /
18	REAR TAILLAMP LH - DR. RH X NN	2		$ 2,338.40	849.6 /
19	SPARE TYRE TOP BOARD X NN	1		$ 453.60	X
				$ 8,147.95	3235.85
			Less 20%	$ 1,629.59	
				$ 6,518.36	2588.68
	S/NETT ITEMS				
20	REAR BUMPER CLIP / MC.	1 SET		$ 50.00	30
21	REAR REVERSE SENSOR X NN	1 SET		$ 400.00	200
22	JOINT SEALANT ? / MC	1		$ 150.00	40
				$ 600.00	270
			Parts Total:	**$ 7,118.36**	
	Labour to:				
23	CHECK REAR WIRING AND LIGHTNING SYSTEM			$ 60.00	30
24	REMOVE AND REFIT REAR LINING, TRIM AND LINING			$ 150.00	60
25	REMOVE AND RENEW REAR REVERSE SENSOR			$ 150.00	40
26	REMOVE AND STRAIGHTEN REAR EXHAUST			$ 150.00	X NN.
27	TRANSFER PARTS, ATTACHMENT FROM OLD BOOTLID TO NEW			$ 200.00	60
28	PANEL BEATING ON AFFECTED AREAS			$ 1,200.00	~~[illegible]~~ 500
29	SPRAY PAINTING ON AFFECTED AREAS			$ 1,000.00	600
30	APPLY ANTI RUST ON AFFECTED AREAS			$ 150.00	60
				$ 3,060.00	1350
			Grand total:	**$ 10,178.36**	

5 Days.

Lumpsum Repair. 13/2/19.

After repair photos.

Enquiry - 82880282

4208.68

20% : 3350