c

A

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443
TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D   GST REG:200707743D

11-Feb-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8473 K

1 pc	O/s headlamp		$	1,028.00
1 pc	Front bumper		$	531.00
1 pc	Front bumper emblem		$	44.00
1 pc	Front bumper n/s & o/s protector		$	51.00
1 pc	Front bumper n/s & o/s fog lamp cover		$	66.00
1 pc	Front bumper o/s & n/s side retainer		$	16.00
			$	1,736.00
		Less 10%	$	173.60
			$	1,562.40

S/NETT

1 set	Front bumper clips		$	48.00
	Sundry		$	~~50.00~~ 20
	To check wiring for headlamp		$	~~40.00~~ 20
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of same, etc		$	200 ~~550.00~~
	To putty and spray painting on bonnet grille, front bumper		$	180 ~~350.00~~
			$	2,600.40

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kelvin KKN
12/2/19 1640hn
2 Pays
4/5
After Repairing to

18/2/19
4/5 $1150/2hn