PRECISE AUTO SERVICE

NO. 1 KAKI BUKIT AVE 6 #02-34 AUTOBAY SINGAPORE 417883
TEL : 6745 7367 FAX : 6841 3390

Not Authorised
Nah
4/S @ 2550
3 days.

15-04-19

Date Of Accident : 01-02-2019

Marcus.

OUR REF : SLC 8714M/T/19

Date in/out : 13/03/19 to 17/03/19

OPTIMAL SERVICES
18 Tampines Industrial Crescent
#05-97
Singapore 528605

ESTIMATE BILL ON VEH NO : SLC 8714M
MODEL : VOLKSWAGEN JETTA
CHASSIS NO: WVWZZZ1KZ9U020562

LKK/ ... Consultants ... hence notify the R... following:
- To ... spray painting
- To ... survey
- ... information
- T... basis
- S... surveyed and is s... approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

LIST ITEM

Rear Bumper Fascia		00/De	1,488.90
Rear Bumper Lower Spoiler		De	733.96
Rear Bumper Centre Retainer		cm	189.70
Rear Bumper Reinforcement		n	600.33 X
Rear Bumper Reflactor	~~2pcs @ 99.71~~	n1	199.42 X
Rear Bumper Clips	10pcs @ 7.11	1ee	71.10
Reverse Sensor with Control Unit	2412.50 3201.30	shield	899.68 200
			4,183.09
	Less Discount 10% :		418.31
			3,764.78

LABOUR CHARGE

To Check and Reset Electrical System.	20	120.00
To Respray Affected Areas.	400	500.00
To Remove & Refix Reverse Sensor.	50	120.00
To Renew Damaged Parts, Straighten & Repair Rear End Panel & Aligned All Parts.	300	500.00
To Remove & Refix Interior Upholstery.	60	120.00
		5,124.78
	GST 7%:	358.73
	AMOUNT DUE :	**4,766.05**