[illegible] Farah | REF: III | 04339

ASSIGNMENT

From | Date: 28/2/19

Estimated Cost

OD / (TP) / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: 8GC 1015Y

at Workshop m/s: Volkswagen

of: 1 Kampot Ampat

Insured:

Policy No:

Claims No:

Sum Insured: | Excess:

(Client's Record)

Make of Veh: 3.30pm (waiting)

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR. Seen: Consistent? : Yes or No

Est. Repairs: days | Res.: Yes or No

Lum Sum: % | 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: | Person Contacted:

Veh No: SGC 1015C | Yr Regn: 2018. SEP

Type: (M.Car) / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: VOLKSWAGEN TIGUAN HL | c.c.: 1395

Colour: GREY | A/C: Insured / Std / NI / NA

Sp.Reading: 10039 | T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WVG ZZZ5N ZJW949534

Gen. Cond: Good / (Fair) / Poor / Burnt

Steering: (Inorder) / Jammed / Leaked / Burnt or

Brake: (Inorder) / Jammed / Leaked / Burnt or

Modi.: Nil / (S/Rim) / STD A/Rim or

Tyre Size: F: 235/55R18

R: - -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / (PIR) / SUMI / TOYO / YOKO or

Front			Rear		
R/Bal.	6	mm	R/Bal.	6	mm
L/Bal.	6	mm	L/Bal.	6	mm

D.O.A. 26/02/19 | D.O.I. 28/02/19

Survey held at: KG AMPAT

Des. of Damages: Frt / (Rear) / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time | Action / Instruction

Date/Time, File Pass to?
1)
Date/Time, File Return to?
2)

[ ] : Preli. Report

[ ] : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: [ ] Site Insp ($)
[ ] Interview ($)
[ ] Tech. Invs ($)
[ ] Weekend ($)

Report Format:

Lump Sum / I.B.I: ($)

Survey Fee:
Transportation
S+PS SI
Photos
Other
TOTAL