Repair Estimate

VAG Singapore Pte Ltd
48 Toh Guan Road East
#05-123, Enterprise Hub
Singapore 608586

Tel: 6267 9916
Fax: 6267 9313
www.avantage.sg

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Date : 4-Mar-2019
Vehicle Num : SKL4200U
Make/Model : VW GOLF VARIANT
Chassis No : WVWZZZAUZGP578579

S/N	PARTS	QTY	PRICE	TOTAL
1	REAR BUMPER	1	$ 1,500.00	$ de 1,500.00
2	REAR ATTACHMENT STRIP	1	$ 70.00	$ ne 70.00
3	IMPACT BEAM	1	$ 500.00	$ bt 500.00
4	LH GUIDE PIECE	1	$ 50.00	$ ne 50.00
5	RH GUIDE PIECE	1	$ 50.00	$ x 50.00
6	LH GUIDE PIECE FOR TAILLIGHT	1	$ 50.00	$? 50.00
7	RH GUIDE PIECE FOR TAILLIGHT	1	$ 50.00	$ x 50.00
8	REAR DIFFUSOR	1	$ 350.00	$ de 350.00
9	REAR TRUCK LID	1	$ 1,800.00	$ bt 1,800.00
10	REAR TRUCK WEATHERSTRIP	1	$ 410.00	$ x 410.00
11	REAR GAS FILLED STRUT	2	$ 100.00	$ x 200.00
12	REAR TRUCK HINGE	2	$ 90.00	$ x 90.00
13	REAR TRUCK STICKER PLATE	1	$ 50.00	$? 50.00
14	REAR TRUCK LATCH LOCK	1	$ 209.00	$ x 209.00
15	REAR APRON	1	$ 650.00	$ Rp 650.00
16	END PLATE	1	$ 140.00	$ x 140.00
17	REAR BUMPER HOLDER	2	$ 30.00	$? 60.00
18	REAR TRUCK WIRING GROMMET	2	$ 35.00	$? 70.00
19	REAR PARKING SENSOR	2	$ 170.00	$? 340.00
20	REAR PARKING SENSOR SEAL RING	2	$ 5.00	$ ne 10.00
21	GOLF R BADGE	1	$ 90.00	$ ne 90.00
22	REAR EXHAUST	1	$ 810.00	$? 810.00
23	BRACKET FOR EXHAUST	1	$ 60.00	$? 60.00
24	EXHAUST HANGER	1	$ 30.00	$? 30.00
25	EXHAUST CLAMP	1	$ 55.00	$? 55.00
26	LH OUTER TAILLAMP	1	$ 240.00	$ x 240.00
27	REAR BUMPER WIRING HARNESS FOR PARKING AID	1	$ 320.00	$? 320.00
	TOTAL PARTS			$ 8,254.00
	TOTAL AMOUNT			$ 8,254.00
	MISCELLANEOUS ITEM			
	LABOUR			
1	To remove/refit/panel beat of rear bumper, rear lid, rear apron , rear end panel		$ 1,500.00	$ 800 1,500.00
	& other affect areas.			
2	To putty and spray rear bumper, rear lid, rear end panel and other affected area		$ 1,000.00	$ 700 1,000.00
	(LH and RH rear quarter panel)			
3	To diagnose on wiring harness issue due to impact.		$ 60.00	$ 30 60.00
4	To clear faults after repair is done.		$ 50.00	$ / 50.00
	Taufiq 97495749 / 67418434			
	'WP' 7/3/19 @ 350 pm			
	05 days			
	Reserving after repair *TOTAL*			$ 10,864.00
	GST 7%			$ 760.48
	GRAND TOTAL			$ 11,624.48

sure lkkauto.com