Allswell Motor Traders

25 Defu Lane 9. Singapore 539266
Tel : +65 6679 1146 email:ben@allswellmotor.com.sg

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before after spray painting
- To display damaged parts(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer :

(3rd party claim against Indus Insured SH6295)

Estimate repair

Vehicle No. : SJU4731T
Make & Model : Corolla Altis
Chassis No. : 1.6A
Date of survey :

Submitted by : Ben
COE expiry : 25-3-2023
Engine No. :

S/No	Part Description	Qty	Unit Price	Price	Disposition by
01	Front bumper X Repair	01	$890.00	X	
02	LH front retainer / RR	01	$69.00	35	
03	LH headlamp / Scr	01	$760.00	395.1	
	Special nut			$34.1	
				25%:	325.58
01	Clips / retainer clips for rear bumper $25/set / MCC.	01	$25.00		
	Labour Description				
01	Dismantle / Assembly of rear bumper	01	$260.00	200	
02	Spray painting of rear bumper	01	$300.00	200	
03	Re-wiring of sunroof	01	$40.00	30	
	35 Days.			430	
	Guo Qiang			780.58	
	15/3/23.		20%	600	
	Lamp gun repair.				
	After repair photos.				

Note: If any of the quoted parts are recommended to be repaired, then an additional labour cost will be charged accordingly under supplementary.