MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933
Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376
Reg. No: 201427944N
Email : mg3solution@gmail.com

TO	: CHINA TAIPING	DATE	: 01/04/2019
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		

VEHICLE DETAILS

VEHICLE NO : SJN3565A

MODEL : TOYOTA WISH 1.8A

Asher

CHASSIS NO

ACCIDENT DETAILS DATE : 30-Mar-19
TIME : 17:35HRS

THIRD PARTY REQUESTOR / CONTACT : MS HONG / SHARON

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE	
1	REAR BUMPER Rehand	1	$ 865.20	$ ~~865.20~~	581
2	REAR BUMPER SIDE RETAINER RH New	2	$ 62.20	$ ~~124.40~~	62.20
3	REAR FENDER RH Repair	1	$ 988.20	$ 988.20	+
4	REAR FENDER INNER COWLING RH torn	1	$ 88.50	$ 88.50	—
5	REAR FENDER AIR VENT cracked	1	$ 103.20	$ 103.20	—
6	REAR QUARTER GLASS WITH MOULDING RH Not New	1	$ 580.20	$ 580.20	+
7	TAILLAMP RH Lit	2	$ 655.20	$ ~~1,310.40~~	418.
8	TAILLAMP LOWER BRACKET RH Not New	2	$ 62.30	$ 124.60	+
9	REAR END PANEL Repair	1	$ 612.00	$ 612.00	+.

1232.50 TOTAL PRICE $ 4,796.70
939.67 LESS 25% $ 1,199.18
SUB TOTAL PRICE $ 3,597.53

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR BUMPER CLIP (SET) New	1	$ 22.00	$ 22.00	—
2	TAIL LAMP CLIP (SET) New	1	$ 20.00	$ ~~20.00~~	10.
3	REAR FENDER INNER COWLING CLIP (SET) New	1	$ 20.00	$ ~~20.00~~	10
4	REAR FENDER QUARTER GLASS SEALANT Not New	1	$ 80.00	$ 80.00	+

5	REAR FENDER QUARTER GLASS INNER SEAL	1	$ 150.00	$ 150.00	
6	REAR END PANEL INSULATION SEAL	1	$ 150.00	$ 150.00	
7	REVERSE SENSOR	1	$ 220.00	$ 220.00	
	Wheel Rim		TOTAL	$ 662.00	

442 ~~550~~ 400(SN).

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVING AND REPLACING PARTS	$ 1,200.00	400	
2	SPRAY PAINTING TO AFFECTED AREA	$ 1,200.00	500	
3	WIRING CHECK	$ 150.00	30	
4	TUFF COAT	$ 180.00	X	
5	REMOVE AND REFIX UPHOLSTERY TO FACILITATE REPAIR	$ 60.00	40	
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	$ 120.00	50	
7	REMOVE AND REFIX REAR FENDER QUARTER GLSS RH	$ 80.00	X	
	TOTAL	$2,990.00	1020	

ESTIMATE REPORT

TOTAL PARTS COST	: $	4,259.53
TOTAL LABOUR COST	: $	2,990.00
TOTAL REPAIR COST	: $	7,249.53

Adrian L total: 2401.67
L/S 02/04/19. L/S: 1.9K.
04 Days

APPROVED DETAILS

EXCESS :

NO. OF WORKING DAYS :

RE-SURVEY :

PART BY PART OR LUMP SUM

DATE & TIME OF SURVEY

SURVEYED BY

CONTACT NUMBER

FAX NUMBER

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: