Repair Estimate

VAG Singapore Pte Ltd
48 Toh Guan Road East
#05-123, Enterprise Hub
Singapore 608586

Tel: 6267 9916
Fax: 6267 9513
www.aventage.sg

Date : 1st April 2019
Vehicle Num : SGD6895R
Make/Model : Golf Mk7 1.4TSI
Chassis No : [redacted]W099064

1	Tow Cap Cover for rear bumper	1	$ 30.00	$ X NM 30.00
2	1 set of mounting parts for bumper	1	$ 75.00	$ X NM 75.00
3	Rear Bumper	1	$ 1,080.00	$ ✓ 1,080.00
4	Rear diffuser	1	$ 375.00	$ X NM 375.00
5	Left reflector	1	$ 55.00	$ X NM 55.00
6	Right reflector	1	$ 55.00	$ X NM 55.00
	TOTAL PARTS		1080	$ 1,670.00
		10%	972	
	TOTAL AMOUNT			$ 1,670.00
1	Cover for bumper to rework cut-out for vehicle with park dealet			$ 200 200.00
	> Including removal and assembly bumper, punch out of sensors			
2	To perform surface preparation and spraypaint			$ ~~200~~ 250 250.00
3	To perform complete vehicle diagnostic check			$ ✓ 90.00
4				
	Tanjin 97495749/67485734			
	8/4/19 @ 4pm.			
	Surveyor Inspection.			
	02 days			
	Receiving before paint.			
	TOTAL			$ 3,340.00
	GST 7%			$ 233.80
				$ 3,573.80

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Paint prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

972
200
250
90
$1512
02 days