ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920
* zoomautowerks@gmail.com

* Hsiao Tong

Not Authorised

25 April 2019

L/S # 30580
25/4/19

REG NO. : SLS 8343 R
MAKE/MODEL : HONDA VEZEL

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION			AMT(S$)
	LIST ITEMS			
1	Rear bumper	$	11	950.60
1	Rear bumper - side	$	11	225.30
1	Rear door -R/H	$	DD/Bent	1,085.50
1	Rear door inner lock	$	11	285.00
1	Rear door regulator c/w motor	$	Bent/Sticky	488.80
1	Rear door weatherstrip	$	new	130.80
1	Rear fender -R/H	$	11	1,500.70
1	Rear fender wheel arch garnish	CW/$	Torn	300.70
1	Rear mudflap	$	SVC	125.00
1	Rear wheel rim -R/H	$	DD/Bent	750.00
1	Rear wheel hup c/w bearing	$	Dage	332.50
1	Rear shock absorber	$	11	421.00
1	Rear axle beam	$	11	1,513.30
		$		8,109.20
	Less 20%	$		1,621.84
		$		6,487.36

2338.30
20%
1870.64

	SPECIAL NETT ITEMS			
1	Rear door sticker set	$	new	150.00
1	Rear tyre	$	11	350.00
		$		500.00

S/N	LABOUR CHARGES		
1	To remove, replaced damaged lamps and check up rear wiring.	$	80.00
2	To remove and refit inner garnishes.	$	150.00
3	To remove and refit rear undercarriage.	$	350.00
4	To conduct wheel alignment.	$	150.00
5	To remove, refit doors fittings & replace damaged parts, transfer all fittings to new door.	$	180.00
6	To apply undercoating.	$	150.00
7	Panel beating.	$	1,600.00
8	To re-spray painting on the affected areas.	$	1,500.00
		$	4,160.00
	GRAND TOTAL :	**$**	**11,147.36**

20
60
120
60
60
30
450
600

- To notify
- To re-spray painting
- To [illegible] part(s) during resurvey
- Parts [illegible] subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No [illegible] is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

PAGE 1 OF 1

P - 1870.64
S.N - 570.00
labour - 1400.00
3840.64
3072.17