COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

LONPAC / LKK

VEHICLE NO : SHB 4473L **DATE 2/5/2019 14:50**

(FZ)

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Bumper Cover			$ 544.50	
	Front Bumper Bracket Top (RH) ?			$ 22.40	
	Front Bumper Bracket (LRH) ?			$ 24.60	
	Front Fender (LRH)			$ 566.30	
	Front Fender Shield (RH) X			$ 175.90	
	Front Fender Retainer X			$ 24.60	
	Frt Wheel Hub Cap, RH			$ 107.10	
	SUB TOTAL			**$ 1,465.40**	
	LESS 20%			$ 293.08	
	DISCOUNTED TOTAL			**$ 1,172.32**	
	Front Fender Advertisement Logo (RH)			$ 100.00	**Nett**
				$ 100.00	
	Labour Charge				
	Panel Beating			$ ~~400.00~~ 300	
	Spray Painting Charge		400	$ ~~600.00~~	
	Wiring			$ X ~~50.00~~	
	Tuff Kote			$ 20 ~~50.00~~	
	Frt Wheel Alignment			$ X ~~80.00~~	
	TOTAL LABOUR			**$ 1,180.00**	
	ESTIMATE TOTAL			**$ 2,452.32**	

Kalvin 1LKK

2/5/19 1605 hrs.

2 Days

P/P

Before Paint photo

LKK Auto Care Sultan hence notify the Repairer of the following:
- To resurvey before the repairs are starting
- To display damaged parts, pending resurvey
- Parts incorrectly replaced
- Third party damage not to be repaired
- Not legal requirement to have damaged parts replaced and
- Supplementary (Hidden) damage is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.