96 MOTORSPORTS

96 MOTORSPORTS PTE LTD

64 Kaki Bukit Ave 6 Singapore (417893)

Email: estimator@96motorsports.com

Tel: 67026996/83118211

VEHICLE NUM:	GBC 403 G
MAKE & MODEL:	
MILEAGE:	
TYRE: FRONT	
TYRE: REAR	
CHASSIS NUM:	

TP LonPac
Ashes.

ATTN:

NO.	DESCRIPTION - PARTS	QTY	UNIT	ADJUSTED PRICE
1	REAR BUMPER Deformed	1	$ 986.00	✓
2	REAR BUMPER RETAINER L+R Alt New	2	$ 268.00	✗
3	REAR REINFORCEMENT Bent	1	$ 466.00	✓
4	REAR BUMPER CLIP New	1SET	$ ~~80.00~~	✓ 30
5	REAR BUMPER STEP GARNISH Deformed	1	$ 272.00	✓
6	REAR BUMPER REFLECTOTR L+R	2	$ 230.00	✗
7	REAR BUMPER TOWING CAP Alt	1	$ 65.00	✗
8	REAR BUMPER BRACKET L+R New	2	$ 154.00	✗
9				
10				
			1754	
			1578.60	

	SUBTOTAL		$ 2,521.00	$ -
	10%		$ 252.10	$ -
	PARTS TOTAL		$ 2,268.90	$ -
	SPECIAL NETT	QTY	PRICE	PRICE
	REVERSE SENSOR	1SET	$ 200.00	X nn
	REAR BUMPER STICKER	1	$ 300.00	X nn
	SPECIAL NETT T		$ 500.00	$ -
	LABOUR	QTY	PRICE	PRICE
	TO KNOCK, STRAIGHTEN AND REALIGN ACCIDENT AFFECTED AREA	1	$ ~~800.00~~	200
	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	1	$ ~~600.00~~	200
	TO RUST PROOF ACCIDENT AFFECTED AREA 450	1	$ 60.00	*
	TO CHECK REVERSE SENSOR AND WIRING	1	$ ~~80.00~~	50.
	LABOUR TOTAL		$ 1,540.00	$ -
	GRAND TOTAL COST		$ 4,308.90	$ -

Total: 2028.60

L/S · 1.6K

02 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: