96 MOTORSPORTS

96 MOTORSPORTS PTE LTD
64 Kaki Bukit Ave 6 Singapore (417893)
Email: estimator@96motorsports.com
Tel: 83118211

TP AXA.
Cecilia.

VEHICLE NUM:	TOYOTA HIACE
MAKE & MODEL:	GBD 3320 L
MILEAGE:	
TYRE: FRONT	
TYRE: REAR	
CHASSIS NUM:	JTFHT02P700150277

ATTN:

NO.	DESCRIPTION - PARTS	QTY	PRICE	ADJUSTED PRICE
4	HEAD LAMP LH Ewed	1	$ ~~980.00~~	786
5	HEAD LAMP CLIP Ne	1SET	$ 20.00	
6	FRONT DOOR LH Stotted		1415	
7	FRONT DOOR UPPER HINGE LH New		48	
8	FRONT DOOR LOWER HINGE LH Bent		39	
9	FRONT STEP LH Dented		165	
10	FRONT BUMPER Distorted	1	$ 681.80	
11	FRONT BUMPER SIDE RETAINER LH New	2	$ ~~430.00~~	65
12	FRONT BUMPER CLIP New	1SET	$ ~~50.00~~	30
13	FRONT BUMPER FOG COVER LH Dented	1	$ 242.80	48.
15	FRONT BUMPER TOP REINFORCEMENT Bent.	1	$ 342.70	
18	SUPPORT PANEL New	1	$ 482.80	
19	BRACE PANEL New	1	$ 89.00	
	358.50			
	269.37			
	SUBTOTAL		$ 3,319.10	$ -
	25%		$ 829.78	$ -
	PARTS TOTAL		$ 2,489.33	$ -

	SPECIAL NETT	QTY	PRICE	PRICE
1	FRONT NUMBER PLATE WITH COVER New	1	$ 120.00	

2	RADIATOR COOLANT Nil	1	$	100.00	X
	SPECIAL NETT T		$	220.00	$ -
	LABOUR	QTY		PRICE	PRICE
1	TO KNOCK, STRAINHTEN AND REALIGN ACCIDENT AFFECTED AREA	1	$	1,400.00	400.
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	1	$	1,200.00	800.
3	TO RUST PROOF ACCIDENT AFFECTED ARAE	1	$	120.00	X
4	TO R & R AIR CON AND RADIATOR	1	$	350.00	X
					1000
	LABOUR TOTAL		$	3,070.00	$ -
	GRAND TOTAL COST		$	5,779.33	$ -

Adrian
L/S 13/06/19.
04 Pays

Total 369437
L/S: 2.91K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: