LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV No.	AC2100754
INV Date	03/02/2021
Reference	CC6/CTI19011111/Kpa3q2
Code	CTI

PROFESSIONAL SERVICE FEE

Vehicle No.	SKS 6895P
Insured Veh.	SBN 8298H
Claim No.	SNM19D202908/C02/TKL
Policy No.	DMPCSN3065091800
Accident Date	16/06/2019
Inspection Date	21/06/2019

Description	**Total**
Third Party Express Settlement	400.00
Subtotal	**400.00**
GST (7%)	**28.00**
Grand Total	**428.00**

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD	Ref: CC6/CTI19011111/Kpa3q2
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909	Date: 03/02/2021
	Code: CTI

1.	Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	SBN 8298H	**Veh. Inspected**	SKS 6895P
	Policy No.	DMPCSN3065091800	**Coverage ($)**	0.00
	Claim No.	SNM19D202908/C02/TKL	**Excess ($)**	0.00
	Assign From		**Assign Date**	21/06/2019

2.	Vehicle Particulars & Condition			
	Make & Model	TOYOTA PREVIA (A)	**c.c**	2362
	Engine No.	HIDDEN	**Year of Reg.**	2015
	Chassis No.	JTEGD54M60A046922	**Colour**	METALLIC BROWN
	Odometer	93018 KM	**Steering**	IN ORDER
	Brakes	IN ORDER	**Modification**	STANDARD ALLOY RIM
	General	GOOD		

3.	Conditions of Tyres			
		Size	**Make**	**Balance**
	R/H Front Tyre	215/55 R17	KUMHO	8 mm
	L/H Front Tyre	215/55 R17	KUMHO	8 mm
	R/H Rear Tyre	215/55 R17	KUMHO	8 mm
	L/H Rear Tyre	215/55 R17	KUMHO	8 mm

4.	Description of Damages
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.

5.	General Information			
	Accident Date	16/06/2019	**Inspection Date**	21/06/2019
	Survey held at	CITY AUTO PTE LTD BLK 8, SIN MING IND. ESTATE #01-60/62 SIN MING ROAD SINGAPORE 575643.		

5a.	Remarks
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b.	Estimate Days of Repair	
	ESTIMATED NORMAL PERIOD FOR REPAIR:	**6 Working Days**

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKS 6895P

Qty	Description of Parts	Condition	Estimate By Workshop ($))	Our Adjusted ($)
	REPLACEMENT OF PARTS			
1	TAILGATE		1,855.40	-
1	TAILGATE GLASS MOULDING		145.07	-
1	TAILGATE LOCK	TO REPAIR SEE LABOUR	470.40	-
1	TAILGATE WEATHERSTRIP		356.40	-
1	TAILGATE EMBLEM - TOYOTA	NOT NECESSARY	49.70	-
1	TAILGATE EMBLEM - PREVIA	NOT NECESSARY	51.60	-
1	TAILGATE EMBLEM - GL	NOT NECESSARY	40.75	-
1	TAILGATE CHROME MOULDING	NOT NECESSARY	240.90	-
1	REAR BUMPER	BENT	523.30	523.30
2	REAR BUMPER SIDE RETAINER @ $50.33	SERVICEABLE	100.66	-
8	REAR BUMPER CLIPS @ $3.89	NECESSARY	31.12	31.12
2	REAR BUMPER SPONGE @ $74.70	SERVICEABLE	149.40	-
1	REAR KEYLESS ENTRY ANTENNA	CRACKED	259.50	259.50
1	REAR KEYLESS ENTRY BUZZER	CRACKED	271.60	271.60
1	REAR END PANEL	BENT	871.90	871.90
1	REAR END PANEL TOP GARNISH	MTG DISTORTED	227.85	227.85
	LESS 25% DISCOUNT		-1,411.39	-546.32
			4,234.16	1,638.95
	SPECIAL NETT ITEMS			
2	PARKING SENSOR @ $356.40 (SN)	SHORTED	712.80	356.40
1	TAILGATE GLASS SEALANT (SN)	NOT NECESSARY	40.00	-
			752.80	356.40
	LABOUR			
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.	NOT NECESSARY	150.00	-
	TO REMOVE AND REFIT TRIMS AND UPHOLSTERY.		120.00	80.00
	TO SUPPLY PANEL SEALANT TO SEAL OFF ALL WELD SEAM AND GAPS.		80.00	30.00
	TO CHECK WIRING AND LIGHTING.		60.00	20.00
	TO REMOVE AND INSTALL REVERSE SENSOR AND REAR VIEW CAMERA.	NOT NECESSARY	100.00	-

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Qty	Description of Parts	Condition	Estimate By Workshop ($))	Our Adjusted ($)
	TO RECALIBRATE AUTO TAILGATE SYSTEM.	NOT NECESSARY	180.00	-
	TO KNOCK JACKOUT DAMAGED PARTS, PANEL BEATING, WELDING ALIGN, REFIX AND TO RENEW ACCIDENT PARTS. INCLUSIVE OF THE REPAIR OF TAILGATE LOCK.		750.00	600.00
	SPRAY PAINTING ON AFFECTED & REPLACE PARTS.		900.00	500.00
	TO SPRAY RUBBERIZED COATING.		120.00	30.00
			2,460.00	1,260.00
	GRAND TOTAL		**7,446.96**	**3,255.35**

	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			**2,600.00**

Report Ref No. CC6/CTI19011111/Kpa3q2

KSC

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKS 6895P **INSPECTION**

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKS 6895P **RE-INSPECTION**

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKS 6895P **RE-INSPECTION**