SJK8864U
TP/India

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : INDIA INT'L INSURANCE PTE LTD
64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711

TEL: 63476100 FAX: 62247743
ATTN: Motor Claim Department
WS Ref: TP/INDIA
Claim Type: Third Party
Accident Date: 13/07/2019

Not authorised
Chg 8%
Resurvey after Paint

Estimate No: ES1991746/WS
Date: 15 Jul 2019
Policy No:
Veh Reg No: SJK8864U
Make/Model: HONDA STREAM 1.8X A
Chassis No: RN61084665
Engine No: R18A1793934
Reg. Date: 07/11/2008

Estimate Repair Cost to Vehicle No :SJK8864U

6 days

	Description	U/Price	Quantity		List Price S$	Amount S$
	List Price					
1	REAR BUMPER	610.50	1 PC	Rp	610.50	
2	REAR BUMPER TOW COVER	13.50	1 PC	Rpl	13.50	
3	REAR BUMPER LH SIDE RETAINER	20.50	1 PC	Rpl	20.50	
4	REAR BUMPER CLIP	3.90	6 PC	Rn	23.40	
5	TAILGATE	903.20	1 PC	Rp	903.20	
6	TAILGATE EMBLEM "STREAM"	32.60	1 PC	Rn	32.60	
7	TAILGATE OUTER GARNISH	202.80	1 PC		202.80	?
8	TAILGATE OUTER GARNISH LOGO	27.40	1 PC		27.40	?
9	TAILGATE INNER LOCK	119.40	1 PC	Rpl	119.40	
10	TAILGATE INNER RUBBER	121.60	1 PC	Dis/Con	121.60	50%
11	TAILGATE INNER TRIM BOARD	165.40	1 PC		165.40	?
12	REAR WINDSCREEN GLASS MOULDING	65.30	1 PC	Rn	65.30	
13	TAILLAMPS	352.40	2 PC		704.80	
14	REAR CENTRE PANEL	306.40	1 PC	Rp	306.40	
15	REAR CENTRE PANEL INNER TOP GARNISH	116.50	1 PC	Rpl	116.50	
16	REAR EXHAUST PIPE	709.50	1 PC		709.50	?
17	REAR FENDER LH INNER GARNISH	209.80	1 PC		209.80	?
					4,352.60	
			Less 20%		870.52	3,482.08
	Special Net					
18	TAILGATE EMBLEM " TYPE R"	30.00	1 PC	Rn	30.00	
19	REAR WINDSCREEN GLASS SEALANT	40.00	1 PC	Rn	40.00	
20	1 SET REVERSE SENSOR	200.00	1 PC	Rpl	200.00	
21	REAR NUMBER PLATE	35.00	1 PC	Rpl	35.00	
					305.00	305.00
	Labour					
22	REMOVE AND REFIT REAR BUMPER ASSY, TAILLAMPS, TAILGATE AND ATTACHMENT, REAR WIPER, LOCK ASSY. TO CUT,WELD AND RENEW REAR END PANEL, KNOCK AND REPAIR REAR SPARE TYRE COMPARTMENT AND REALIGN THE SAME.	900.00	1 LA		900.00	700
23	REMOVE AND REFIX REAR WINDSCREEN GLASS	100.00	1 LA		100.00	
24	PUTTY AND RESPRAY ON REAR PANEL, REAR BUMPER, REAR SPARE TYRE COMPARTMENT,TAILGATE.	900.00	1 LA		900.00	800
25	RUSTPROOFING	60.00	1 LA		60.00	
					1,960.00	1,960.00
				Total		S$ 5,747.08
				Add GST @ 7%		402.30
				Total Amount Payable		S$ 6,149.38

MS CM

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledge by Repairer
Signature:
Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE