Claim Documents

***YK3300K (1201900020199)**
[SJH371T]
TP
HENRY GAS PTE LTD
Jul 11 2019 4:00PM
[MOK SHAO WEI]
Mah Lian Motor Vehicle Repairer

Upload Documents | Upload Photos | Compose New Letter

View: View in Browser

Photos/Images — 3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	03/09/19 10:29	**General View**		Load JPG	✓
2	03/09/19 10:29	**General View**		Load JPG	✓
3	03/09/19 10:29	**General View**		Load JPG	✓
4	03/09/19 10:29	**General View**		Load JPG	✓
5	03/09/19 10:29	**General View**		Load JPG	✓
6	03/09/19 10:29	**General View**		Load JPG	✓
7	03/09/19 10:29	**General View**		Load JPG	✓
8	03/09/19 10:29	**General View**		Load JPG	✓
9	03/09/19 10:29	**General View**		Load JPG	✓
10	03/09/19 10:29	**General View**		Load JPG	✓
11	03/09/19 10:29	**General View**		Load JPG	✓
12	03/09/19 10:29	**General View**		Load JPG	✓
13	03/09/19 10:29	**General View**		Load JPG	✓
14	03/09/19 10:29	**General View**		Load JPG	✓
15	03/09/19 10:29	**General View**		Load JPG	✓
16	03/09/19 10:29	**General View**		Load JPG	✓
17	03/09/19 10:29	**General View**		Load JPG	✓
18	03/09/19 10:29	**General View**		Load JPG	✓
19	03/09/19 10:29	**General View**		Load JPG	✓
20	03/09/19 10:29	**General View**		Load JPG	✓
21	03/09/19 10:29	**General View**		Load JPG	✓
22	03/09/19 10:29	**General View**		Load JPG	✓
23	03/09/19 10:29	**General View**		Load JPG	✓
24	03/09/19 10:29	**General View**		Load JPG	✓
25	03/09/19 10:29	**General View**		Load JPG	✓
26	03/09/19 10:29	**General View**		Load JPG	✓
27	03/09/19 10:29	**General View**		Load JPG	✓
28	03/09/19 10:29	**General View**		Load JPG	✓
29	03/09/19 10:29	**General View**		Load JPG	✓
30	03/09/19 10:29	**General View**		Load JPG	✓
31	03/09/19 10:29	**General View**		Load JPG	✓
32	03/09/19 10:29	**General View**		Load JPG	✓
33	03/09/19 10:29	**General View**		Load JPG	✓
34	03/09/19 10:29	**General View**		Load JPG	✓
35	03/09/19 10:29	**General View**		Load JPG	✓

Photos/Images

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
			3 per page		✔
36	03/09/19 10:29	**General View**		Load JPG	✔
37	03/09/19 10:29	**General View**		Load JPG	✔
38	03/09/19 10:29	**General View**		Load JPG	✔
39	03/09/19 10:29	**General View**		Load JPG	✔
40	03/09/19 10:29	**General View**		Load JPG	✔
41	03/09/19 10:29	**General View**		Load JPG	✔
42	03/09/19 10:29	**General View**		Load JPG	✔
43	03/09/19 10:29	**General View**		Load JPG	✔
44	03/09/19 10:29	**General View**		Load JPG	✔
45	03/09/19 10:29	**General View**		Load JPG	✔
46	03/09/19 10:29	**General View**		Load JPG	✔
47	03/09/19 10:29	**General View**		Load JPG	✔
48	03/09/19 10:29	**General View**		Load JPG	✔
49	03/09/19 10:29	**General View**		Load JPG	✔
50	03/09/19 10:29	**General View**		Load JPG	✔
51	03/09/19 10:29	**General View**		Load JPG	✔
52	03/09/19 10:29	**General View**		Load JPG	✔
53	03/09/19 10:29	**General View**		Load JPG	✔
54	03/09/19 10:29	**General View**		Load JPG	✔
55	03/09/19 10:29	**General View**		Load JPG	✔
56	03/09/19 10:29	**General View**		Load JPG	✔
57	03/09/19 10:29	**General View**		Load JPG	✔
58	03/09/19 10:29	**General View**		Load JPG	✔
59	03/09/19 10:29	**General View**		Load JPG	✔
60	03/09/19 10:29	**General View**		Load JPG	✔
61	03/09/19 10:29	**General View**		Load JPG	✔
62	03/09/19 10:29	**General View**		Load JPG	✔
63	03/09/19 10:29	**General View**		Load JPG	✔
64	03/09/19 10:29	**General View**		Load JPG	✔
65	03/09/19 10:29	**General View**		Load JPG	✔
66	03/09/19 10:29	**General View**		Load JPG	✔
67	03/09/19 10:29	**General View**		Load JPG	✔
68	03/09/19 10:29	**General View**		Load JPG	✔
69	03/09/19 10:29	**General View**		Load JPG	✔
70	03/09/19 10:29	**General View**		Load JPG	✔
71	03/09/19 10:29	**General View**		Load JPG	✔
72	03/09/19 10:29	**General View**		Load JPG	✔
73	03/09/19 10:29	**General View**		Load JPG	✔
74	03/09/19 10:29	**General View**		Load JPG	✔
75	03/09/19 10:29	**General View**		Load JPG	✔
76	03/09/19 10:29	**General View**		Load JPG	✔
77	03/09/19 10:29	**General View**		Load JPG	✔
78	03/09/19 10:29	**General View**		Load JPG	✔
79	03/09/19 10:29	**General View**		Load JPG	✔
80	03/09/19 10:29	**General View**		Load JPG	✔
81	03/09/19 10:29	**General View**		Load JPG	✔
82	03/09/19 10:29	**General View**		Load JPG	✔
83	03/09/19 10:29	**General View**		Load JPG	✔

Photos/Images 3 per page ▼

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
84	03/09/19 10:29	**General View**		Load JPG	
85	03/09/19 10:29	**General View**		Load JPG	
86	03/09/19 10:29	**General View**		Load JPG	
87	03/09/19 10:29	**General View**		Load JPG	
88	03/09/19 10:29	**General View**		Load JPG	
89	03/09/19 10:29	**General View**		Load JPG	
90	03/09/19 10:29	**General View**		Load JPG	
91	03/09/19 10:29	**General View**		Load JPG	
92	03/09/19 10:29	**General View**		Load JPG	
93	03/09/19 10:29	**General View**		Load JPG	
94	03/09/19 10:29	**General View**		Load JPG	
95	03/09/19 10:29	**General View**		Load JPG	
96	03/09/19 10:29	**General View**		Load JPG	
97	03/09/19 10:29	**General View**		Load JPG	
98	03/09/19 10:29	**General View**		Load JPG	
99	03/09/19 10:29	**General View**		Load JPG	
100	03/09/19 10:29	**General View**		Load JPG	
101	03/09/19 10:29	**General View**		Load JPG	
102	03/09/19 10:29	**General View**		Load JPG	
103	03/09/19 10:29	**General View**		Load JPG	
104	03/09/19 10:29	**General View**		Load JPG	
105	03/09/19 10:29	**General View**		Load JPG	
106	03/09/19 10:29	**General View**		Load JPG	
107	03/09/19 10:29	**General View**		Load JPG	
108	03/09/19 10:29	**General View**		Load JPG	
109	03/09/19 10:29	**General View**		Load JPG	
110	03/09/19 10:29	**General View**		Load JPG	
111	03/09/19 10:29	**General View**		Load JPG	
112	03/09/19 10:29	**General View**		Load JPG	
113	03/09/19 10:30	**Reinspection Photo**		Load JPG	
114	03/09/19 10:30	**Reinspection Photo**		Load JPG	
115	03/09/19 10:30	**Reinspection Photo**		Load JPG	
116	03/09/19 10:30	**Reinspection Photo**		Load JPG	
117	03/09/19 10:30	**Reinspection Photo**		Load JPG	
118	03/09/19 10:30	**Reinspection Photo**		Load JPG	
119	03/09/19 10:30	**Reinspection Photo**		Load JPG	
120	03/09/19 10:30	**Reinspection Photo**		Load JPG	
121	03/09/19 10:30	**Reinspection Photo**		Load JPG	
122	03/09/19 10:30	**Reinspection Photo**		Load JPG	
123	03/09/19 10:30	**Reinspection Photo**		Load JPG	
124	03/09/19 10:30	**Reinspection Photo**		Load JPG	
125	03/09/19 10:31	**Reinspection Photo**		Load JPG	
126	03/09/19 10:31	**Reinspection Photo**		Load JPG	
127	03/09/19 10:31	**Reinspection Photo**		Load JPG	
128	03/09/19 10:31	**Reinspection Photo**		Load JPG	
129	03/09/19 10:31	**Reinspection Photo**		Load JPG	
130	03/09/19 10:31	**Reinspection Photo**		Load JPG	
131	03/09/19 10:31	**Reinspection Photo**		Load JPG	

Photos/Images 3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
132	03/09/19 10:31	**Reinspection Photo**		Load JPG	✔
133	03/09/19 10:31	**Reinspection Photo**		Load JPG	✔
134	03/09/19 10:31	**Reinspection Photo**		Load JPG	✔
135	03/09/19 10:31	**Reinspection Photo**		Load JPG	✔
136	03/09/19 10:31	**Reinspection Photo**		Load JPG	✔
137	03/09/19 10:31	**Reinspection Photo**		Load JPG	✔
138	03/09/19 10:31	**Reinspection Photo**		Load JPG	✔
139	03/09/19 10:31	**Reinspection Photo**		Load JPG	✔
140	03/09/19 10:31	**Reinspection Photo**		Load JPG	✔
141	03/09/19 10:31	**Reinspection Photo**		Load JPG	✔
142	03/09/19 10:31	**Reinspection Photo**		Load JPG	✔
143	03/09/19 10:31	**Reinspection Photo**		Load JPG	✔
144	03/09/19 10:31	**Reinspection Photo**		Load JPG	✔
145	03/09/19 10:31	**Reinspection Photo**		Load JPG	✔
146	03/09/19 10:31	**Reinspection Photo**		Load JPG	✔
147	03/09/19 10:31	**Reinspection Photo**		Load JPG	✔
148	03/09/19 10:31	**Reinspection Photo**		Load JPG	✔
149	03/09/19 10:31	**Reinspection Photo**		Load JPG	✔
150	03/09/19 10:31	**Reinspection Photo**		Load JPG	✔
151	03/09/19 10:31	**Reinspection Photo**		Load JPG	✔
152	03/09/19 10:31	**Reinspection Photo**		Load JPG	✔
153	03/09/19 10:31	**Reinspection Photo**		Load JPG	✔
154	03/09/19 10:31	**Reinspection Photo**		Load JPG	✔
155	03/09/19 10:31	**Reinspection Photo**		Load JPG	✔

Documentation 1 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	17/07/19 14:35	**NOTIFICATION FROM LAWYER**		Load PDF	
2	17/07/19 14:35	**LAWYER PRI**		Load PDF	
3	17/07/19 14:35	**TP GIA REPORT**		Load PDF	
4	17/07/19 14:35	**OI GIA REPORT**		Load PDF	
5	17/07/19 14:35	**ACKNOWLEDGEMENT EMAIL TO FWD DD 17.07.2019**		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/FWD19012609/UTF3S2
Date: 06/09/2019

REFERENCE

Handling Insurer:	FWD Singapore Pte. Ltd.	Policy No:	PNPV2019-00009479		
Claimant Vehicle No :	YK3300K	**Insured Vehicle No :**	SJH371T		
Date of Loss:	11/07/2019	Nature of Claim:	TP	Claim No:	1201900020199

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	**YK3300K**		
Make & Model:	ISUZU NPR71L, 4.6 D (A)	Engine No:	4HG1972388
Reg. Date:	17/04/2003 (Man. Year: 2003)	Chassis No:	JAANPR71L37101654
Colour:	White	Odometer:	0 km
Engine Capacity:	4570 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S$):	**Market Value/New Car Price**		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	7.50-16	Rear Tyre Size:	7.50-16 (D)
Front Left Side:	GT SUPER 88N 6 mm	Rear Left Side:	GT SUPER 88N 6/6 mm
Front Right Side:	GT SUPER 88N 6 mm	Rear Right Side:	GT SUPER 88N 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	33,276.20	15,631.60	17,644.60	53.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,690.00	3,890.00	9,800.00	71.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S$)	**46,966.20**	**19,521.60**	**27,444.60**	**58.43**
Approved Total (Overridden) (S$)		**15,000.00**		
(S$)	46,966.20	15,000.00	31,966.20	68.06
+ GST 7.00/7.00% (S$)	3,287.63	1,050.00	2,237.63	68.06
Nett Amount (S$)	**50,253.83**	**16,050.00**	**34,203.83**	**68.06**

INSPECTION

Date of Assignment:	17/07/2019		
Date Inspected:	17/07/2019	Inspected At:	Mah Lian Motor Vehicle Repairer (HQ) NO. 38 DEFU LANE 9 Singapore 539278
Estimated Period of Repair:	20.0 days		

Adjuster: MARCUS CHUA **Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:		(Last Synchronised: 06 Sep 2019)
Parts:	N/A	ISUZU NPR71L 4.6 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YK3300K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	825.00 FL	*825.00 FL
2	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	485.00 FL	*- FL
3	1		*FRONT BUMPER BRACKET - LH/RH	N/s Bent	216.00 FL	*108.00 FL
4	1		*HEADLAMP ASSY - LH/RH	N/s Broken	508.00 FL	*254.00 FL
5	1		*HEADLAMP BRACKET - LH/RH	N/s Torn	204.00 FL	*102.00 FL
6	1		*HEADLAMP TOP GARNISH - LH/RH	N/s Bent	170.00 FL	*85.00 FL
7	2		*HORN	Not Necessary	264.00 FL	*- FL
8	1		*SIGNAL LAMP - LH/RH	N/s Broken	190.00 FL	*95.00 FL
9	2		*FRONT CHASSIS BRACKET - LH/RH	Repair	1,176.00 FL	*- FL
10	1		*FRONT GRILLE	Cracked	462.00 FL	*462.00 FL
11	1		*FRONT PANEL	Distorted	983.00 FL	*983.00 FL
12	1		*FRONT WIPER GARNISH	Distorted	663.00 FL	*663.00 FL
13	1		*FRONT CORER PANEL - LH/RH	N/s Distorted	244.00 FL	*122.00 FL
14	1		*WIPER BLADES	N/s Bent	76.00 FL	*38.00 FL
15	1		*WIPER LINK	Bent / Jammed	236.00 FL	*236.00 FL
16	2		*WIPER PANEL NOZZLE	Not Necessary	116.00 FL	*- FL
17	1		*FRONT WINDSCREEN	Broken	980.00 FL	*980.00 FL
18	1		*WINDSCREEN RUBBER SEAL	Necessary	238.00 FL	*238.00 FL
19	1		*DOOR ASSY - LH/RH	N/s Buckled	4,690.00 FL	*1,665.00 FL
20	1		*FRONT DOOR INNER TRIM BOARD N/S	Distorted	316.00 FL	*316.00 FL
21	1		*CABIN ROOF	Distorted	3,785.00 FL	*2,200.00 FL
22	1		*CABIN ROOF LINING	Distorted	1,185.00 FL	*1,185.00 FL
23	1		*SIDE MIRROR FRAME - LH/RH	N/s Bent	636.00 FL	*318.00 FL
24	1		*SIDE MIRROR BRACKET - LH/RH	N/s Bent	136.00 FL	*68.00 FL
25	1		*SIDE MIRROR GARNISH - LH/RH	N/s Cracked	190.00 FL	*95.00 FL
26	1		*SIDE MIRROR - LH/RH	N/s Broken	256.00 FL	*128.00 FL
27	1		*DASHBOARD ASSY	Distorted	1,983.00 FL	*1,100.00 FL
28	1		*DASHBOARD REINFORCEMENT	Not Necessary	985.00 FL	*- FL
29	1		*CABIN ROOF TOP COMPARTMENT	Not Necessary	608.00 FL	*- FL
30	1		*FRONT LH SIDE COMPARTMENT	Not Necessary	582.00 FL	*- FL
31	1		*METER ASSY	Not Necessary	850.00 FL	*- FL
32	1		*REAR VIEW MIRROR	Not Necessary	68.00 FL	*- FL
33	1		*REAR VIEW MIRROR BRACKET	Not Necessary	34.00 FL	*- FL
34	1		*REAR CABIN GLASS	Cracked	226.00 FL	*226.00 FL
35	1		*REAR CABIN GLASS RUBBER SEAL	Necessary	108.00 FL	*108.00 FL
36	1		*DOOR HINGES UPPER - LH/RH	N/s Twisted	150.00 FL	*75.00 FL
37	1		*DOOR HINGES LOWER - LH/RH	N/s Twisted	170.00 FL	*85.00 FL
38	1		*AIRCON COMPRESSOR	Not Necessary	1,380.00 FL	*- FL
39	1		*AIRCON COOLING UNIT	Cracked	680.00 FL	*680.00 FL
40	1		*AIRCON EVAPORATOR UNIT	Cracked	808.00 FL	*808.00 FL
41	1		*AIRCON DISCHARGE HOSE	Not Necessary	108.00 FL	*- FL
42	1		*AIRCON LIQUID HOSE	Not Necessary	88.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*AIRCON SUCTION HOSE	Not Necessary	38.00 FL	*- FL
44	1		*AIRCON DRIER	Not Necessary	58.00 FL	*- FL
45	1		*AIRCON BLOCK VALVE	Not Necessary	28.00 FL	*- FL
46	1		*LICENSE LAMP	Not Necessary	80.00 FL	*- FL
47	2		*TAILLAMP - LH/RH	Cracked	216.00 FL	*216.00 FL
48	1		*FRONT CROSSMEMBER	Repair	1,480.00 FS	*- FS
49	1		*RADIO	Not Necessary	280.00 FS	*- FS
50	1		*NUMBER PLATE	Rear Distorted	100.00 FS	*14.00 FS
51	1		*REAR BUMPER	Distorted	1,580.00 FS	*800.00 FS
52	2		*REAR BUMPER BRACKET - LH/RH	Bent	1,376.00 FS	*700.00 FS
53	1		*SET COMPANY ADVERTISEMENT STICKER	Necessary	980.00 FS	*300.00 FS
54	1		*SET FRONT WOODEN DECK FRAME	Cracked	1,850.00 FS	*800.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S$)	**36,124.00**	**17,078.00**
- List Item Discount on L Items 10.00/10.00% (S$)	2,847.80	1,446.40
Total Parts (S$)	**33,276.20**	**15,631.60**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	**TOWING CHARGE.**	New	150.00	60.00
2	**LABOUR TO REMOVE & REFIT WINDSCREEN, SEAL.**	New	150.00	80.00
3	**LABOUR TO DISMANTLE FRONT WOODEN TIPPER FRAME & RENEW.**	New	850.00	300.00
4	**LABOUR TO JACK & STRAIGHTEN CHASSIS.**	New	2,300.00	0.00
5	**LABOUR TO REMOVE & REFIT AIRCON SYSTEM & TOP UP GAS.**	New	680.00	100.00
6	**LABOUR TO REMOVE & REFIT DASHBOARD**	New	220.00	200.00
7	**LABOUR TO REMOVE & KNOCK & JACK & REFIT ALL DENTED PARTS.**	New	4,800.00	1,500.00
8	**TO RUST PROOFING.**	New	850.00	100.00
9	**TO SPRAY & PAINTING ON DENTED AFFECTED AREA.**	New	2,800.00	1,500.00
10	**LABOUR TO CHECK & CONNECT WIRING & REFOCUS ALL HEADLAMP.**	New	890.00	50.00
		Gross Labour Cost (S$)	**13,690.00**	**3,890.00**

Report was unsubmitted during this print-out.

< END OF ESTIMATES >