19/5/2010

INS. CASE OWNER: KC | CC 4/~~AXA~~ASM 1901 2498 12/17 a3 52 | LKK: IDAC:

ASSIGNMENT

Surveyor: Rasul DOI: 9/9/19 Date / Time : 5/8/19.

Registered in Merimen:

Pre-assign / CCU / FTE

Insured Vehicle No. : SKX 8729Y. Claim No. : SAMU2V71 / 130025

Name of Insured : LEE KHEE TAT Policy No. :

Insured Tel No. : HP: Make / Model :

Excess Sec II :SS D.O.A : 1/8/19. Place of Accident :

Is driver the owner? (YES / NO) Nature of Accident :

If **NO**. Driver Name / Age : OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. : (V/L: YES / NO) Insured Liability : % **Final ? Yes / No**

SLV 8977X → → →

INSRS:	INSRS:	INSRS:	INSRS:
WSP: Kah motor	WSP:	WSP:	WSP:
Tel :	Tel :	Tel :	Tel :
Liability :	Liability :	Liability :	Liability :
RMKS:	RMKS:	RMKS:	RMKS:

Date/ Time	
	SLV8977X - WA/ [illegible] DOA · 20/7/19
	SKX 8729Y - X
7/8/19	As cu vn
17/3/2020	DS form sent
19/3/2020	File → MK to dc

STAGE	DATE / PIC
Non-Reporting ltr (1st):	
Non-Reporting ltr (2nd):	
Non-Reporting ltr (Final):	
Notification ltr (if non-pickup):	
Call OI:	
After call ltr to OI:	7/8/19 (by email).

Documentation Check List:	Handler	Typist
Notification ltr (if non-pickup)		
After call ltr to OI:		
Authorisation To Act:		
Release Voucher:		
Final Repair Bill:		
Car Rental Invoice:		
Towing Invoice		
LTA / GIA :		
Medical Bill:		
PIR:		
Mandate/Reject Instruction:		
LOD		
Payment Breakdown Form:		
Post-Repair Photos:		
Others:		

PRELIMINARY ADVICE Date/Time: Sent By:

FINALIZATION Date/Time: Confirm with: Confirm by:

Repair Cost: S$ (days) Reduction: % Email Call

FINAL SETTLEMENT Date/Time: 17/3/2020 Confirm with Dermond Email Call

Final Liability: % (W) (Agreed / Assessed) BOLA S/N No. : 27 If NO or B 28. Ass. Lia :

Repair Cost: W/GM S$ 6864.61

Loss of Rental (LOR): S$ – (days)

Loss of Use (LOU): S$ 480-00 (S 60 x 8 days)

Loss of Income (LOI): S$ – (S x days)

LOR only LOU only LOR + LOU LOR + LO [**Tick only one**]

GIA/LTA Search S$ –

Medical: S$ – 1) Claim status: Normal/Reject/Private Settle

Disbursement: S$ – (e.g. Tow/ Independent) 2) Report Format: GP

Legal Cost S$ – 3) Survey fee: $350-00

Total: S$ 7344.61 **Global Sum S$:**

COPY SENT 19/3/2020

FINAL PAYMENT Date/Time: Confirm with: Email Call

Payee 1:	S$ 7344.61	Name 1:	Kah Motor Co. Sdn. Bhd
Payee 2: (Strike if N.A.)	S$	Name 2:	
Payee 3: (Strike if N.A.)	S$	Name 3:	

Unknown Rosie | REF: Asm (Asm) P | 684A

ASSIGNMENT

From: Date: 9.9.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLV 8977X

at Workshop m/s: Kah motor

of 255 Alexandra Road

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh: morning

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 58K

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR. Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS mp'

Vehicle: IN / OUT

Date: Person Contacted:

Veh No. SLV 8977X Yr Regn: 2018 / JAN

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: HONDA JAZZ 1.3 CVT c.c 1318

Colour BLUE A/C: Insured / Std / NI / NA

Sp.Reading 023407 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JHMGK3850JX204808

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 175/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	5 mm	R/Bal.	5 mm
L/Bal.	5 mm	L/Bal.	5 mm
D.O.A.	02/08/19	D.O.I.	09/09/19

Survey held at KAH MOTOR

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	P/P # 6415.52 (Recd # 7866.06 / 55%).

Date/Time, File Pass to? 1) ☐ : Preli. Report ☐ : Final Report

Date/Time, File Return to? 2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($) ☐ : Interview ($) ☐ : Tech. Invs ($) ☐ : Weekend ($)

Report Format :

Lump Sum / I.B.I: ($)

Survey Fee:

Transportation: S + R5, S

Photos:

Offers:

TOTAL:

HONDA

QUOTATION

GST Reg No.: M20[illegible]050223
Company Ref. No.: S60FC1380G

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair
Tel: +65 6841 3838 Website: www.honda.com.sg
For 24-hours Roadside Assistance, Call 98203838

Customer	: AXA INSURANCE PTE LTD 8 SHENTON WAY #27-01 AXA TOWER SINGAPORE 068811	**Document No.**	: SQT19003401	**Page** 1
		Date	: 2. Aug 2019	
		Customer No.	: WZA006	
		Svc Advisor	: NG SIN HAI	
Registration No	: SLV8977X	**Engine No**	: L13B11030070	
Chassis No	: JHMGK3850JX204808	**Date | Time**	: 2. Aug 2019 7:44:19 PM	
Model	: JAZZ 1.3LXR CVT 18YM (EURO 6)	**Surveyor Name**	:	
Owner's Name	: PUA JIUNN SIONG	**Survey Date**	:	
Ins Policy No.	:	**Authorisation Date**	:	
Date of Accident	: 2/8/2019			

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:						
	OWNER INSURER:						
	ACC DATE:						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:						
	TP VEH:						
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR ?	1	320.00		320.00	22.40	342.40
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N) X	1	45.00		45.00	3.15	48.15
33500-T5A-J02	TAILLIGHT ASSY,R. X	1	223.90	25	167.92	11.75	179.67
33550-T5A-J02	TAILLIGHT ASSYL. X	1	223.90	25	167.92	11.75	179.67
34150-T5A-J01	LIGHT ASSYR.LID X	1	81.70	25	61.27	4.29	65.56
34155-T5A-J01	LIGHT ASSYL.LID X	1	81.70	25	61.27	4.29	65.56
34270-T5A-J01	LIGHT ASSYHIGH MOUNT STOP X	1	79.80	25	59.85	4.19	64.04
68100-TAR-U10ZZ	TAILGATE COMP st /	1	730.60	25	547.95	38.36	586.31
74440-T5A-003	WEATHERSTRIPTAILGATE ?	1	92.30	25	69.22	4.85	74.07
74801-T5S-K01	LOCK ASSY,TAILGATE ?	1	78.90	25	59.17	4.14	63.31
74810-S6A-003	HANDLETAILGATE X	1	60.40	25	45.30	3.17	48.47
75722-T5L-T01	EMBLEMRR. na /	1	10.90	25	8.17	0.57	8.74
74890-T5A-A11	GARNISH ASSY,RR LICENCE X	1	105.50	25	79.12	5.54	84.66
34100-S60-013	LIGHT ASSYLICENCE X	2	34.10	25	51.15	3.58	54.73
04715-T5A-J50ZZ	FACE,RR.BUMPER de /	1	492.70	25	369.52	25.87	395.39
71502-T5A-J60	COVER,R.RR.BUMPER X	1	20.70	25	15.52	1.09	16.61
71503-T5A-J50	COVER,RR.EXPI FIN X	1	9.30	25	6.97	0.49	7.46
71505-T5A-J50	GARNISH,RR.BUMPER ?	1	38.30	25	28.72	2.01	30.73
71507-T5A-J60	COVER,L.RR.BUMPER X	1	20.70	25	15.52	1.09	16.61

Printed on 2/8/2019 8:12:17 PM

This is a computer generated invoice. No signature is required.
Part prices are subjected to change without notice.
The above estimated cost of repair do not include any unforeseen damages.
GST Amount is calculated from individual line(s).
An amount of $53.50 (incl GST) will be applicable for the request of the above quotation for estimates above $2,000.00.
However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

HONDA

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)
Service and Body Repair
Tel: +65 6841 3838 Website: www.honda.com.sg
For 24-hours Roadside Assistance, Call 98203838

Customer	: AXA INSURANCE PTE LTD 8 SHENTON WAY #27-01 AXA TOWER SINGAPORE 068811	Document No.	: SQT19003401
		Date	: 2. Aug 2019
		Customer No.	: WZA006
		Svc Advisor	: NG SIN HAI
Registration No	: SLV8977X	Engine No	: L13B11030070
Chassis No	: JHMGK3850JX204808	Date | Time	: 2. Aug 2019 7:44:19 PM
Model	: JAZZ 1.3LXR CVT 18YM (EURO 6)	Surveyor Name	:
Owner's Name	: PUA JIUNN SIONG	Survey Date	:
Ins Policy No.	:	Authorisation Date	:
Date of Accident	: 2/8/2019		

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
71593-T5A-J50	SPACER,R.RR.BUMPER SIDE	1	16.90	25	12.67	0.89	13.56
71598-T5A-J50	SPACER,L.RR.BUMPER SIDE	1	16.90	25	12.67	0.89	13.56
91505-TM8-003	CLIP,BUMPER	7	2.30	25	12.07	0.84	12.91
66100-TAR-T00ZZ	PANEL COMPRR. Repair	1	320.40	25	240.30	16.82	257.12
04655-TAS-300ZZ	PANEL SET,RR.FLOOR X	1	683.30	25	512.47	35.87	548.34
84640-T5A-003ZA	LINING ASSYRR.PANEL X	1	60.80	25	45.60	3.19	48.79
72841-SH3-315	OILSHEET X	3	40.70	25	91.57	6.41	97.98
73127-TY0-000	RUBBER CWINDSHIELD DAMPER	1	11.40	25	8.55	0.60	9.15
73214-T5A-013	RUBBERWINDSHIELD DAMPER	2	6.50	25	9.75	0.68	10.43
73226-SZW-000	DAMPERSTD 5X5	1	8.50	25	6.37	0.45	6.82
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00	8.40	128.40
				Sum Item	3251.58	227.62	3,479.20
BOSUN	SUNDRIES	1	~~100.00~~ 30		100.00	7.00	107.00
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00		180.00	12.60	192.60
BOJSE	SEALANT FOR REAR END PANEL	1	80.00 ?		80.00	5.60	85.60
BOJSE	SEALANT FOR TAILGATE	1	80.00		80.00	5.60	85.60
BOJSE	SEALANT FOR REAR FLOOR PANEL	1	80.00 X		80.00	5.60	85.60
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00		180.00	12.60	192.60
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	560.00 X		560.00	39.20	599.20
BMI02D	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	1	~~560.00~~ 280		560.00	39.20	599.20
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	~~560.00~~ 280		560.00	39.20	599.20
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	560.00		560.00	39.20	599.20
BODAMKIT	WINDSCREEN DAM KIT.	1	80.00		80.00	5.60	85.60
BKRP02M	CUT OFF & RENEW RR PANEL.	1	~~4000.00~~ 1680		4000.00	280.00	4280.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	~~3000.00~~ 1350		3000.00	210.00	3210.00
BKOT00R	REMOVE & RENEW RR FLOOR INSULATOR.(N)	1	450.00 X		450.00	31.50	481.50

Printed on 2/8/2019 8:12:17 PM

This is a computer generated invoice. No signature is required.
Part prices are subjected to change without notice.
The above estimated cost of repair do not include any unforeseen damages.
GST Amount is calculated from individual line(s).
An amount of $53.50 (incl GST) will be applicable for the request of the above quotation for estimates above $2,000.00.
However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

HONDA

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)
Service and Body Repair
Tel: +65 6841 3838 Website: www.honda.com.sg
For 24-hours Roadside Assistance, Call 98203838

Page 3

Customer	: AXA INSURANCE PTE LTD 8 SHENTON WAY #27-01 AXA TOWER SINGAPORE 068811	**Document No.**	: SQT19003401
		Date	: 2. Aug 2019
		Customer No.	: WZA006
		Svc Advisor	: NG SIN HAI
Registration No	: SLV8977X	**Engine No**	: L13B11030070
Chassis No	: JHMGK3850JX204808	**Date | Time**	: 2. Aug 2019 7:44:19 PM
Model	: JAZZ 1.3LXR CVT 18YM (EURO 6)	**Surveyor Name**	:
Owner's Name	: PUA JIUNN SIONG	**Survey Date**	:
Ins Policy No.	:	**Authorisation Date**	:
Date of Accident	: 2/8/2019		

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BKBU01R	REMOVE, RE-FIX AND ALIGN REAR VIEW CAMERA	1	560.00		560.00	39.20	599.20
				Sum Labor	**11030.00**	**772.10**	**11,802.10**

Survey By	Rasul - Hp 90010068				
Date & Time	09/09/19 @ 1345	**Total Amount**	14,281.58	999.72	15,281.30
Excess		**Total (Inclusive of GST)**			**15,281.30**
Status	5 days				
Signature					

Resurvey before paint

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Printed on 2/8/2019 8:12:17 PM
This is a computer generated invoice. No signature is required.
Part prices are subjected to change without notice.
The above estimated cost of repair do not include any unforeseen damages.
GST Amount is calculated from individual line(s).
An amount of $53.50 (incl GST) will be applicable for the request of the above quotation for estimates above $2,000.00.
However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

HSIAU TONG

HONDA

QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)
Service and Body Repair
Tel: +65 6841 3838 Website: www.honda.com.sg
For 24-hours Roadside Assistance: Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: AXA INSURANCE PTE LTD 8 SHENTON WAY #27-01 AXA TOWER SINGAPORE 068811	Document No.	: SQT19003401	Page	1
		Date	: 2. Aug 2019		
		Customer No.	: WZA006		
		Svc Advisor	: NG SIN HAI		
Registration No	: SLV8977X	Engine No	: L13B11030070		
Chassis No	: JHMGK3850JX204808	Date | Time	: 2. Aug 2019 7:44:19 PM		
Model	: JAZZ 1.3LXR CVT 18YM (EURO 6)	Surveyor Name	:		
Owner's Name	: PUA JIUNN SIONG	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 2/8/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:						
	OWNER INSURER:						
	ACC DATE:						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:						
	TP VEH:						
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR ?XSUC	1	320.00		320.00	22.40	342.40
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N) XSUC	1	45.00		45.00	3.15	48.15
33500-T5A-J02	TAILLIGHT ASSY,R. X	1	223.90	25	167.92	11.75	179.67
33550-T5A-J02	TAILLIGHT ASSYL X SUC	1	223.90	25	167.92	11.75	179.67
34150-T5A-J01	LIGHT ASSYR.LID X	1	81.70	25	61.27	4.29	65.56
34155-T5A-J01	LIGHT ASSYL.LID X	1	81.70	25	61.27	4.29	65.56
34270-T5A-J01	LIGHT ASSYHIGH MOUNT STOP XNA	1	79.80	25	59.85	4.19	64.04
68100-TAR-U10ZZ	TAILGATE COMP bf	1	730.60	25	547.95	38.36	586.31
74440-T5A-003	WEATHERSTRIPTAILGATE ?XSUC	1	92.30	25	69.22	4.85	74.07
74801-T5S-K01	LOCK ASSY,TAILGATE ?XSUC	1	78.90	25	59.17	4.14	63.31
74810-S6A-003	HANDLETAILGATE XSUC	1	60.40	25	45.30	3.17	48.47
75722-T5L-T01	EMBLEMRR. NA	1	10.90	25	8.17	0.57	8.74
74890-T5A-A11	GARNISH ASSY,RR LICENCE XSUC	1	105.50	25	79.12	5.54	84.66
34100-S60-013	LIGHT ASSYLICENCE XSUC	2	34.10	25	51.15	3.58	54.73
04715-T5A-J50ZZ	FACE,RR.BUMPER dr	1	492.70 676.[illegible]	25	507.09 369.52	25.87	395.39
71502-T5A-J60	COVER,R.RR.BUMPER X	1	20.70	25	15.52	1.09	16.61
71503-T5A-J50	COVER,RR.EXPI FIN X	1	9.30	25	6.97	0.49	7.46
71505-T5A-J50	GARNISH,RR.BUMPER X NA	1	38.30	25	28.72	2.01	30.73
71507-T5A-J60	COVER,L.RR.BUMPER X	1	20.70	25	15.52	1.09	16.61

Printed on 2/8/2019 8:12:17 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of $53.50 (incl GST) will be applicable for the request of the above quotation for estimates above $2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd., it will be refunded.

HONDA

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)
Service and Body Repair
Tel: +65 6841 3838 Website: www.honda.com.sg
For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: AXA INSURANCE PTE LTD 8 SHENTON WAY #27-01 AXA TOWER SINGAPORE 068811	Document No.	: SQT19003401	Page	2
		Date	: 2. Aug 2019		
		Customer No.	: WZA006		
		Svc Advisor	: NG SIN HAI		
Registration No	: SLV8977X	Engine No	: L13B11030070		
Chassis No	: JHMGK3850JX204808	Date | Time	: 2. Aug 2019 7:44:19 PM		
Model	: JAZZ 1.3LXR CVT 18YM (EURO 6)	Surveyor Name	:		
Owner's Name	: PUA JIUNN SIONG	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 2/8/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
71593-T5A-J50	SPACER,R.RR.BUMPER SIDE	1	16.90	25	12.67	0.89	13.56
71598-T5A-J50	SPACER,L.RR.BUMPER SIDE	1	16.90	25	12.67	0.89	13.56
91505-TM8-003	CLIP,BUMPER	7	2.30	25	12.07	0.84	12.91
66100-TAR-T00ZZ	PANEL COMPRR. Repair X	1	320.40	25	240.30	16.82	257.12
04655-TAS-300ZZ	PANEL SET,RR FLOOR X NA	1	683.30	25	512.47	35.87	548.34
84640-T5A-003ZA	LINING ASSYRR.PANEL X SUL	1	60.80	25	45.60	3.19	48.79
72841-SH3-315	OILSHEET X NA	3	40.70	25	91.57	6.41	97.98
73127-TY0-000	RUBBER CWINDSHIELD DAMPER	1	11.40	25	8.55	0.60	9.15
73214-T5A-013	RUBBERWINDSHIELD DAMPER X NA	2	6.50	25	9.75	0.68	10.43
73226-SZW-000	DAMPERSTD 5X5	1	8.50	25	6.37	0.45	6.82
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00	8.40	128.40
				Sum Item	3251.58	227.62	3,479.20
BOSUN	SUNDRIES need	1	~~100.00~~ 30		100.00	7.00	107.00
BA02R	REMOVE & RENEW REVERSE SENSORS ~~4 PCS~~ (N)	1	180.00		180.00	12.60	192.60
BOJSE	SEALANT FOR REAR END PANEL	1	80.00 ? X NA		80.00	5.60	85.60
BOJSE	SEALANT FOR TAILGATE	1	80.00		80.00	5.60	85.60
BOJSE	SEALANT FOR REAR FLOOR PANEL	1	80.00 X NA		80.00	5.60	85.60
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00		180.00	12.60	192.60
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES (N)	1	560.00 X NA		560.00	39.20	599.20
BMI02D	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	1	~~560.00~~ 280		560.00	39.20	599.20
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE ADJUST &	1	~~560.00~~ 280		560.00	39.20	599.20
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	560.00		560.00	39.20	599.20
BODAMKIT	WINDSCREEN DAM KIT need	1	80.00		80.00	5.60	85.60
BKRP02M	CUT OFF & RENEW RR PANEL	1	~~4000.00~~ 1680		4000.00	280.00	4280.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (6P)	1	~~3000.00~~ 1350		3000.00	210.00	3210.00
BKOT00R	REMOVE & RENEW RR FLOOR INSULATOR.(N)	1	450.00 X NA		450.00	31.50	481.50

Printed on 2/8/2019 8:12:17 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of $53.50 (incl GST) will be applicable for the request of the above quotation for estimates above $2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

HONDA

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)
Service and Body Repair
Tel: +65 6841 3838 Website: www.honda.com.sg
For 24-hours Roadside Assistance, Call 98203838

Page 3

Customer	: AXA INSURANCE PTE LTD 8 SHENTON WAY #27-01 AXA TOWER SINGAPORE 068811	Document No.	: SQT19003401
		Date	: 2. Aug 2019
		Customer No.	: WZA006
		Svc Advisor	: NG SIN HAI
Registration No	: SLV8977X	Engine No	: L13B11030070
Chassis No	: JHMGK3850JX204808	Date | Time	: 2. Aug 2019 7:44:19 PM
Model	: JAZZ 1.3LXR CVT 18YM (EURO 6)	Surveyor Name	:
Owner's Name	: PUA JIUNN SIONG	Survey Date	:
Ins Policy No.	:	Authorisation Date	:
Date of Accident	: 2/8/2019		

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BKBU01R	REMOVE, RE-FIX AND ALIGN REAR VIEW CAMERA	1	~~560.00~~	48%	560.00	39.20	599.20
				Sum Labor	11030.00	772.10	11,802.10

Total Amount	14,281.58	999.72	15,281.30
Total (Inclusive of GST)			15,281.30

Survey By: Rasul - Hp 90010068
Date & Time: 09/09/19 @ 1345
Excess:
Status: 5 days
Signature:

Resurvey before paint

14419.13

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:
Date:

Printed on 2/8/2019 8:12:17 PM

This is a computer generated invoice. No signature is required.
Part prices are subjected to change without notice.
The above estimated cost of repair do not include any unforeseen damages.
GST Amount is calculated from individual line(s).
An amount of $53.50 (incl GST) will be applicable for the request of the above quotation for estimates above $2,000.00.
However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd. It will be refunded.

HONDA

SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)
370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022
255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer:	CU0120180 / AXA INSURANCE	**Document No:**	SVO19058339
Chassis No:	JHMGK3850JX204808	**Printed By:**	SHNG
License No:	SLV8977X	**Order Date:**	9. September 2019
Mileage:	18285	**Order Time:**	4:48:44 PM
Engine No:	L13B11030070	**Service Advisor:**	NG SIN HAI

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	Amount Incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:PUA JIUNN SIONG						
	OWNER INSURER:AVIVA						
	ACC DATE:02/08/2019						
	SURVEYED BY:RASUL						
	DATE:09/09/2019						
	REF NO:						
	TP INSURER:AXA						
	TP VEH:SKX8729Y						
68100-T5A-U10ZZ	TAIL GATE COMP	1	730.60	25	547.95	38.36	586.31
75722-T5L-T01	EMBLEMRR.	1	10.90	25	8.17	0.57	8.74
71501-T5A-J50ZH	FACE RR.BUMPER	1	676.10	25	507.07	35.49	542.56
71593-T5A-J50	SPACER,R.RR.BUMPER SIDE	1	16.90	25	12.67	0.89	13.56
71598-T5A-J50	SPACER,L.RR.BUMPER SIDE	1	16.90	25	12.67	0.89	13.56
91505-TM8-003	CLIP,BUMPER	7	2.30	25	12.07	0.84	12.91
73127-TY0-000	RUBBER CWINDSHIELD DAMPER	1	11.40	25	8.55	0.60	9.15
73226-SZW-000	DAMPERSTD 5X5	1	8.50	25	6.37	0.45	6.82
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00	8.40	128.40
			SUM PARTS:		**1,235.52**	**86.49**	**1,322.01**
BOSUN	0701 SUNDRIES	1	30.00		30.00	2.10	32.10
BA02R	0671 REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00		180.00	12.60	192.60
BOJSE	1610 SEALANT FOR TAILGATE	1	80.00		80.00	5.60	85.60
BML02I	1610 INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	180.00		180.00	12.60	192.60
BMI02D	1757 REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK LININGS GARNISHES & ETC.(N)	1	280.00		280.00	19.60	299.60
BKTG02R	0671 REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)	1	280.00		280.00	19.60	299.60
BG02D	1757 REMOVE & INSTALL RR. WINDSCREEN. (N)	1	560.00		560.00	39.20	599.20
BODAMKIT	1757 WINDSCREEN DAM KIT.	1	80.00		80.00	5.60	85.60
BKRP02M	0671 CUT OFF & RENEW RR PANEL. RR FLOOR PAN & RENEW DAMAGE PARTS.	1	1,680.00		1,680.00	117.60	1,797.60
BP06R	1610 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P) REAR PORTION	1	1,350.00		1,350.00	94.50	1,444.50

HONDA

SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)
370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022
255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer:	CU0120180 / AXA INSURANCE	**Document No:**	SVO19058339
Chassis No:	JHMGK3850JX204808	**Printed By:**	SHNG
License No:	SLV8977X	**Order Date:**	9. September 2019
Mileage:	18285	**Order Time:**	4:48:44 PM
Engine No:	L13B11030070	**Service Advisor:**	NG SIN HAI

BKBU01R	1610 REMOVE, RE-FIX AND ALIGN REAR VIEW CAMERA	1	480.00	480.00	33.60	513.60
			SUM LABOUR:	**5,180.00**	**362.60**	**5,542.60**
			TOTAL SGD	6,415.52	449.09	6,864.61

Total Payable (SGD) **6,864.61**

GST Amount is calculated from individual line(s)

LKK AUTO CONSULTANTS PTE LTD (TP) Menu

Service Request Details

Claim
S9M01VZ1

Reference
None

Loss Date
August 2, 2019

Report Date
Aug 5, 2019 9:07:00 AM

Request Date
August 5, 2019

Due Date
August 14, 2019

Vendor Name
LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss
Third Party Vehicle Damage

Services
Pending verification - Direct Settlement

P: Sin Hui
T: 11.41am
V: not In
E: ✓

Actions

Next Step
Agree to perform service

Decline Work | Accept Work

Vehicle Information

Incident Vehicle Registration #
SLV8977X

LKK AUTO CONSULTANTS PTE LTD (TP) Menu

Model
JAZZ-1.3 (A)

Service Address

, , ,

Primary Contact/Insured

LEE KHEE TAT
BLOCK 257 #06-409, JURONG EAST STREET 24, 600257, Singapore
90600173
keanu_lee@hotmail.com

Claim Handler

CHAN Kian Chuan
68805444
kianchuan.chan@axa.com.sg

Additional Instructions

3

Messages Invoices History Documents Assessment Metrics Notes

New Message

Catherine Chong (LKK Auto)

From:	Ng Sin Hai <shng@kahmotor.onmicrosoft.com>
Sent:	Friday, 2 August, 2019 8:15 PM
To:	SG AXA Insurance SM AXA SGP - Motor Survey
Subject:	RE: 3rd party direct settlement SLV8977X/ & your insured SKX8729Y/DOA:02/08/2019/Est $
Attachments:	4132_001.pdf
Categories:	Mateen

Dear Motor Claims,

Please refer to the attached pdf, we are assisting our insured vehicle **SLV8977X** to file a 3rd party claim against your insured vehicle **SKX8729Y** and to request for direct settlement.

Please assist and expedite to check the claim liability soonest.

Please arrange for a survey on 05/08/2019.

Thank you and have a nice day,☺

Warmest Regards,

Ng Sin Hai
Kah Motor Co. Sdn. Bhd
(A member of Oriental Holdings Berhad)
Body Repair & Paint Centre
255 Alexandra Road
Singapore 159937
DID: 6471 5419
HP: 9072 1769
E-mail: shng@honda.com.sg

Visit our Facebook page

CONFIDENTIAL NOTE: The Information contained in the e-mail is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable low. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you for your collaboration.

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Wednesday, 7 August 2019 12:16 PM
To: Ng Sin Hai
Cc: Admin A; assignments
Subject: RE: 3rd party direct settlement SLV8977X/ & your insured SKX8729Y/DOA:02/08/2019/Est $ //LKK REF: CC4/ASM19013498/pb3

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both party, the liability is clear subject to the BOLA guideline settlement.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle and admission of any liability to our Insured's part. The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor and approved by our principal.

Please note that all finalisation subject insurer's approval.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,
Hsiao Tong, Chew | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ng Sin Hai <shng@kahmotor.onmicrosoft.com>
Sent: Tuesday, 6 August 2019 11:33 AM
To: SG AXA Insurance SM AXA SGP - Motor Survey <motor.survey@axa.com.sg>
Subject: RE: 3rd party direct settlement SLV8977X/ & your insured SKX8729Y/DOA:02/08/2019/Est $

Dear All,

Please advise on the liability.

Thank you and have a nice day,☺

Warmest Regards,

Ng Sin Hai
Kah Motor Co. Sdn. Bhd
(A member of Oriental Holdings Berhad)
Body Repair & Paint Centre
255 Alexandra Road
Singapore 159937
DID: 6471 5419
HP: 9072 1769
E-mail: shng@honda.com.sg

BLUE SKIES FOR OUR CHILDREN
Visit our Facebook page
Please consider the environment before printing this email

CONFIDENTIAL NOTE: The Information contained in the e-mail is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable low. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you for your collaboration.

From: Ng Sin Hai
Sent: Friday, 2 August 2019 8:15 PM
To: axa t/p (motor.survey@axa.com.sg) <motor.survey@axa.com.sg>
Subject: RE: 3rd party direct settlement SLV8977X/ & your insured SKX8729Y/DOA:02/08/2019/Est $

Dear Motor Claims,

Please refer to the attached pdf, we are assisting our insured vehicle SLV8977X to file a 3rd party claim against your insured vehicle SKX8729Y and to request for direct settlement.

Please assist and expedite to check the claim liability soonest.

Please arrange for a survey on 05/08/2019.

Thank you and have a nice day,☺

Warmest Regards,

Ng Sin Hai
Kah Motor Co. Sdn. Bhd
(A member of Oriental Holdings Berhad)
Body Repair & Paint Centre
255 Alexandra Road
Singapore 159937
DID: 6471 5419
HP: 9072 1769

E-mail: shng@honda.com.sg

Visit our
Facebook page

CONFIDENTIAL NOTE: The Information contained in the e-mail is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable low. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you for your collaboration.

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

LKK AUTO CONSULTANTS PTE LTD (TP) Menu

<TP - Mandate IA> - S9M01VZ1 [ACCIDENT INVOLVING SKX 8729Y(OI) & SLV 8977X(TP) ON 02/08/2019]

Type
Question

Message
Liability: 100%. Insured rear-ended third party. Inform OI about third party claim. Agreed to settle at best and aware NCD issue. We seek your mandate at $7,292.06(if claim LOU) - $$ 7,621.06(if claim LOR). TP-Mandate IA had been uploaded in Smartclaims. Kindly let us have your approval/instruction. Hsiao Tong – 24-Sep-19

Reply

LKK Auto Consultants Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd **Date: 24/09/2019**

Survey Details:

Date of loss	2-Aug-19
Date of appointment	1-Aug-19
Date of survey	9-Sep-19
Location of survey	KAH MOTOR CO SDN BERHAD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SLV 8977X
Make and Model	HONDA JAZZ 1.3 CVT
Date of registration	22/1/2018
Excess	
Market Value	$58,000
Parf Rebate	$38,639
Nett Loss	$19,361

Repair details:

Initial Estimate	$	14,281.58

Proposed/Revised repair cost:

Parts	$	1,235.52
Check items (estimate)		
Labour	$	5,180.00
Total	**$**	**6,415.52**
Lump Sum(if applicable)	**$**	**-**
Number of days for repair		**5**

LKK Auto Consultants Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

OI rear-ended third party.

Mandate:

Liability(TP)		**100%**		
Proposed repair cost (w/GST)	$	6,864.61	$	6,864.61
Loss of use (7days x $60.00)	$	420.00		NIL
Loss of rental (7days x $100)(w/GST)		NIL	$	749.00
Loss of income		NIL		NIL
LTA search fees	$	7.45	$	7.45
Others		NIL		NIL
Proposed Total	**$**	**7,292.06**	**$**	**7,621.06**

Hsiao Tong (LKKAuto)

From: Shu Pei (LKKAuto)
Sent: Thursday, 3 October 2019 9:11 AM
To: Hsiao Tong (LKKAuto)
Subject: RE: New message for service request 130025, vehicle number SLV8977X

			AM
]	REC'D TP ESTIMATE-MARKED-FINAL *** PASS TO CHT	LSL1	17/9/2019 2:32:49 PM
]	MessageLiability: 100%. Insured rear-ended third party. Inform OI about third party claim. Agreed to settle at best and aware NCD issue. We seek your mandate at $7,292.06(if claim LOU) - $$ 7,621.06(if claim LOR). TP-Mandate IA had been uploaded in Smartclaims. Kindly let us have your approval/instruction. Hsiao Tong – 24-Sep-19	CHT	24/9/2019 12:23:20 PM
]	10/2/19 1:33 PM CHAN Kian Chuan-------- PLS PROCEED AS PROPOSED	LSP	3/10/2019 8:58:10 AM

Best Regards,
Shu Pei| Admin
LKK Auto Consultants Pte Ltd
Phone: 6366-0055 | email: shupei@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----
From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Wednesday, 2 October 2019 1:36 PM
To: Admin A <admin-a@lkkauto.com>
Subject: FW: New message for service request 130025, vehicle number SLV8977X

Best Regards,
Summer Lee | Admin
LKK Auto Consultants Pte Ltd
Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----
From: kianchuan.chan@axa.com.sg <kianchuan.chan@axa.com.sg>
Sent: Wednesday, 2 October, 2019 1:34 PM
To: admin-d@lkkauto.com
Subject: New message for service request 130025, vehicle number SLV8977X

AXA Insurance has sent you a message for claim number S9M01VZ1.
Please click here https://vp.smartclaims.axa.com.sg/claim-portal/ to view the message in Vendor Portal.
This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

Hsiao Tong (LKKAuto)

From: Desmond Toh <desmondtoh@honda.com.sg>
Sent: Wednesday, 5 February 2020 12:07 PM
To: Hsiao Tong (LKKAuto)
Cc: Winson Chow; Jerome Tan; Leon Lim
Subject: FW: SLV8977X - TP CLAIM AGAINST SKX8729Y DOA: 02.08.2019
Attachments: 1053_001.pdf

Your Ref: SKX8729Y

Our Ref: SLV8977X

M/s: AXA Insurance Singapore Pte Ltd
8 Shenton Way
#27-01 AXA Tower
Singapore 068811
Attn: Motor Claims Dept

Dear All,

Above is the attached document for third party direct settlement claim.

Kindly provide us your finalized settlement & payment as your soonest.

Will appreciate your response after receiving this email.

Best Regards
Desmond Toh
Contact No. 65145848
Kah Motor Co Sdn Bhd
Website : www.honda.com.sg

BLUE SKIES FOR OUR CHILDREN

Visit our Facebook page

Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

LKK AUTO CONSULTANTS PTE LTD (TP) Menu

RE: Re:<TP - Mandate IA> - S9M01VZ1 [ACCIDENT INVOLVING SKX 8729Y(OI) & SLV 8977X(TP) ON 02/08/2019]

Type
Question

Message
Hi, For LOU, Third party rejected our offer at 7days x $60.00 and proposed 8days x $60.00. Third party proposed : CORw/GST: $6,841.61 + LOU(8days x $60.00): $480.00 = TOTAL: $7,321.61. Kindly advise if we may proceed to settle at $7,321.61(all-in). Thanks. Hsiao Tong - 16 March 2020

Reply

Hsiao Tong (LKKAuto)

From: Mei Kwan (LKKAuto)
Sent: Monday, 16 March 2020 6:03 PM
To: Hsiao Tong (LKKAuto)
Subject: FW: New message for service request 130025, vehicle number SLV8977X

16/3/20 1:25 PM *** PLS PROCEED - CHAN Kian Chuan

-----Original Message-----
From: kianchuan.chan@axa.com.sg <kianchuan.chan@axa.com.sg>
Sent: Monday, 16 March, 2020 1:26 PM
To: admin-d@lkkauto.com
Subject: New message for service request 130025, vehicle number SLV8977X

AXA Insurance has sent you a message for claim number S9M01VZ1.
Please click here https://vp.smartclaims.axa.com.sg/claim-portal/ to view the message in Vendor Portal.
This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

LKK AUTO CONSULTANTS PTE LTD (TP) Menu

Re:RE: Re:<TP - Mandate IA> - S9M01VZ1 [ACCIDENT INVOLVING SKX 8729Y(OI) & SLV 8977X(TP) ON 02/08/2019]

Type
Question

Message
CORw/GST: $6,864.61 + LOU(8days x $60.00): $480.00 = TOTAL: $7,344.61

17/3/2020 ch

Reply

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Tuesday, 17 March 2020 12:41 PM
To: Desmond Toh
Cc: Winson Chow; Jerome Tan; Leon Lim
Subject: RE: SLV8977X - TP CLAIM AGAINST SKX8729Y DOA: 02.08.2019 //LKK REF:
Attachments: EXPRESS SETTLEMENT FORM_SLV8977X.pdf

Without Prejudice

Dear Sirs/Mdm,

We refer to your below email.

We confirm settlement as follows: -

1. Cost of Repair (w/GST)	$ 6,864.61
2. Loss of Use (8days x $60.00)	$ 480.00
Total	**$ 7,344.61**

Please duly sign the **documents** enclosed and return to us (LKK) for our necessary action.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Desmond Toh <desmondtoh@honda.com.sg>
Sent: Thursday, 12 March 2020 9:04 AM
To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Cc: Winson Chow <winsonchow@honda.com.sg>; Jerome Tan <jerometan@honda.com.sg>; Leon Lim <leonlim@honda.com.sg>
Subject: RE: SLV8977X - TP CLAIM AGAINST SKX8729Y DOA: 02.08.2019

Dear Hsiao Tong,

Kindly help to extend for one more day, so easy for us to explain to our client.

Best Regards
Desmond Toh
Contact No. 65145848
Kah Motor Co Sdn Bhd
Website : www.honda.com.sg

BLUE SKIES FOR OUR CHILDREN

Visit our Facebook page

From: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Sent: Thursday, 12 March, 2020 8:50 AM
To: Desmond Toh <desmondtoh@honda.com.sg>
Cc: Winson Chow <winsonchow@honda.com.sg>; Jerome Tan <jerometan@honda.com.sg>; Leon Lim <leonlim@honda.com.sg>
Subject: RE: SLV8977X - TP CLAIM AGAINST SKX8729Y DOA: 02.08.2019

Without Prejudice

Dear Sirs/Mdm,

We refer to your below email.

We are of the view that our offer is reasonable as surveyor recommended 5 repair days + 2 days = 7days.

Kindly re-consider our offer.

Thanks.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,
Hsiao Tong, Chew (Ms) | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Desmond Toh <desmondtoh@honda.com.sg>
Sent: Wednesday, 4 March 2020 3:16 PM
To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Cc: Winson Chow <winsonchow@honda.com.sg>; Jerome Tan <jerometan@honda.com.sg>; Leon Lim <leonlim@honda.com.sg>
Subject: RE: SLV8977X - TP CLAIM AGAINST SKX8729Y DOA: 02.08.2019

Dear Hsiao Tong,

We are unable to accept your offer on the LOU, the number of day is too less kindly consider one more addition day base on weekend.

Best Regards
Desmond Toh
Contact No. 65145848
Kah Motor Co Sdn Bhd
Website : www.honda.com.sg

From: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Sent: Wednesday, 4 March, 2020 3:05 PM
To: Desmond Toh <desmondtoh@honda.com.sg>
Cc: Winson Chow <winsonchow@honda.com.sg>; Jerome Tan <jerometan@honda.com.sg>; Leon Lim <leonlim@honda.com.sg>
Subject: RE: SLV8977X - TP CLAIM AGAINST SKX8729Y DOA: 02.08.2019

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

We propose settlement as follows: -

1. Cost of Repair (w/GST)	$ 6,864.61
2. Loss of Use (7days x $60.00)	$ 420.00
Total	**$ 7,284.61**

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,
Hsiao Tong, Chew (Ms) | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Desmond Toh <desmondtoh@honda.com.sg>
Sent: Wednesday, 4 March 2020 1:56 PM
To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Cc: Winson Chow <winsonchow@honda.com.sg>; Jerome Tan <jerometan@honda.com.sg>; Leon Lim <leonlim@honda.com.sg>
Subject: RE: SLV8977X - TP CLAIM AGAINST SKX8729Y DOA: 02.08.2019

Dear Hsiao Tong,

Any outcome on the above case, our client is chasing us on the claim status.

Best Regards
Desmond Toh
Contact No. 65145848
Kah Motor Co Sdn Bhd
Website : www.honda.com.sg

BLUE SKIES FOR OUR CHILDREN

Visit our Facebook page

From: Desmond Toh
Sent: Wednesday, 5 February, 2020 12:07 PM
To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Cc: Winson Chow <winsonchow@honda.com.sg>; Jerome Tan <jerometan@honda.com.sg>; Leon Lim <leonlim@honda.com.sg>
Subject: FW: SLV8977X - TP CLAIM AGAINST SKX8729Y DOA: 02.08.2019

Your Ref: SKX8729Y

Our Ref: SLV8977X

M/s: AXA Insurance Singapore Pte Ltd
8 Shenton Way
#27-01 AXA Tower
Singapore 068811
Attn: Motor Claims Dept

Dear All,

Above is the attached document for third party direct settlement claim.

Kindly provide us your finalized settlement & payment as your soonest.

Will appreciate your response after receiving this email.

Best Regards
Desmond Toh
Contact No. 65145848
Kah Motor Co Sdn Bhd
Website : www.honda.com.sg

BLUE SKIES FOR OUR CHILDREN

Visit our Facebook page

Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

HONDA

Kah Motor Co. Sdn. Bhd.
(A Member of Oriental Holdings Berhad)
Body Repair & Paint Centre
6A Mandai Estate
Singapore 729903
Tel : +65 6841 3838
Fax : +65 6362 5015
www.honda.com.sg

M/s: AXA Insurance Singapore Pte Ltd
8 Shenton Way
#27-01
Singapore 068811
Attn: Motor Claims Department

Date : 3/2/2020

Your ref : SKX8729Y

Our ref : SLV8977X

Dear Sir / Madam,

THIRD PARTY DIRECT SETTLEMENT

ACCIDENT INVOLVING SLV8977X & SKX8729Y ON 02/08/2019

We refer to the item(s) marked [✓] below:

[✓] We refer to your email dated 07/08/2019.

[✓] We enclosed herewith the repair invoice / Third Party Direct Settlement Agreement.

[✓] Kindly forward the discharge voucher for our client's signature within **2 weeks** via email to **desmondtoh@honda.com.sg.**

[ ] We return your discharge voucher duly completed.

[✓] Kindly expedite settlement of the following :-

Repair Cost	**S$6,864.61 payable to Kah Motor Co. Sdn. Bhd.**
Loss of use	**S$60.00 x 9 days : S$540.00 payable to PUA JIUNN SIONG.**
	[Inclusive of 2 PRI, 1 Saturday, 1 Sunday.]

[✓] Kindly let us have your cheque made in favour of the above mentioned name(s) for our transmission as soon as possible.

[✓] Enclosures

- [✓] Repair/Excess Bill
- [ ] Rental Invoice
- [ ] Others: _____
- [✓] Letter of Authority
- [ ] GIA Search
- [ ] LTA Search

Thank you.

Yours faithfully,

Ng Sin Hai

HONDA

Service Tax Invoice

Kah Motor Co. Sdn. Bhd.
(A Member of Oriental Holdings Berhad)
6A Mandai Estate, SINGAPORE 729903
Mandai Parts Centre
Phone No. : +65 6841 3838 Fax No. :

GST Reg No. M200050223
Company Ref. No. S60FC1380G

Invoice No.	:	SINV-BM20000131
Invoice Date	:	22/01/20
Order No.	:	SVO19058339
Reference	:	
Job Card No.	:	10969
Date/Time Received	:	02/08/19 / 7:44:19 PM
Licence No.	:	SLV8977X
Model	:	JAZZ 1.3LXR CVT 18YM
Car Chassis No.	:	JHMGK3850JX204808
Car Engine No.	:	L13B11030070
Mileage	:	18285
Service Advisor	:	NG SIN HAI 1596
Served By	:	SHNG
Page	:	1

AXA INSURANCE PTE LTD
MOTOR CLAIMS DEPT
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE, 068811

Customer Code : CU0129734
Payment Term : 30 Days

No.		Description	Qty.	UoM	U. Price	Disc %	Amount	7% GST Amount	Incld GST
		TP DIRECT SETTLEMENT (J/NO:)							
		OWNER:PUA JIUNN SIONG							
		OWNER INSURER:AVIVA							
		ACC DATE:02/08/2019							
		SURVEYED BY:RASUL							
		DATE:09/09/2019							
		REF NO:							
		TP INSURER:AXA							
		TP VEH:SKX8729Y							
BOSUN	0701	SUNDRIES	1	Hours	30.00		30.00	2.10	32.10
BA02R	0671	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	Hours	180.00		180.00	12.60	192.60
BOJSE	1610	SEALANT FOR TAILGATE	1	Hours	80.00		80.00	5.60	85.60
BML02I	1610	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	Hours	180.00		180.00	12.60	192.60
BMI02D	1757	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK LININGS GARNISHES & ETC.(N)	1	Hours	280.00		280.00	19.60	299.60
BKTG02R	0671	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)	1	Hours	280.00		280.00	19.60	299.60
BG02D	1757	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	Hours	560.00		560.00	39.20	599.20
BODAMKIT	1757	WINDSCREEN DAM KIT.	1	Hours	80.00		80.00	5.60	85.60
BKRP02M	0671	CUT OFF & RENEW RR PANEL. RR FLOOR PAN & RENEW DAMAGE PARTS.	1	Hours	1,680.00		1,680.00	117.60	1,797.60
BP06R	1610	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P) REAR PORTION	1	Hours	1,350.00		1,350.00	94.50	1,444.50
BKBU01R	1610	REMOVE, RE-FIX AND ALIGN REAR VIEW CAMERA	1	Hours	480.00		480.00	33.60	513.60
68100-T5A-U10ZZ		TAIL GATE COMP	1	Each	730.60	25	547.95	38.36	586.31
75722-T5L-T01		EMBLEMRR.	1	Each	10.90	25	8.17	0.57	8.74
71501-T5A-J50ZH		FACE RR.BUMPER	1	Each	676.10	25	507.07	35.49	542.56
71593-T5A-J50		SPACER,R.RR.BUMPER SIDE	1	Each	16.90	25	12.67	0.89	13.56
71598-T5A-J50		SPACER,L.RR.BUMPER SIDE	1	Each	16.90	25	12.67	0.89	13.56
91505-TM8-003		CLIP,BUMPER	7	Each	2.30	25	12.07	0.84	12.91
73127-TY0-000		RUBBER CWINDSHIELD DAMPER	1	Each	11.40	25	8.55	0.60	9.15
73226-SZW-000		DAMPERSTD 5X5	1	Each	8.50	25	6.37	0.45	6.82
BO-WS-SEALANT		WINDSCREEN SEALANT (N)	2	Each	60.00		120.00	8.40	128.40

Printed by SHNG on 22 Jan 2020 at 3:09:35 PM

This is a computer generated invoice. No signature is required. Please review your bill and advise us of any errors or omissions. Kah Motor reserves the right to deliver a subsequent bill for any charge omitted. GST Amount is calculated from individual line(s).

Please give us your feedback by scanning the QR Code using mobile device.

Payment due upon Payment Terms as stated above. Please make payment strictly in accordance with payment terms. Interest will be charged at 2% per month on overdue amounts.

HONDA

Service Tax Invoice

Kah Motor Co. Sdn. Bhd.
(A Member of Oriental Holdings Berhad)
6A Mandai Estate, SINGAPORE 729903
Mandai Parts Centre
Phone No. : +65 6841 3838 Fax No. :

GST Reg No. M200050223
Company Ref. No. S60FC1380G

Invoice No.	:	SINV-BM20000131
Invoice Date	:	22/01/20
Order No.	:	SVO19058339
Reference	:	
Job Card No.	:	10969
Date/Time Received	:	02/08/19 / 7:44:19 PM
Licence No.	:	SLV8977X
Model	:	JAZZ 1.3LXR CVT 18YM
Car Chassis No.	:	JHMGK3850JX204808
Car Engine No.	:	L13B11030070
Mileage	:	18285
Service Advisor	:	NG SIN HAI 1596
Served By	:	SHNG
Page	:	2

AXA INSURANCE PTE LTD
MOTOR CLAIMS DEPT
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE, 068811

Customer Code : CU0129734
Payment Term : 30 Days

Sum Labor	5,180.00	362.60	5,542.60
Sum Item	1,235.52	86.49	1,322.01
Total SGD	6,415.52	449.09	6,864.61
Total Payable (SGD)			6,864.61

Printed by SHNG on 22 Jan 2020 at 3:09:35 PM

This is a computer generated invoice, No signature is required. Please review your bill and advise us of any errors or omissions. Kah Motor reserves the right to deliver a subsequent bill for any charge omitted. GST Amount is calculated from individual line(s).

Payment due upon Payment Terms as stated above. Please make payment strictly in accordance with payment terms. Interest will be charged at 2% per month on overdue amounts.

Please give us your feedback by scanning the QR Code using mobile device.

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

ATTN: KIAN CHUAN

Ref : CC4/ASM19013498/R1pa3s2

Date : 23-03-2020

Code : ASM

1.	Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	SKX 8729Y	**Veh. Inspected**	SLV 8977X
	Policy No.	VA1/GA301882	**Coverage ($)**	0.00
	Claim No.	S9M01VZ1	**Excess ($)**	0.00
	Assign From	KIAN CHUAN	**Assign Date**	01/08/2019

2.	Vehicle Particulars & Condition			
	Make & Model	HONDA JAZZ 1.3 CVT	**c.c**	1318
	Engine No.	HIDDEN	**Year of Reg.**	2018
	Chassis No.	JHMGK3850JX204808	**Colour**	BLUE
	Odometer	023407	**Steering**	IN ORDER
	Brakes	IN ORDER	**Modification**	SPORTS RIM
	General	FAIR		

3.	Conditions of Tyres			
		Size	**Make**	**Balance**
	R/H Front Tyre	175/65 R15	YOKOHAMA	5 mm
	L/H Front Tyre	175/65 R15	YOKOHAMA	5 mm
	R/H Rear Tyre	175/65 R15	YOKOHAMA	5 mm
	L/H Rear Tyre	175/65 R15	YOKOHAMA	5 mm

4.	Description of Damages
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.

5.	General Information			
	Accident Date	02/08/2019	**Inspection Date**	09/09/2019
	Survey held at	KAH MOTOR CO SDN BERHAD NO. 255 ALEXANDRA ROAD SINGAPORE 159937		

5a.	Remarks
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b.	Estimate Days of Repair	
	ESTIMATED NORMAL PERIOD FOR REPAIR:	**5 Working Days**

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 8977X

Qty	Description of Parts	Condition	Estimate By Workshop ($))	Our Adjusted ($)
	REPLACEMENT OF PARTS			
4	ACT RR.SENSOR (SN) (CONSISTENT)	SERVICEABLE	320.00	-
1	NUMBER PLATE WITH CASING - L (SN) (CONSISTENT)	SERVICEABLE	45.00	-
1	TAILLIGHT ASSY,R. (SN) (CONSISTENT)	SERVICEABLE	167.92	-
1	TAILLIGHT ASSYL. (SN) (CONSISTENT)	SERVICEABLE	167.92	-
1	LIGHT ASSYR.LID (SN) (CONSISTENT)	SERVICEABLE	61.27	-
1	LIGHT ASSYL.LID (SN) (CONSISTENT)	SERVICEABLE	61.27	-
1	LIGHT ASSYHIGH MOUNT STOP (SN) (CONSISTENT)	NOT NECESSARY	59.85	-
1	TAILGATE COMP (SN) (CONSISTENT)	BENT	547.95	547.95
1	WEATHERSTRIP TAILGATE (SN) (CONSISTENT)	SERVICEABLE	69.22	-
1	LOCK ASSY, TAILGATE (SN) (CONSISTENT)	SERVICEABLE	59.17	-
1	HANDLE TAILGATE (SN) (CONSISTENT)	SERVICEABLE	45.30	-
1	EMBLEMRR. (SN) (CONSISTENT)	NECESSARY	8.17	8.17
1	GARNISH ASSY,RR LICENCE (SN) (CONSISTENT)	SERVICEABLE	79.12	-
2	LIGHT ASSYLICENCE (SN) (CONSISTENT)	SERVICEABLE	51.15	-
1	FACE, RR.BUMPER (SN) (CONSISTENT)	DEFORMED	507.07	507.07
1	COVER, R.RR.BUMPER (SN) (CONSISTENT)	NOT NECESSARY	15.52	-
1	COVER,RR.EXPI FIN (SN) (CONSISTENT)	NOT NECESSARY	6.97	-
1	GARNISH,RR.BUMPER (SN) (CONSISTENT)	NOT NECESSARY	28.72	-
1	COVER,L.RR.BUMPER (SN) (CONSISTENT)	NOT NECESSARY	15.52	-
1	SPACER,R.RR.BUMPER SIDE (SN) (CONSISTENT)	NECESSARY	12.67	12.67
1	SPACER,L.RR.BUMPER SIDE (SN) (CONSISTENT)	NECESSARY	12.67	12.67
7	CLIP, BUMPER (SN) (CONSISTENT)	NECESSARY	12.07	12.07
1	PANEL COMPRR. (SN) (CONSISTENT)	TO REPAIR SEE LABOUR	240.30	-
1	PANEL SET,RR.FLOOR (SN) (CONSISTENT)	NOT NECESSARY	512.47	-
1	LINING ASSYRR.PANEL (SN) (CONSISTENT)	SERVICEABLE	45.60	-
3	OILSHEET (SN) (CONSISTENT)	NOT NECESSARY	91.57	-
1	RUBBER CWINDSHIELD DAMPER (SN) (CONSISTENT)	NECESSARY	8.55	8.55
2	RUBBERWINDSHIELD DAMPER (SN) (CONSISTENT)	NOT NECESSARY	9.75	-
1	DAMPERSTD 5X5 (SN) (CONSISTENT)	NECESSARY	6.37	6.37
2	WINDSCREEN SEALANT (SN) (CONSISTENT)	NECESSARY	120.00	120.00

Report Ref No. CC4/ASM19013498/R1pa3s2

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Qty	Description of Parts	Condition	Estimate By Workshop ($))	Our Adjusted ($)
1	SUNDRIES (SN) (CONSISTENT)	NECESSARY	100.00	30.00
1	WINDSCREEN DAM KIT (SN) (CONSISTENT)	NECESSARY	80.00	80.00
			3,569.13	1,345.52
	LABOUR			
	REMOVE & RENEW REVERSE SENSORS (SN) (CONSISTENT)		180.00	180.00
	SEALANT FOR REAR END PANEL.	NOT NECESSARY	80.00	-
	SEALANT FOR TAILGATE (SN) (CONSISTENT)		80.00	80.00
	SEALANT FOR REAR FLOOR PANEL.	NOT NECESSARY	80.00	-
	INSPECT RR LIGHTING MECAHNISMS. PERFORM WATER.		180.00	180.00
	RREMOVE & INSTALL FUEL TANK FUEL PIPES.	NOT NECESSARY	560.00	-
	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK.		560.00	280.00
	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &.		560.00	280.00
	REMOVE & INSTALL RR. WINDSCREEN.		560.00	560.00
	CUT OFF & RENEW RR PANEL.		4,000.00	1,680.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.		3,000.00	1,350.00
	REMOVE & RENEW RR FLOOR ISULATION.	NOT NECESSARY	450.00	-
	REMOVE, RE-FIX AND ALIGN REAR VIEW CAMERA.		560.00	480.00
			10,850.00	5,070.00
	GRAND TOTAL		**14,419.13**	**6,415.52**

	RECOMMENDED COST OF REPAIRS			**6,415.52**

Report Ref No. CC4/ASM19013498/R1pa3s2

MRB

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.