Premium Automobiles
55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJF 345 E

S/N	Parts Description				Damaged Parts & Prices S/Nett	Remarks
22	PEDESTRIAN PROTECTION WARNING SIGN	NEC	$		13.00	
23	HORN - LOW TONE LH	NN	$		178.00	
24	HORN - HIGH TONE RH		$		178.00	
25	FRONT PARKING AID SENSOR - INNER 1pc / DM		$		462.00	184.80
26	FRONT PARKING AID SENSOR - OUTER NN	2	$		462.00	
27	FRONT PARKING AID SENSOR SEAL RING	4	$		12.00	
28	FRONT BUMPER WIRING SET NN		$		378.00	
29	FRONT FENDER - LH / RH Repair	2	$		2,602.00	
30	FRONT FENDER FRONT BRACKET - LH / RH	2	$		412.00	
31	FRONT FENDER CENTRE BRACKET - LH / RH	2	$		32.00	P = $3950.00
32	FENDER ATTACHMENT PARTS - FRONT	2	$	NN	119.00	R = $747.00
33	FRONT FENDER INNER SHIELD - LH / RH OUTER	2	$		142.00	
34	CLOSURE PANEL - LH / RH	2	$		56.00	
35	COVER PANEL - LH / RH / CRA	2	$		72.00	28.40
36	WHEEL HOUSING LINER - LH / RH	2	$		492.00	
37	WHEEL SPOILER - LH		$		146.00	
38	WHEEL SPOILER - RH / TN		$		139.00	110.80
39	BONNET / Bmc.		$		3,707.00	2965.60
	SUB TOTAL SPARE PARTS		**$**		**9,602.00**	

Premium Automobiles
55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJF 345 E

S/N	Parts Description			Damaged Parts & Prices S/Nett	Remarks
40	LID HINGE - LH / RH	2	$	292.00	
41	BONNET ATTACHMENT PARTS		$	127.00	
42	GAS FILLED STRUT		$	217.00	
43	SAFETY CATCH - LH / RH	2	$	218.00	
44	INSULATOR PAD		$	289.00	
45	IMPACT PROTECTION - LH / RH / CENTRE	NEC	$	75.00	59.44
46	PLENUM CHAMBER COVER		$	131.00	
47	LID LOCK - FRONT	2	$	391.00	
48	MICRO SWITCH - 2 PIN	2	$	24.00	
49	RELEASE CABLE RETAINER	2	$	18.00	
50	BOWDEN CABLE - CENTRE		$	53.00	P = $7302 ? = $8531
51	RELEASE ELEMENT		$	53.00	
52	RELEASE LEVER		$	13.00	
53	LID LOCK CABLE		$	67.00	
54	HEADLIGHT MOUNTING - LH / RH		$	214.00	171.20
55	LED HEADLIGHT - LH / RH	2	$ 7227.00	14,454.00	5781.60
56	LIGHT CONTROL SYSTEM CONTROL UNIT		$	692.00	
57	MAIN LIGHT ELECTRONICS POWER MODULE		$	693.00	
58	LED WITH HEAT SINK - RH		$	990.00	
59	HEADLIGHT HOSE - RH		$	35.00	
60	LIFT CYLINDER - LH / RH	2	$	256.00	102.00
	SUB TOTAL SPARE PARTS		**$**	**19,302.00**	

Premium Automobiles
55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJF 345 E

S/N	Parts Description		Damaged Parts & Prices S/Nett	Remarks
61	LIFT CYLINDER HOSE X	NN	$ 113.00	
62	WASHER PUMP X		$ 147.00	
63	WASHER PUMP HOSE X		$ 61.00	
64	WASHER PUMP INSULATOR X		$ 19.00	
65	WINDSCREEN WASHER SYSTEM PUMP X		$ 118.00	
66	WASH WATER RESERVOIR X		$ 200.00	
67	WASH WATER RESERVOIR STRAINER X		$ 24.00	
68	WASH WATER RESERVOIR END CAP X		$ 59.00	P= $889 T= $3955
69	LOCK CARRIER ? ✓ CPA		$ 1,169.00	✓ 935.20
70	A/C CONDENSOR ? ✓ BT		$ 547.00	✓ 437.60
71	REFRIGERANT LINE INLET ?	NN	$ 263.00	X
72	REFRIGERANT LINE OUTLET ?		$ 273.00	X
73	RADIATOR ? ✓ BT		$ 820.00	✓ 655.60
74	RADIATOR RUBBER BUSH - LOWER ?	MC.	$ 24.00	✓ 18.56
75	RADIATOR RUBBER BUSH - LOWER ? ✓		$ 17.00	✓ 13.44
76	COOLANT FROST PROTECTION X ~~MC~~	NN	$ 165.00	X
77	INTERCOOLER ✓ BT		$ 724.00	✓ 578.80
78	SEAL RING ? ✓ MC.		$ 82.00	✓ 32.48
79	INTERCOOLER PRESSURE HOSE - RH ?	NN	$ 283.00	X
80	INTERCOOLER PRESSURE PIPE - LH ?		$ 477.00	X
	SUB TOTAL SPARE PARTS		**$ 5,585.00**	

Premium Automobiles
55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJF 345 E

S/N	Parts Description			Damaged Parts & Prices S/Nett	Remarks
81	O-RING		$	17.00	X
82	MAP SENSOR		$	183.00	X
83	FAN RING		$	373.00	✓ 298.40
84	RADIATOR FAN WITH CONTROL UNIT		$	2,159.00	✓ 1727.20
85	RADIATOR LOUVRE		$	483.00	✓ 386
86	AIR GUIDE - UPPER / LOWER	2	$	86.00	X
87	AIR GUIDE - CENTRE		$	37.00	✓ 29.52
88	AIR GUIDE - LH / RH	2	$	100.00	✓ 39.68
89	SERVOMOTOR		$	166.00	X
90	ADJUST MOTOR CAP	2	$	14,454.00	X Part = $2268 ? = $20502.00
91	AIR DUCT		$	79.00	X
92	AIR FILTER		$	368.00	X
93	INTAKE HOSE			TBC	X
94	FRONT WHEEL COVER - LH / RH	2	$	1,154.00	✓ 922.40
95	FRONT WINDOW SLOT SEAL WITH TRIM STRIP - LH / F	2	$	1,074.00	✓ 859.20
96	WINDOW GUIDE TRIM STRIP - LH / RH	2	$	622.00	X
97	NOISE INSULATION		$	743.00	X
98	FRONT NO. PLATE	S/N	$	40.00	✓
100	SUNDRIES		$	1,000.00	✓ 240.24
	TOTAL SPARE PARTS		**$**	**67,997.00**	
	TOTAL LABOUR CHARGES		**$**	**19,644.00**	
	GRAND TOTAL		**$**	**87,641.00**	

Part = $22859.00
? = $35655.00

All charges are not inclusive of GST.
Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

8934 1.64

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name	:	Guo Qing — 82880282
Surveyed Date	:	06/8/19.
Authorised Date	:	
Excess Cost	:	Not Authorised.
Liability	:	
Remarks	:	before paint photos. 10 Days.

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 **Attn: Mr. Adrian Ling - Motor Claims Dept** **Tel: 6841 0055 - Fax: 6256 4315**	**Estimate No.** **Date** **Service Advisor** **Pages** **Regn No** **Model No**	PA/OD/0940/2019/NS 20-Aug-19 Glory Tan 1 of 1 SJF 345 E Audi Q5 SPORT 2.0 TFSI qu

Quantity	Description	Unit Price	Amount
Parts			
1	~~Support for~~ lock carrier LHS	$ 48.00 bt	38.32
2	~~Support for~~ lock carrier RHS	$ 48.00 bt	38.32
3	Front bumper reinforcement bracket RHS	$ 231.00 bt	184.40
4	Front bumper reinforcement bracket LHS	$ 231.00 bt	184.40
5	Headlight compensating piece	$ 72.00 dis	28.80
6	Headlight adjusting screw	$ 33.00 rep	26.40
		$ 663.00	
	TOTAL	**$ 663.00**	

For Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Authorised Signature

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 **Attn: Mr. Adrian Ling - Motor Claims Dept** **Tel: 6841 0055 - Fax: 6256 4315**	**Estimate No.** **Date** **Service Advisor** **Pages** **Regn No** **Model No**	PA/OD/0940/2019/NS 23-Aug-19 Glory Tan 1 of 1 SJF 345 E Audi Q5 SPORT 2.0 TFSI qu

Quantity	Description	Unit Price	Amount
Labour 1	To respray lhs front fender.	$ 1,200.00	~~550~~
		$ 1,200.00	
	TOTAL	**$ 1,200.00**	

For Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183
Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0940/2019/NS
Date	:	6-Aug-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Guo Qiang
We took 16 days of repairs exclude 2 Sundays. - jb - 15 Oct 19

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	MS. LIU YING
Address	:	BLK 602 ELIAS ROAD #15-236 Singapore 510602
Telephone	:	HP +65 94560687
Type of Claim	:	Own Damage Claims
Policy No.	:	1900093775
Vehicle No	:	**SJF 345 E**
Model Code	:	Audi Q5 SPORT 2.0 TFSI qu
Model / Year	:	30/4/2019
Engine No	:	DAX 052445
Chassis No	:	WAUZZZFY7K2045178
Mileage	:	
Date In	:	2-Aug-19
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	2-Aug-19
Place of Accident	:	TPE TOWARD AIRPORT NEAR PIE ENTRANCE

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SJF 345 E

S/n	Nature of Jobs			Estimated Charges		Surveyor's Recommendation	
1	To tow and recover vehicle from scene of accident.	S/N	$	280.00			
2	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N	$	480.00	$	*480.00*	✓
3	To remove and renew aircon condenser, charged air cooler, radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N	$	1,400.00	$	*1,400.00*	✓
4	To dismantle both front door panel trims. To remove and reinstall both wing mirror assy.	S/N	$	600.00	$	*300.00*	✓
5	To dismantle and renew front bumper, both front fenders, bonnet and both headlights. Renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.		$	7,200.00	$	*3,250.00*	3000
6	To respray front bumper, front lower spoiler, both front fenders, bonnet, hinges, both front wheel arch trims, both upper A-pillar and both front doors.		$	9,300.00	$	*3,575.00*	✓
7	***Added labour - see attached***		$	*1,200.00*	$	*550.00*	X
8	To carry out diagnostic checks.	S/N	$	384.00	$	*384.00*	
	TOTAL LABOUR CHARGES	:	**$**	**20,844.00**	$	*9,939.00*	

Premium Automobiles
55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJF 345 E

S/N	Parts Description			Damaged Parts & Prices S/Nett		Remark
1	FRONT BUMPER ASSY		$	2,364.00	$	*1,891.20*
2	FRONT BUMPER FIXING PARTS		$	244.00		
3	FRONT BUMPER SECURING STRIP - LH / RH	2	$	68.00		
4	FRONT BUMPER CLOSING ELEMENT - LH / RH	2	$	202.00		
5	FRONT BUMPER GRILLE - CENTER		$	129.00	$	*102.80*
6	FRONT BUMPER SPOILER		$	685.00	$	*548.00*
7	FRONT BUMPER UNDERRUN BAR - SILVER		$	431.00	$	*344.80*
8	FRONT BUMPER CLOSING ELEMENT		$	156.00	$	*124.40*
9	RADIATOR GRILLE		$	3,258.00	$	*2,606.40*
10	"QUATTRO" EMBLEM	NEC	$	87.00	$	*69.28*
11	STRIKER PLATE		$	222.00	$	*177.20*
12	FRONT BUMPER AIR GUIDE GRILLE LH / RH	2	$	1,038.00	$	*829.60*
13	FRONT BUMPER END CAP - LH / RH	2	$	166.00	$	*131.68*
14	FRONT BUMPER LOCKING CLIP		$	15.00	$	*11.52*
15	FOAM FILLER PIECE		$	259.00	$	*207.20*
16	FRONT BUMPER CARRIER		$	831.00	$	*664.40*
17	FRONT BUMPER TOP COVER		$	116.00	$	*92.40*
18	FRONT BUMPER GUIDE SECTION - LH / RH	2	$	68.00		
19	"CAUTION" SIGN STICKER	NEC	$	13.00	$	*9.76*
20	"AIR COND " STICKER	NEC	$	18.00	$	*14.00*
	SUB TOTAL SPARE PARTS		**$**	**10,370.00**	*$*	*7,824.64*

Premium Automobiles
55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJF 345 E

S/N	Parts Description			Damaged Parts & Prices S/Nett		Remarks
	c/f				$	*7,824.64*
22	PEDESTRIAN PROTECTION WARNING SIGN	NEC	$	13.00		
23	HORN - LOW TONE LH		$	178.00		
24	HORN - HIGH TONE RH		$	178.00		
25	FRONT PARKING AID SENSOR - INNER	2	$	462.00	$	*184.80*
26	FRONT PARKING AID SENSOR - OUTER	2	$	462.00		
27	FRONT PARKING AID SENSOR SEAL RING	4	$	12.00		
28	FRONT BUMPER WIRING SET		$	378.00		
29	FRONT FENDER - LH / RH	2	$	2,602.00		
30	FRONT FENDER FRONT BRACKET - LH / RH	2	$	412.00		
31	FRONT FENDER CENTRE BRACKET - LH / RH	2	$	32.00		
32	FENDER ATTACHMENT PARTS - FRONT	2	$	119.00		
33	FRONT FENDER INNER SHIELD - LH / RH OUTER	2	$	142.00		
34	CLOSURE PANEL - LH / RH	2	$	56.00		
35	COVER PANEL - LH / RH	2	$	72.00	$	*28.40*
36	WHEEL HOUSING LINER - LH / RH	2	$	492.00		
37	WHEEL SPOILER - LH		$	146.00		
38	WHEEL SPOILER - RH		$	139.00	$	***110.80***
39	BONNET		$	3,707.00	$	***2,965.60***
	SUB TOTAL SPARE PARTS		**$**	**9,602.00**	$	***11,114.24***

Premium Automobiles
55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJF 345 E

S/N	Parts Description			Damaged Parts & Prices S/Nett		Remarks
	c/f				$	11,114.24
40	LID HINGE - LH / RH	2	$	292.00		
41	BONNET ATTACHMENT PARTS		$	127.00		
42	GAS FILLED STRUT		$	217.00		
43	SAFETY CATCH - LH / RH	2	$	218.00		
44	INSULATOR PAD		$	289.00		
45	IMPACT PROTECTION - LH / RH / CENTRE	NEC	$	75.00	$	*59.44*
46	PLENUM CHAMBER COVER		$	131.00		
47	LID LOCK - FRONT	2	$	391.00		
48	MICRO SWITCH - 2 PIN	2	$	24.00		
49	RELEASE CABLE RETAINER	2	$	18.00		
50	BOWDEN CABLE - CENTRE		$	53.00		
51	RELEASE ELEMENT		$	53.00		
52	RELEASE LEVER		$	13.00		
53	LID LOCK CABLE		$	67.00		
54	HEADLIGHT MOUNTING - LH / RH	2	$	214.00	$	*171.20*
55	LED HEADLIGHT - LH / RH	2	$	14,454.00	$	*5,781.60*
56	LIGHT CONTROL SYSTEM CONTROL UNIT		$	692.00		
57	MAIN LIGHT ELECTRONICS POWER MODULE		$	693.00		
58	LED WITH HEAT SINK - RH		$	990.00		
59	HEADLIGHT HOSE - RH		$	35.00		
60	LIFT CYLINDER - LH / RH	2	$	256.00	$	*102.00*
	SUB TOTAL SPARE PARTS		**$**	**19,302.00**	$	*17,228.48*

Premium Automobiles
55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJF 345 E

S/N	Parts Description		Damaged Parts & Prices S/Nett		Remarks
	c/f			$	17,228.48
61	LIFT CYLINDER HOSE	$	113.00		
62	WASHER PUMP	$	147.00		
63	WASHER PUMP HOSE	$	61.00		
64	WASHER PUMP INSULATOR	$	19.00		
65	WINDSCREEN WASHER SYSTEM PUMP	$	118.00		
66	WASH WATER RESERVOIR	$	200.00		
67	WASH WATER RESERVOIR STRAINER	$	24.00		
68	WASH WATER RESERVOIR END CAP	$	59.00		
69	LOCK CARRIER	$	1,169.00	$	*935.20*
70	A/C CONDENSOR	$	547.00	$	*437.60*
71	REFRIGERANT LINE INLET	$	263.00		
72	REFRIGERANT LINE OUTLET	$	273.00		
73	RADIATOR	$	820.00	$	*655.60*
74	RADIATOR RUBBER BUSH - LOWER	$	24.00	$	*18.56*
75	RADIATOR RUBBER BUSH - LOWER	$	17.00	$	*13.44*
76	COOLANT FROST PROTECTION	$	165.00		
77	INTERCOOLER	$	724.00	$	*578.80*
78	SEAL RING	$	82.00	$	*32.48*
79	INTERCOOLER PRESSURE HOSE - RH	$	283.00		
80	INTERCOOLER PRESSURE PIPE - LH	$	477.00		
	SUB TOTAL SPARE PARTS	**$**	**5,585.00**	$	*19,900.16*

Premium Automobiles
55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJF 345 E

S/N	Parts Description			Damaged Parts & Prices S/Nett		Remarks
	c/f				$	19,900.16
81	O-RING		$	17.00		
82	MAP SENSOR		$	183.00		
83	FAN RING		$	373.00	$	*298.40*
84	RADIATOR FAN WITH CONTROL UNIT		$	2,159.00	$	*1,727.20*
85	RADIATOR LOUVRE		$	483.00	$	*386.00*
86	AIR GUIDE - UPPER / LOWER	2	$	86.00		
87	AIR GUIDE - CENTRE		$	37.00	$	*29.52*
88	AIR GUIDE - LH / RH	2	$	100.00	$	*39.68*
89	SERVOMOTOR		$	166.00		
90	ADJUST MOTOR CAP	2	$	14,454.00		
91	AIR DUCT		$	79.00		
92	AIR FILTER		$	368.00		
93	INTAKE HOSE			TBC		
94	FRONT WHEEL COVER - LH / RH	2	$	1,154.00	$	*922.40*
95	FRONT WINDOW SLOT SEAL WITH TRIM STRIP - LH /	2	$	1,074.00	$	*859.20*
96	WINDOW GUIDE TRIM STRIP - LH / RH	2	$	622.00		
97	NOISE INSULATION		$	743.00		
98	FRONT NO. PLATE	S/N	$	40.00	$	*40.00*
240	SUPPLEMENTARY		$	663.00	$	*500.64*
102	SUNDRIES		$	1,000.00	$	*240.24*
	TOTAL SPARE PARTS		**$**	**68,660.00**	$	*24,943.44*
	TOTAL LABOUR CHARGES		**$**	**20,844.00**	$	*9,939.00*
	GRAND TOTAL		**$**	**89,504.00**	$	*34,882.44*

All charges are not inclusive of GST.
Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 **Attn: Mr. Adrian Ling - Motor Claims Dept** **Tel: 6841 0055 - Fax: 6256 4315**	**Estimate No.** **Date** **Service Advisor** **Pages** **Regn No** **Model No**	PA/OD/0940/2019/NS 20-Aug-19 Glory Tan 1 of 1 SJF 345 E Audi Q5 SPORT 2.0 TFSI qu

Quantity	Description	Unit Price	Amount
Parts			
1	Support for lock carrier LHS	$ 48.00	$ 38.32
2	Support for lock carrier RHS	$ 48.00	$ 38.32
3	Front bumper reinforcement bracket RHS	$ 231.00	$ 184.40
4	Front bumper reinforcement bracket LHS	$ 231.00	$ 184.40
5	Headlight compensating piece	$ 72.00	$ 28.80
6	Headlight adjusting screw	$ 33.00	$ 26.40
		$ 663.00	$ 500.64
	TOTAL	**$ 663.00**	$ 500.64

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 **Attn: Mr. Adrian Ling - Motor Claims Dept** **Tel: 6841 0055 - Fax: 6256 4315**	**Estimate No.** **Date** **Service Advisor** **Pages** **Regn No** **Model No**	PA/OD/0940/2019/NS 23-Aug-19 Glory Tan 1 of 1 SJF 345 E Audi Q5 SPORT 2.0 TFSI qu

Quantity	Description	Unit Price	Amount
Labour			
1	To respray lhs front fender.	$ 1,200.00	*$ 550.00*
		$ 1,200.00	*$ 550.00*
	TOTAL	**$ 1,200.00**	

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SJF 345 E

Norah Khai From
6768 9911 Telephone +65 -
6841 1183 Telefax +65 -
Nora.khai@premiumauto.com.sg Mobile +65 -
Body & Paint Dept Our Dept
PA/OD/0940/2019/NH Email

23-Mar-2020 Date
Total Pages

Premium Automobiles Pte Ltd,
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Dear Sir,

RE: INSURANCE CLAIM FOR SJF 345 E, Audi Q5 SPORT 2.0 TFSI QU S-TRONIC.

With reference to the above-mentioned vehicle, no. **SJF 345 E**, claimant, **Ms. Liu Ying**, please find the related document per attached.

1. A copy of the Original invoice no. 85014989 – SS 35,398.21.
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encl
AIG Insurance – SJF 345 E

Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 15:57

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 079120

Invoice No: 85014989
Date : 19/03/2020
Order : SJF0345E
Term : 30

Account: A0006 (T 0)

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

Regn No: SJF0345E (V 41789) Regn Date: 30/04/2019 Mileage: 9412 WIP No.: 62985

Model: Q5 SPORT 2.0 TFSI qu S tronic Chassis: WAUZZZFY7K2045178 Engine: DAX 052445 Dept: U

You have been assisted by :- UB-Tony Foong (33)

		Details	Qty	Unit Price	Amount
S	SUBLET	M: TO SUPPLY VEHICLE NUMBER PLATE	40.00	1.00	40.00
Q	EXC	M: 8888 Insurance Excess/Liability	-1000.00	1.00	-1,000.00
S	BODYWORK	M: TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	480.00	1.00	480.00
S	BODYWORK	M: TO REMOVE AND RENEW AIRCON CONDENSER,CHARGED AIR COOLER,RADIATOR.CHECK ELECTRICAL FANS AND CONTROL UNIT.PRESSURISE COOLING SYSTEM.TO CARRY OUT VACUUM AND REGAS	1400.00	1.00	1,400.00
S	BODYWORK	M: TO DISMANTLE BOTH FRONT DOOR PANEL TRIMS. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY	300.00	1.00	300.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER,BONNET AND HEADLIGHT.RENEW LOCK CARRIER AND ALIGN TO POSITION.REORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	3000.00	1.00	3,000.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER,FRONT LOWER SPOILER, BOTH FRONT FENDER,BONNET,BOTH FRONT WHEEL ARCH TRIMS,UPPER A PILLAR AND FRONT DOOR	3575.00	1.00	3,575.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	384.00	1.00	384.00
X	A80A807107A GRU	COVER LH(LAST) Less 020%	1.00	1090.00	872.00
X	A80A807108A GRU	COVER RH(LAST) Less 020%	1.00	1090.00	872.00
X	A80A807661 GRU	(SK)CONN PIECE Less 020%	1.00	184.00	147.20
X	A80A807647A 9B9	GRILLE(LAST) Less 020%	1.00	128.50	102.80
X	A80A807061A GRU	(SK)FR.SPOILER Less 020%	1.00	685.00	548.00

Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 2 15:57

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 079120

Invoice No: 85014989
Date : 19/03/2020
Order : SJF0345E
Term : 30

Account: A0006 (T 0)

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

Regn No: SJF0345E (V 41789) Regn Date: 30/04/2019 Mileage: 9412 WIP No.: 62985

Model: Q5 SPORT 2.0 TFSI qu S tronic Chassis: WAUZZZFY7K2045178 Engine: DAX 052445 Dept: U

You have been assisted by :- UB-Tony Foong (33)

		Details		Qty	Unit Price	Amount
X	A80A807531 TB2	007396/(V)(SK)UNDERR	Less 020%	1.00	431.00	344.80
X	A80A807233A	(GER)PLATE	Less 020%	1.00	155.50	124.40
X	A80A853651J RP5	(A)(SK)GRILLE 14.08	Less 020%	1.00	3258.00	2,606.40
X	A80A853736 2ZZ	INSCRIPTION 'QUATTRO	Less 020%	1.00	86.60	69.28
X	A80A853692	(A)(SK)PLATE 20.08	Less 020%	1.00	221.50	177.20
X	A80A807679D RU6	GRILL(LAST)	Less 020%	1.00	518.50	414.80
X	A80A807680D RU6	007379/(V)(GER)GRILL	Less 020%	1.00	518.50	414.80
X	A80A807245	COVER	Less 020%	1.00	82.30	65.84
X	A80A807246	(A)(SK)COVER 14.08	Less 020%	1.00	82.30	65.84
X	A7L5018897A	CLIP	Less 020%	4.00	3.60	11.52
X	A80A807550C	(GER)FOAM INSER	Less 020%	1.00	259.00	207.20
X	A80A807113C	(A)(SK)BRACKET 14.08	Less 020%	1.00	830.50	664.40
X	A80A807081	COVER(LAST)	Less 020%	1.00	115.50	92.40
X	A8K0010520C	PLATE(LAST)	Less 020%	1.00	12.20	9.76
X	A80A010515	STICKER	Less 020%	1.00	17.50	14.00
X	A80A853888C	007392/(V)(GER)SPOIL	Less 020%	1.00	138.50	110.80
X	A80A823029 STL	HOOD(LAST)	Less 020%	1.00	3707.00	2,965.60
X	A80A823125	(A)(SK)PROTECTION 14	Less 020%	1.00	24.90	19.92
X	A80A823126	(A)(SK)PROTECTION 14	Less 020%	1.00	24.70	19.76
X	A80A823124	(A)(SK)PROTECTION 14	Less 020%	1.00	24.70	19.76
X	A80A805607	MOUNTING(LAST) - A/P	Less 020%	1.00	107.00	85.60
X	A80A805608	(SK)MOUNTING - A/P	Less 020%	1.00	107.00	85.60
X	A80A805594	CARRIER(LAST) - A/P	Less 020%	1.00	1169.00	935.20
X	A80A816411M	CONDENSER(LAST) - A/	Less 020%	1.00	547.00	437.60
X	A80A121251D	RADIATOR	Less 020%	1.00	819.50	655.60
X	A4M0121268A	MOUNTING(LAST) - A/P	Less 020%	2.00	11.60	18.56
X	A4M0121275A	MOUNTING(LAST) - A/P	Less 020%	2.00	8.40	13.44
X	AG A13040M2	PREMIX-COOLANT	Less 020%	4.00	21.00	67.20
X	A80A145805J	(A)(SK)COOLER 14.08P	Less 020%	1.00	723.50	578.80
X	A80A121207	COWL(LAST) - A/P	Less 020%	1.00	373.00	298.40
X	A80A959455D	ELECTRIC F(LAST) - A	Less 020%	1.00	2159.00	1,727.20
X	A80A121223	(A)(SK)BLIND - A/P 2	Less 020%	1.00	482.50	386.00
X	A80A121299	CAP(LAST) - A/P	Less 020%	1.00	5.00	4.00
X	A80A853717E GRU	COVER(LAST)	Less 020%	1.00	576.50	461.20

Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 3 15:57

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 079120

Invoice No: 85014989
Date : 19/03/2020
Order : SJF0345E
Term : 30

Account: A0006 (T 0)

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

Regn No: SJF0345E (V 41789) Regn Date: 30/04/2019 Mileage: 9412 WIP No.: 62985

Model: Q5 SPORT 2.0 TFSI qu S tronic Chassis: WAUZZZFY7K2045178 Engine: DAX 052445 Dept: U

You have been assisted by :- UB-Tony Foong (33)

		Details		Qty	Unit Price	Amount
X	A80A853718E GRU	007379/(V)(SK)COVER	Less 020%	1.00	576.50	461.20
X	A80A853283D 3Q7	(A)(SK)WINDOW SLO 14	Less 020%	1.00	537.00	429.60
X	A80A853284D 3Q7	007379/(V)(GER)WINDO	Less 020%	1.00	537.00	429.60
X	A5Q0919275C GRU	Sensor	Less 020%	1.00	231.00	184.80
X	A5Q0919133 9B9	WASHER	Less 020%	4.00	2.00	6.40
X	A80A805201	(A)(SK)MOUNTING - A/	Less 020%	1.00	47.90	38.32
X	A80A805202	(A)(SK)MOUNTING - A/	Less 020%	1.00	47.90	38.32
X	AN 91175701	NUT - A/P	Less 020%	2.00	1.00	1.60
X	AN 90808203	BOLT - A/P	Less 020%	2.00	1.00	1.60
X	A80A807133	BRACKET - A/P	Less 020%	1.00	230.50	184.40
X	A80A807134	BRACKET - A/P	Less 020%	1.00	230.50	184.40
X	AN 10036203	BOLT - A/P	Less 020%	4.00	12.60	40.32
X	AN 02300311	NUT - A/P	Less 020%	4.00	0.50	1.60
X	AN 90648402	BOLT A/P	Less 020%	4.00	7.60	24.32
X	AN 90648402	BOLT - A/P	Less 020%	4.00	7.60	24.32
X	AN 91177601	(A)(SK)BOLT - A/P 20	Less 020%	1.00	2.30	1.84
X	A4G8806305	(A)(SK)SPACER - A/P	Less 020%	1.00	36.00	28.80
X	A80A955102	(A)(SK)CYLINDER - A/	Less 020%	1.00	127.50	102.00
X	A4M0121095	BOLT - A/P	Less 020%	2.00	2.20	3.52
X	A7P0121365	SLEEVE -A/P	Less 020%	2.00	7.50	12.00
X	A7P0121276	GROMMET	Less 020%	2.00	8.80	14.08
X	A80A121674H	(A)(SK)AIR DUCT 20.0	Less 020%	1.00	49.60	39.68
X	A80A121345AE	(A)(SK)AIR DUCT 20.0	Less 020%	1.00	36.90	29.52
X	A80A805285A 9B9	(A)(SK)COVER 20.08	Less 020%	1.00	35.50	28.40
X	A3D0260749C	WASHER - A/P	Less 020%	1.00	4.00	3.20
X	A4E0260749A	WASHER - A/P	Less 020%	1.00	3.60	2.88
X	A7H0820896	SEAL - A/P	Less 020%	1.00	2.50	2.00
X	AN 10666702	(A)(SK)BOLT - A/P 20	Less 020%	4.00	1.00	3.20
X	AN 10554008	007392/(V)(GER)SCREW	Less 020%	1.00	1.00	0.80
X	A5J0941141B	(A)(SK)SCREW - A/P 2	Less 020%	2.00	16.50	26.40
X	A8W0971824AA	(A)(SK) CONDUIT - A/	Less 020%	1.00	17.70	14.16
X	A80A145117	007392/(V)(GER)WASHE	Less 020%	1.00	40.60	32.48
X	A80A820536B	(A)(SK)BRACKET AP 21	Less 020%	1.00	14.00	11.20
X	A80A941774A	HEADLIGHT (REPLACE B	Less 020%	1.00	7227.00	5,781.60

Parts	24,903.44
Labour	0.00
Sublet	9,179.00
Menus	0.00
Lubricant	0.00

Sub-Total	33,082.44
7% GST	2,315.77
Grand Total	35,398.21

PREMIUM AUTOMOBILES PTE LTD

Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SJF 345 E

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0940/2019/TG
31 August 2019

1

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

RE: CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model	:	Audi Q5 Sport 2.0 TFSI QU
Vehicle Chassis No.	:	WAUZZZFY7K2045178
Vehicle Regn No.	:	SJF 345 E
Vehicle Mileage	:	2919 KM
Vehicle Owner	:	Ms. Liu Ying
Certificate No	:	1900093775
Own Damage Excess	:	$1,070.00 (Inclusive GST)
Accident Date	:	02 August 2019
Place	:	TPE Toward Airport Near PIE Entrance
Repair Cost	:	S$ 35,398.21
WIP No.	:	62985
Repairer's Name	:	Premium Automobiles Pte Ltd

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature	:	
Time	:	31/8/2019
Date	:	3 30pm.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Aug 2019		07 Aug 2019 10:34 Edit Adj Rpt	**S$34,082.44** Edit Estimates	**S$34,082.44** View Rpt		**Pending for Survey Report** Cancel Case

Main | Reference | Claim Details | Documents | Show All

CLAIM SUBFOLDER DETAILS **[Created by insurer]**

Insured:	**LIN YING**, ID: S7179002I, Tel: +6594560687, Email: LINYING0610@GMAIL.COM		
Vehicle Reg. No.:	**SJF345E**	Date of Loss:	02/08/2019 14:00 - :59 [**3** Months and **3** Days From LTA Reg Date (Man Yr)]
Claim Type:	**OD** / 5997142761SG	Policy/Cover Note No.:	(Comprehensive)
		Excess:	S$1,000.00
Repairer:	**Premium Automobiles Pte Ltd (UBI)** 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911		
Handling Insurer:	**AIG Asia Pacific Insurance Pte. Ltd. (SG)** - Tel: 65-6419-3000 ... [Handled by **Mithoo Singh, Aashweenjeet Kaur**] Aashweenjeetkaur.Mithoosingh@aig.com		
Adjuster:	**LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Handled by **XING GUO QIANG**] ... [**Final Rpt** due 20/08/2019]		
Driver/Custodian:	LIN YING (48 / Female) , NRIC: S7179002I, Tel: +6594560687 Email: LINYING0610@GMAIL.COM		

ASSOCIATED MAIL RECEIVED View All | Compose Case Mail

- AIG_SG (11/02/2020): **Alert - Adj Mandate Approved (S$34082.44) - SJF345E - Claim Handler: Mithoo Sing...**
- AIG_SG (02/09/2019): **Alert - Adj Mandate Maintained - SJF345E - Claim Handler: Mithoo Singh, Aashween...**
- AIG_SG (28/08/2019): **Alert - Adj Mandate Maintained - SJF345E - Claim Handler: Mithoo Singh, Aashween...**
- AIG_SG (23/08/2019): **Alert - Adj Mandate Approved (S$32411.00) - SJF345E - Claim Handler: Mithoo Sing...**
- AIG_SG (08/08/2019): **Alert - Adj Mandate Approved (S$31748.00) - SJF345E - Claim Handler: Mithoo Sing...**
- AIG_SG (07/08/2019): **SJF345E / OD / 02/08/2019 / Coverage & Excess update**

ALL ASSOCIATED TASKS View All | Search Tasks | Create New Task | Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?

No results.

Claim Documents

***SJF345E (5997142761SG)**
OD
Aug 2 2019 2:00PM
[LIN YING]
Premium Automobiles Pte Ltd

Upload Documents | Upload Photos | Compose New Letter | Upload Video | Upload Audio

View: View in Browser

Assessment Reports — 1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	07/08/19 15:02	**Adjuster Immediate Advice**	i	Load HTM	
2	21/08/19 17:35	**Adjuster Immediate Advice**	i	Load HTM	
3	21/08/19 17:42	**Adjuster Immediate Advice**	i	Load HTM	
4	28/08/19 10:34	**Adjuster Immediate Advice**	i	Load HTM	

Photos/Images — 3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	07/08/19 10:56	**General View**	i	Load JPG	✓
2	07/08/19 10:56	**General View**	i	Load JPG	✓
3	07/08/19 10:56	**General View**	i	Load JPG	✓
4	07/08/19 10:56	**General View**	i	Load JPG	✓
5	07/08/19 10:56	**General View**	i	Load JPG	✓
6	07/08/19 10:56	**General View**	i	Load JPG	✓
7	07/08/19 10:56	**General View**	i	Load JPG	✓
8	07/08/19 10:56	**General View**	i	Load JPG	✓
9	07/08/19 10:56	**General View**	i	Load JPG	✓
10	07/08/19 10:56	**General View**	i	Load JPG	✓
11	07/08/19 10:56	**General View**	i	Load JPG	✓
12	07/08/19 10:56	**General View**	i	Load JPG	✓
13	07/08/19 10:56	**General View**	i	Load JPG	✓
14	07/08/19 10:56	**General View**	i	Load JPG	✓
15	07/08/19 10:56	**General View**	i	Load JPG	✓
16	07/08/19 10:56	**General View**	i	Load JPG	✓
17	07/08/19 10:56	**General View**	i	Load JPG	✓
18	07/08/19 10:56	**General View**	i	Load JPG	✓
19	07/08/19 10:56	**General View**	i	Load JPG	✓
20	07/08/19 10:56	**General View**	i	Load JPG	✓
21	07/08/19 10:56	**General View**	i	Load JPG	✓
22	07/08/19 10:56	**General View**	i	Load JPG	✓
23	07/08/19 10:56	**General View**	i	Load JPG	✓
24	07/08/19 10:56	**General View**	i	Load JPG	✓
25	07/08/19 10:56	**General View**	i	Load JPG	✓
26	07/08/19 10:56	**General View**	i	Load JPG	✓
27	07/08/19 10:56	**General View**	i	Load JPG	✓
28	07/08/19 10:56	**General View**	i	Load JPG	✓
29	07/08/19 10:56	**General View**	i	Load JPG	✓
30	07/08/19 10:56	**General View**	i	Load JPG	✓
31	07/08/19 10:56	**General View**	i	Load JPG	✓

Assessment Reports 1 per page ▼

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
32	07/08/19 10:56	**General View**		Load JPG	
33	07/08/19 10:56	**General View**		Load JPG	
34	07/08/19 10:56	**General View**		Load JPG	
35	07/08/19 10:56	**General View**		Load JPG	
36	07/08/19 10:56	**General View**		Load JPG	
37	07/08/19 10:56	**General View**		Load JPG	
38	07/08/19 10:56	**General View**		Load JPG	
39	07/08/19 10:56	**General View**		Load JPG	
40	07/08/19 10:56	**General View**		Load JPG	
41	07/08/19 10:56	**General View**		Load JPG	
42	07/08/19 10:56	**General View**		Load JPG	
43	07/08/19 10:56	**General View**		Load JPG	
44	07/08/19 10:56	**General View**		Load JPG	
45	07/08/19 10:56	**General View**		Load JPG	
46	07/08/19 10:56	**General View**		Load JPG	
47	07/08/19 10:56	**General View**		Load JPG	
48	07/08/19 10:56	**General View**		Load JPG	
49	07/08/19 10:56	**General View**		Load JPG	
50	07/08/19 10:56	**General View**		Load JPG	
51	07/08/19 10:56	**General View**		Load JPG	
52	07/08/19 10:56	**General View**		Load JPG	
53	07/08/19 10:56	**General View**		Load JPG	
54	07/08/19 10:56	**General View**		Load JPG	
55	07/08/19 10:56	**General View**		Load JPG	
56	07/08/19 10:56	**General View**		Load JPG	
57	07/08/19 10:56	**General View**		Load JPG	
58	07/08/19 10:56	**General View**		Load JPG	
59	07/08/19 10:56	**General View**		Load JPG	
60	07/08/19 10:56	**General View**		Load JPG	
61	07/08/19 10:56	**General View**		Load JPG	
62	07/08/19 10:56	**General View**		Load JPG	
63	07/08/19 10:56	**General View**		Load JPG	
64	07/08/19 10:56	**General View**		Load JPG	
65	07/08/19 10:56	**General View**		Load JPG	
66	07/08/19 10:56	**General View**		Load JPG	
67	07/08/19 10:56	**General View**		Load JPG	
68	07/08/19 10:56	**General View**		Load JPG	
69	07/08/19 10:56	**General View**		Load JPG	
70	07/08/19 10:56	**General View**		Load JPG	
71	07/08/19 10:56	**General View**		Load JPG	
72	07/08/19 10:56	**General View**		Load JPG	
73	07/08/19 10:56	**General View**		Load JPG	
74	07/08/19 10:56	**General View**		Load JPG	
75	07/08/19 10:56	**General View**		Load JPG	
76	07/08/19 10:56	**General View**		Load JPG	
77	07/08/19 10:56	**General View**		Load JPG	
78	07/08/19 10:56	**General View**		Load JPG	
79	07/08/19 10:56	**General View**		Load JPG	

Assessment Reports 1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
80	07/08/19 10:56	**General View**		Load JPG	
81	07/08/19 10:56	**General View**		Load JPG	
82	07/08/19 10:56	**General View**		Load JPG	
83	07/08/19 10:56	**General View**		Load JPG	
84	07/08/19 10:56	**General View**		Load JPG	
85	07/08/19 10:56	**General View**		Load JPG	
86	07/08/19 10:56	**General View**		Load JPG	
87	07/08/19 10:56	**General View**		Load JPG	
88	07/08/19 10:56	**General View**		Load JPG	
89	07/08/19 10:56	**General View**		Load JPG	
90	07/08/19 10:56	**General View**		Load JPG	
91	07/08/19 10:56	**General View**		Load JPG	
92	07/08/19 10:56	**General View**		Load JPG	
93	07/08/19 10:56	**General View**		Load JPG	
94	07/08/19 10:56	**General View**		Load JPG	
95	07/08/19 10:56	**General View**		Load JPG	
96	07/08/19 10:56	**General View**		Load JPG	
97	07/08/19 10:56	**General View**		Load JPG	
98	21/08/19 17:37	**Reinspection Photo**		Load JPG	
99	21/08/19 17:37	**Reinspection Photo**		Load JPG	
100	21/08/19 17:37	**Reinspection Photo**		Load JPG	
101	21/08/19 17:37	**Reinspection Photo**		Load JPG	
102	21/08/19 17:37	**Reinspection Photo**		Load JPG	
103	21/08/19 17:37	**Reinspection Photo**		Load JPG	
104	21/08/19 17:37	**Reinspection Photo**		Load JPG	
105	21/08/19 17:37	**Reinspection Photo**		Load JPG	
106	21/08/19 17:37	**Reinspection Photo**		Load JPG	
107	21/08/19 17:37	**Reinspection Photo**		Load JPG	
108	21/08/19 17:37	**Reinspection Photo**		Load JPG	
109	21/08/19 17:37	**Reinspection Photo**		Load JPG	
110	21/08/19 17:37	**Reinspection Photo**		Load JPG	
111	21/08/19 17:37	**Reinspection Photo**		Load JPG	
112	21/08/19 17:37	**Reinspection Photo**		Load JPG	
113	21/08/19 17:37	**Reinspection Photo**		Load JPG	
114	21/08/19 17:37	**Reinspection Photo**		Load JPG	
115	21/08/19 17:37	**Reinspection Photo**		Load JPG	
116	21/08/19 17:37	**Reinspection Photo**		Load JPG	
117	21/08/19 17:37	**Reinspection Photo**		Load JPG	
118	21/08/19 17:37	**Reinspection Photo**		Load JPG	
119	21/08/19 17:37	**Reinspection Photo**		Load JPG	
120	21/08/19 17:37	**Reinspection Photo**		Load JPG	
121	21/08/19 17:37	**Reinspection Photo**		Load JPG	
122	21/08/19 17:37	**Reinspection Photo**		Load JPG	
123	21/08/19 17:37	**Reinspection Photo**		Load JPG	
124	21/08/19 17:37	**Reinspection Photo**		Load JPG	
125	21/08/19 17:37	**Reinspection Photo**		Load JPG	
126	21/08/19 17:37	**Reinspection Photo**		Load JPG	
127	21/08/19 17:37	**Reinspection Photo**		Load JPG	

Assessment Reports 1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
128	21/08/19 17:37	**Reinspection Photo**		Load JPG	
129	21/08/19 17:37	**Reinspection Photo**		Load JPG	
130	21/08/19 17:37	**Reinspection Photo**		Load JPG	
131	21/08/19 17:37	**Reinspection Photo**		Load JPG	
132	21/08/19 17:37	**Reinspection Photo**		Load JPG	
133	21/08/19 17:37	**Reinspection Photo**		Load JPG	
134	21/08/19 17:37	**Reinspection Photo**		Load JPG	
135	21/08/19 17:37	**Reinspection Photo**		Load JPG	
136	21/08/19 17:37	**Reinspection Photo**		Load JPG	
137	21/08/19 17:37	**Reinspection Photo**		Load JPG	
138	21/08/19 17:37	**Reinspection Photo**		Load JPG	
139	21/08/19 17:37	**Reinspection Photo**		Load JPG	
140	21/08/19 17:37	**Reinspection Photo**		Load JPG	
141	21/08/19 17:37	**Reinspection Photo**		Load JPG	
142	21/08/19 17:37	**Reinspection Photo**		Load JPG	
143	21/08/19 17:37	**Reinspection Photo**		Load JPG	
144	21/08/19 17:37	**Reinspection Photo**		Load JPG	
145	21/08/19 17:37	**Reinspection Photo**		Load JPG	
146	21/08/19 17:37	**Reinspection Photo**		Load JPG	
147	21/08/19 17:37	**Reinspection Photo**		Load JPG	
148	21/08/19 17:37	**Reinspection Photo**		Load JPG	
149	21/08/19 17:37	**Reinspection Photo**		Load JPG	
150	21/08/19 17:37	**Reinspection Photo**		Load JPG	
151	21/08/19 17:37	**Reinspection Photo**		Load JPG	
152	21/08/19 17:37	**Reinspection Photo**		Load JPG	
153	21/08/19 17:37	**Reinspection Photo**		Load JPG	
154	21/08/19 17:37	**Reinspection Photo**		Load JPG	
155	21/08/19 17:37	**Reinspection Photo**		Load JPG	
156	21/08/19 17:37	**Reinspection Photo**		Load JPG	
157	21/08/19 17:37	**Reinspection Photo**		Load JPG	
158	21/08/19 17:37	**Reinspection Photo**		Load JPG	
159	21/08/19 17:37	**Reinspection Photo**		Load JPG	
160	21/08/19 17:37	**Reinspection Photo**		Load JPG	
161	28/08/19 10:30	**Reinspection Photo**		Load JPG	
162	28/08/19 10:31	**Reinspection Photo**		Load JPG	
163	28/08/19 10:31	**Reinspection Photo**		Load JPG	
164	28/08/19 10:31	**Reinspection Photo**		Load JPG	
165	28/08/19 10:31	**Reinspection Photo**		Load JPG	
166	28/08/19 10:31	**Reinspection Photo**		Load JPG	
167	28/08/19 10:31	**Reinspection Photo**		Load JPG	
168	28/08/19 10:31	**Reinspection Photo**		Load JPG	
169	16/10/19 10:28	**Reinspection Photo**		Load JPG	
170	16/10/19 10:28	**Reinspection Photo**		Load JPG	
171	16/10/19 10:28	**Reinspection Photo**		Load JPG	
172	16/10/19 10:28	**Reinspection Photo**		Load JPG	
173	16/10/19 10:28	**Reinspection Photo**		Load JPG	
174	16/10/19 10:28	**Reinspection Photo**		Load JPG	
175	16/10/19 10:28	**Reinspection Photo**		Load JPG	

Assessment Reports 1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
176	16/10/19 10:28	**Reinspection Photo**		Load JPG	
177	16/10/19 10:29	**Reinspection Photo**		Load JPG	
178	16/10/19 10:29	**Reinspection Photo**		Load JPG	
179	16/10/19 10:29	**Reinspection Photo**		Load JPG	

Documentation 1 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	07/08/19 10:53	**Certificate of Insurance**		Load PDF	
2	07/08/19 10:53	**NRIC and Driving Licence**		Load PDF	
3	07/08/19 10:53	**ESTIMATE**		Load PDF	
4	07/08/19 10:53	**Singapore Accident Statement**		Load PDF	
5	21/08/19 17:36	**SUPPLEMENTARY.pdf**		Load PDF	
6	28/08/19 10:34	**SUPP 2.pdf**		Load PDF	
7	23/01/20 13:17	**ESTIMATE & SUPP MARKED.pdf**		Load PDF	
8	02/04/20 15:13	**DISCHARGE VOUCHER**		Load PDF	
9	02/04/20 15:13	**WORKSHOP INVOICE**		Load PDF	

Linked Accident Report Documents

View View in Browser

Assessment Reports 1 per page

No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	04/09/19 02:20	**Accident Statement**		Load HTM	

Photos/Images 3 per page

No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	05/08/19 16:29	**Accident Photo**		Load JPG	
2	05/08/19 16:29	**Accident Photo**		Load JPG	
3	05/08/19 16:29	**Accident Photo**		Load JPG	
4	05/08/19 16:29	**Accident Photo**		Load JPG	
5	05/08/19 16:29	**Accident Photo**		Load JPG	
6	05/08/19 16:29	**Accident Photo**		Load JPG	
7	05/08/19 16:29	**Accident Photo**		Load JPG	
8	05/08/19 16:29	**Accident Photo**		Load JPG	
9	05/08/19 16:29	**Accident Photo**		Load JPG	
10	05/08/19 16:29	**Accident Photo**		Load JPG	
11	05/08/19 16:29	**Accident Photo**		Load JPG	
12	05/08/19 16:29	**Accident Photo**		Load JPG	
13	05/08/19 16:29	**Accident Photo**		Load JPG	
14	05/08/19 16:29	**Accident Photo**		Load JPG	
15	05/08/19 16:29	**Accident Photo**		Load JPG	
16	05/08/19 16:29	**Accident Photo**		Load JPG	
17	05/08/19 16:29	**Accident Photo**		Load JPG	
18	05/08/19 16:29	**Accident Photo**		Load JPG	
19	05/08/19 16:29	**Accident Photo**		Load JPG	
20	05/08/19 16:29	**Accident Photo**		Load JPG	
21	05/08/19 16:29	**Accident Photo**		Load JPG	
22	05/08/19 16:29	**Accident Photo**		Load JPG	
23	05/08/19 16:29	**Accident Photo**		Load JPG	
24	05/08/19 16:29	**Accident Photo**		Load JPG	
25	05/08/19 16:29	**Accident Photo**		Load JPG	

Assessment Reports 1 per page

No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
26	05/08/19 16:29	**Accident Photo**		Load JPG	
27	05/08/19 16:29	**Accident Photo**		Load JPG	
28	05/08/19 16:29	**Accident Photo**		Load JPG	
29	05/08/19 16:29	**Accident Photo**		Load JPG	
30	05/08/19 16:29	**Accident Photo**		Load JPG	
31	05/08/19 16:29	**Accident Photo**		Load JPG	
32	05/08/19 16:29	**Accident Photo**		Load JPG	
33	05/08/19 16:29	**Accident Photo**		Load JPG	
34	05/08/19 16:29	**Accident Photo**		Load JPG	
35	05/08/19 16:29	**Accident Photo**		Load JPG	
36	05/08/19 16:29	**Accident Photo**		Load JPG	
37	05/08/19 16:29	**Accident Photo**		Load JPG	
38	05/08/19 16:29	**Accident Photo**		Load JPG	
39	05/08/19 16:29	**Accident Photo**		Load JPG	
40	05/08/19 16:29	**Accident Photo**		Load JPG	
41	05/08/19 16:29	**Accident Photo**		Load JPG	
42	05/08/19 16:29	**Accident Photo**		Load JPG	
43	05/08/19 16:29	**Accident Photo**		Load JPG	
44	05/08/19 16:29	**Accident Photo**		Load JPG	
45	05/08/19 16:29	**Accident Photo**		Load JPG	
46	05/08/19 16:29	**Accident Photo**		Load JPG	
47	05/08/19 16:29	**Accident Photo**		Load JPG	
48	05/08/19 16:29	**Accident Photo**		Load JPG	
49	05/08/19 16:29	**Accident Photo**		Load JPG	
50	05/08/19 16:29	**Accident Photo**		Load JPG	
51	05/08/19 16:29	**Accident Photo**		Load JPG	
52	05/08/19 16:29	**Accident Photo**		Load JPG	

Documentation 1 per page

No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	05/08/19 16:33	**Sketch Plan**		Load JPG	
2	05/08/19 16:33	**Sketch Plan #2**		Load JPG	

Documents Checklist

DOCUMENTS CHECKLIST Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19013814/GSF3S2
Date: 02/04/2020

REFERENCE

Insured/Claimant:	LIN YING	Policy No:			
Date of Loss:	02/08/2019	Nature of Claim:	OD	Claim No:	5997142761SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	**SJF345E**		
Make & Model:	AUDI Q5 SPORT, 2.0 TFSI QU S TRONIC (A)	Engine No:	DAX052445
Reg. Date:	30/04/2019 (Man. Year: 2019)	Chassis No:	WAUZZZFY7K2045178
Colour:	Blue	Odometer:	2916 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S$230,000.00		
Sum Insured (S$):	**Market Value/New Car Price**		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/55 R19	Rear Tyre Size:	235/55 R19
Front Left Side:	Continental 9 mm	Rear Left Side:	Continental 9 mm
Front Right Side:	Continental 9 mm	Rear Right Side:	Continental 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	68,497.64	24,943.44	43,554.20	63.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	20,844.00	9,139.00	11,705.00	56.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S$)	**89,341.64**	**34,082.44**	**55,259.20**	**61.85**
- Excess (S$)	1,000.00	1,000.00	0.00	0.00
(S$)	88,341.64	33,082.44	55,259.20	62.55
+ GST 7.00/7.00% (S$)	6,183.91	2,315.77	3,868.14	62.55
Nett Amount (S$)	**94,525.55**	**35,398.21**	**59,127.34**	**62.55**

INSPECTION

Date of Assignment:	07/08/2019		
Date Inspected:	06/08/2019	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	10.0 days		

Adjuster: XING GUO QIANG **Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER ASSY	Cracked	2,364.00 FS	*1,891.20 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	244.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP - LH/RH	Not Necessary	68.00 FS	*- FS
4	2		*FRONT BUMPER CLOSING ELEMENT - LH/RH	Not Necessary	202.00 FS	*- FS
5	1		*FRONT BUMPER GRILLE - CENTRE	Deformed	129.00 FS	*102.80 FS
6	1		*FRONT BUMPER SPONGE	Deformed	685.00 FS	*548.00 FS
7	1		*FRONT BUMPER UNDERRUN BAR - SILVER	Deformed	431.00 FS	*344.80 FS
8	1		*FRONT BUMPER CLOSING ELEMENT	Deformed	156.00 FS	*124.40 FS
9	1		*RADIATOR GRILLE	Cracked	3,258.00 FS	*2,606.40 FS
10	1		*QUATTO EMBLEM	Necessary	87.00 FS	*69.28 FS
11	1		*STRIKER PLATE	Cracked	222.00 FS	*177.20 FS
12	2		*FRONT BUMPER AIR GUIDE GRILLE LH/RH	Cut	1,038.00 FS	*829.60 FS
13	2		*FRONT BUMPER END CAP - LH/RH	Necessary	166.00 FS	*131.68 FS
14	1		*FRONT BUMPER LOCKING CLIP	Necessary	15.00 FS	*11.52 FS
15	1		*FOAM FILLER PIECE	Deformed	259.00 FS	*207.20 FS
16	1		*FRONT BUMPER CARRIER	Bent	831.00 FS	*664.40 FS
17	1		*FRONT BUMPER TOP COVER	Broken	116.00 FS	*92.40 FS
18	1		*FRONT BUMPER GUIDE SECTION - LH/RH	Not Necessary	68.00 FS	*- FS
19	1		*CAUTION SIGN STRIKER	Necessary	13.00 FS	*9.76 FS
20	1		*AIR COND STICKER	Necessary	18.00 FS	*14.00 FS
21	1		*PEDESTRIAN PROTECTION WARNING SIGN	Not Necessary	13.00 FS	*- FS
22	1		*HORN - LOW TORN LH	Not Necessary	178.00 FS	*- FS
23	1		*HORN - HIGH TONE RH	Not Necessary	178.00 FS	*- FS
24	2		*FRONT PARKING AID SENSOR - INNER	Damaged 1pc Only	462.00 FS	*184.80 FS
25	2		*FRONT PARKING AID SENSOR - OUTER	Not Necessary	462.00 FS	*- FS
26	4		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	12.00 FS	*- FS
27	1		*SET FRONT BUMPER WIRING	Not Necessary	378.00 FS	*- FS
28	2		*FRONT FENDER - LH/RH	Repair	2,602.00 FS	*- FS
29	2		*FRONT FENDER FRONT BRACKET - LH/RH	Not Necessary	412.00 FS	*- FS
30	2		*FRONT FENDER CENTRE BRACKET - LH.RH	Not Necessary	32.00 FS	*- FS
31	2		*FENDER ATTACHMENT PARTS - FRONT	Not Necessary	119.00 FS	*- FS
32	2		*FRONT FENDER INNER SHIELD - LH/RH OUTER	Not Necessary	142.00 FS	*- FS
33	2		*CLOSUER PANEL - LH/RH	Not Necessary	56.00 FS	*- FS
34	2		*COVER PANEL - LH/RH	Cracked	72.00 FS	*28.40 FS
35	2		*WHEEL HOUSING LINER - LH/RH	Not Necessary	492.00 FS	*- FS
36	1		*WHEEL SPOILER - LH	Not Necessary	146.00 FS	*- FS
37	1		*WHEEL SPOILER - RH	Torn	139.00 FS	*110.80 FS
38	1		*BONNET	Buckled	3,707.00 FS	*2,965.60 FS
39	2		*LID HINGE - LH/RH	Not Necessary	292.00 FS	*- FS
40	1		*BONNET ATTACHMENT PARTS	Not Necessary	127.00 FS	*- FS
41	1		*GAS FILLED STRUT	Not Necessary	217.00 FS	*- FS
42	2		*SAFETY CATCH - LH/RH	Not Necessary	218.00 FS	*- FS
43	1		*INSULATOR PAD	Not Necessary	289.00 FS	*- FS
44	1		*IMPACT PROTECTION - LH / RH / CENTRE	Necessary	75.00 FS	*59.44 FS
45	1		*PLENUM CHAMBER COVER	Not Necessary	131.00 FS	*- FS
46	2		*LID LOCK - FRONT	Not Necessary	391.00 FS	*- FS
47	2		*MICRO SWITCH - 2 PIN	Not Necessary	24.00 FS	*- FS
48	2		*RELEASE CABLE RETAINER	Not Necessary	18.00 FS	*- FS
49	1		*BOWDEN CABLE - CENTRE	Not Necessary	53.00 FS	*- FS
50	1		*RELEASE ELEMENT	Not Necessary	53.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
51	1		*RELEASE LEVER	Not Necessary	13.00 FS	*- FS
52	1		*LID LOCK CABLE	Not Necessary	67.00 FS	*- FS
53	1		*HEADLIGHT MOUNTING - LH / RH	Cracked	214.00 FS	*171.20 FS
54	1		*LED HEADLIGHT - LH / RH	N/s Not Necessary/O/s Cracked	14,454.00 FS	*5,781.60 FS
55	1		*LIGHT CONTROL SYSTEM CONTROL UNIT	Not Necessary	692.00 FS	*- FS
56	1		*MAIN LIGHT ELECTRONICS POWER MODULE	Not Necessary	693.00 FS	*- FS
57	1		*LED WITH HEAT SINK - RH	Not Necessary	990.00 FS	*- FS
58	1		*HEADLIGHT HOSE - RH	Not Necessary	35.00 FS	*- FS
59	2		*LIFT CYLINDER - LH / RH	Cracked	256.00 FS	*102.00 FS
60	1		*LIFT CYLINDER HOSE	Not Necessary	113.00 FS	*- FS
61	1		*WASHER PUMP	Not Necessary	147.00 FS	*- FS
62	1		*WASHER PUMP HOSE	Not Necessary	61.00 FS	*- FS
63	1		*WASHER PUMP INSULATOR	Not Necessary	19.00 FS	*- FS
64	1		*WINDSCREEN WASHER SYSTEM PUMP	Not Necessary	118.00 FS	*- FS
65	1		*WASH WATER RESERVOIR	Not Necessary	200.00 FS	*- FS
66	1		*WASH WATER RESERVOIR STRAINER	Not Necessary	24.00 FS	*- FS
67	1		*WASH WATER RESERVOIR END CAP	Not Necessary	59.00 FS	*- FS
68	1		*LOCK CARRIER	Cracked	1,169.00 FS	*935.20 FS
69	1		*A/C CONDENSER	Bent	547.00 FS	*437.60 FS
70	1		*REFRIGERANT LINE INLET	Not Necessary	263.00 FS	*- FS
71	1		*REFRIGERANT LINE OUTLET	Not Necessary	273.00 FS	*- FS
72	1		*RADAITOR	Bent	820.00 FS	*655.60 FS
73	1		*RADIATOR RUBBER BUSH - LOWER	Necessary	24.00 FS	*18.56 FS
74	1		*RADIATOR RUBBER BUSH - LOWER	Necessary	17.00 FS	*13.44 FS
75	1		*COOLANT FROST PROTECTION	Not Necessary	165.00 FS	*- FS
76	1		*INTERCOOLER	Bent	724.00 FS	*578.80 FS
77	1		*SEAL RING	Necessary	82.00 FS	*32.48 FS
78	1		*INTERCOOLER PRESSURE HOSE - RH	Not Necessary	283.00 FS	*- FS
79	1		*INTERCOOLER PRESSURE PIPE - LH	Not Necessary	477.00 FS	*- FS
80	1		*O-RING	Not Necessary	17.00 FS	*- FS
81	1		*MAP SENSOR	Not Necessary	183.00 FS	*- FS
82	1		*FAN RING	Cut	373.00 FS	*298.40 FS
83	1		*RADIATOR FAN WITH CONTROL UNIT	Dented	2,159.00 FS	*1,727.20 FS
84	1		*RADIATOR LOUVRE	Deformed	483.00 FS	*386.00 FS
85	2		*AIR GUIDE - UPPER / LOWER	Not Necessary	86.00 FS	*- FS
86	1		*AIR GUIDE - CENTRE	Torn	37.00 FS	*29.52 FS
87	2		*AIR GUIDE - LH/RH	Torn	100.00 FS	*39.68 FS
88	1		*SERVOMOTOR	Not Necessary	166.00 FS	*- FS
89	2		*ADJUST MOTOR CAP	Not Necessary	14,454.00 FS	*- FS
90	1		*AIR DUCT	Not Necessary	79.00 FS	*- FS
91	1		*AIR FILTER	Not Necessary	368.00 FS	*- FS
92	1		*INTAKE HOSE (NPA)	Not Necessary	0.00 FS	*- FS
93	2		*FRONT WHEEL COVER - LH/RH	Deformed	1,154.00 FS	*922.40 FS
94	2		*FRONT WINDOW SLOT SEAL WITH TRIM STRIP - LH/RH	Cut	1,074.00 FS	*859.20 FS
95	2		*WINDOW GUIDE TRIM STRIP - LH/RH	Not Necessary	622.00 FS	*- FS
96	1		*NOISE INSULATION	Not Necessary	743.00 FS	*- FS
97	1		*FRONT NO. PLATE	Bent	40.00 FS	*40.00 FS
98	1		*SUNDRIES	Necessary	1,000.00 FS	*240.24 FS
99	1		*LOCK CARRIER LHS	Bent	38.32 FS	*38.32 FS
100	1		*LOCK CARRIER RHS	Bent	38.32 FS	*38.32 FS
101	1		*FRONT BUMPER REINFORCEMENT BRACKET RHS	Bent	184.40 FS	*184.40 FS
102	1		*FRONT BUMPER REINFORCEMENT BRACKET RHS	Bent	184.40 FS	*184.40 FS
103	1		*HEADLIGHT COMPENSATING PIECE	Distorted	28.80 FS	*28.80 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
104	1		***HEADLIGHT ADJUSTING SCREW**	Necessary	26.40 FS	*26.40 FS

F=Franchise part. S=SpcNett.

Total Parts (S$)	**68,497.64**	**24,943.44**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TOW AND RECOVER VEHICLE FRONT SCENE OF ACCIDENT.	New	280.00	0.00
2	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORN, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	New	480.00	480.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGED AIR COOLER, RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	New	1,400.00	1,400.00
4	TO DISMANTLE BOTH FRONT DOOR PANEL TRIMS. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY.	New	600.00	300.00
5	TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FENDERS, BONNET AND BOTH HEADLIGHTS. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	7,200.00	3,000.00
6	TO RESPRAY FRONT BUMPER, FRONT LOWER SPOILER, RH FRONT FENDERS, BONNET, HINGES, BOTH FRONT WHEEL ARCH TRIMS, RH UPPER A-PILLAR AND LH FRONT DOORS.	New	9,300.00	3,575.00
7	TO CARRY OUT DIAGNOSTIC CHECKS.	New	384.00	384.00
8	TO RESPRAY LHS FRONT FENDER.	New	1,200.00	0.00
		Gross Labour Cost (S$)	**20,844.00**	**9,139.00**

Report was unsubmitted during this print-out.

< END OF ESTIMATES >