CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHB 4842E (Supplementary) DATE : 14.08.2019

MAKE : TEL : 6542 5119

MODEL : HYUNDAI IONIQ FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Windscreen Pillar Side Cover, LH displaced			$ 158.00
	SUB TOTAL			$ 158.00
	LESS 20%			$ 31.60
	DISCOUNTED TOTAL			$ 126.40

14/08/2019

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

CHUNNI MOTOR WORKS PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHB 4842E (Supplementary) DATE : 30.08.2019

MAKE : TEL : 6542 5119

MODEL : HYUNDAI IONIQ FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Gearbox partial jammed		LR 4500/-	$ ~~23,660.40~~
	SUB TOTAL			$ 23,660.40
	LESS 20%			$ 4,732.08
	DISCOUNTED TOTAL			$ 18,928.32
	Labour Charge			
	Remove/Refix Engine/Gearbox for wheel housing replacement.			$ ~~650.00~~ 250.00
	TOTAL LABOUR			$ 650.00
	ESTIMATE TOTAL			$ 19,578.32
	Ryan			4750.00
	LKK Auto			

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

5248.44

REPAIR ESTIMATE*

VEHICLE NO : **SHB 4842E (Supplementary)** DATE : **2.09.2019**

MAKE : TEL : **6542 5119**

MODEL : **HYUNDAI IONIQ** FAX : **6542 6039**

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Wheel Rim Sensor			$ 240.00
	SUB TOTAL			**$ 240.00**
	LESS 20%			**$ 48.00**
	DISCOUNTED TOTAL			**$ 192.00**

Ingar

KK Auto

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.