Yang Yun Xin Bus Service

50 Serangoon North Ave 4
#01-23, First Centre Singapore 555856
Tel :285 7585 Fax: 6382 5058

Date : 21/8/19

mate repair bill fo Toyota Hiace PC6339D

	Description	Unit	Amount
ts			
	Rear Door / Buc.	1	$4,500 ?
	Rear Door weather strip ?	1	$650
	Rear Bumper cover / Re.	1	$580
	rear undercarriage enforcement bar ?	1	$300
	70km sticker / Nil.	1	$30
	LOGO artwork sticker for paint spraying / Nil.	1	$250 100
	Tel artwork sticker for paint spraying / Nil.	1	$250 100
bour			
	To supply labour and materials to remove, replace and align damaged door/bumper/ parts		$1,500 400
	to putty and spray paint all affected area and panels		$1,800 ?
	to dismantle and reinstall door panel and window		$800 150
	to remove and reinstall power door motor		$100 50
	to test and reconnect all electric compound		$100 30

ABOVE PRICE QUOTED ARE SUBJECTED GST

E ABOVE ESTIMATE COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES

Guo Qiang - 82880282
Guo Qiang @ lkkauto.com
03/9/19.
part by part.
before paint photos.
5 Days.

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: