96 MOTORSPORTS

96 MOTORSPORTS PTE LTD
64 Kaki Bukit Ave 6 Singapore (417893)
Email: estimator@96motorsports.com
Tel: 67026996/83118211

VEHICLE NUM:	SJN 3481 H
MAKE & MODEL:	HONDA.FREED
MILEAGE:	
TYRE: FRONT	
TYRE: REAR	
CHASSIS NUM:	GB3-1033276

TP China.
Vic

GB3 1033276

ATTN:	

NO.	DESCRIPTION - PARTS	QTY	UNIT	ADJUSTED PRICE
1	TAIL GATE Dented	1	$ 1,460.30	1247.
2	TAIL GATE BADGE New	1	$ 67.00	✓
3	TAIL GATE EMBLEM (FREED) New	1	$ 82.70	✓
4	REAR BUMPER Rebound	1	$ 1,107.90	: 656.
5	REAR BUMPER SIDE RETAINER LH New	1	$ 126.80	✓
6	REAR BUMPER ATTACHMENT RETAINER LH New	1	$ 80.00	+
7	REAR BUMPER CLIP New	1SET	$ 20.00	✓
8	REAR BUMPER TOWING CAP New	1	$ 56.30	+
9	REAR TAIL LAMP LH Cracked	1	$ 879.00	372
10	REAR TAIL LAMP CLIP New	1SET	$ 30.00	✓
11	REAR SIDE TOP FENDER LH New	1	$ 620.00	+
12	REAR BUMPER REVERSE SENSOR L+R (ORIGINAL) Damaged	1	$ ~~500.00~~	200 (SN).
13	END PANEL Repair	1	$ 590.80	+
14	END PANEL TOP TRIM New	1	$ 125.00	+
	END PANEL TOP TRIM CLIP New	1SET	$ 40.00	+
	260/50 SN 200			
	208/20			
	SUBTOTAL		$ 5,785.80	$ -
	20%		$ 1,157.16	$ -
	PARTS TOTAL		$ 4,628.64	$ -

	SPECIAL NETT	QTY	PRICE	PRICE
1	REAR WINDSCREEN SEALANT New	1	$ 100.00	60.
	~~Reverse Sensor Damaged~~		60 ~~280~~ ~~209~~	
	SPECIAL NETT T		$ 100.00	$ -

	LABOUR	QTY	PRICE	PRICE
1	TO KNOCK, STRAIGHTEN AND REALIGN ACCIDENT AFFECTED AREA	1	$ ~~1,200.00~~	600
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	1	$ ~~1,000.00~~	600
3	TO RUST PROOF ACCIDENT AFFECTED AREA	1	$ ~~120.00~~	x
4	TO R&R REVERSE SENSOR FUNCTION	1	$ ~~120.00~~	50
5	TO R&R BOOT MECH	1	$ ~~120.00~~	80
6	TO R&R REAR WINDSCREEN 1450	1	$ ~~150.00~~	120
	LABOUR TOTAL		$ 2,710.00	$ -
	GRAND TOTAL COST		$ 7,438.64	$ -

Adrian Ling
L/S 27/08/19.
05 Pgs

total: 3791.20

L/S: 3K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: