SG 98 MOTOR PTE LTD

Date: 19th August 2019
To   LKK

Attn : Mr Bryan

VEHICLE NO   : FBE 8035Y   Gilera Nexus 300
ACCIDENT DATE: 9th Sept 2019

	Description	Qty	Quotation $	
1	Handle Bar *kt*	1	350.00	
2	Head Lamp Assy *broken*	1	550.00	
3	Centre Panel *cut*	1	395.00	
4	Front LH Cover Top *cut*	1	355.00	
5	Front Side Panel (LH/RH) *cut*	2	560.00	
6	Front LH Signal *Cut*	1	135.00	
7	Belly Pan (L/RH) *cut*	2	450.00	
8	Brake Lever *cut*	1	155.00	
9	Fork Tube *chyontins*	2	780.00	
10	Fork Under Bracket *HH*	1	280.00	X
11	Bar End Balancer *NH H/S O/S kt*	2 *setpcs*	258.00	129.00
12	Rear Rh Tail Panel *cut*	1	398.00	
13	Signal Lamp Guard - L/RH *cut*	2 pcs	255.00	

Sub-Total	4,921.00
Less 10%	492.10
Sub-Total	4,428.90

4512.00
10% 4060.80

VEHICLE NO   FBE 8035Y   Gilera Nexus 300

<u>Nett items</u>

1	Towing fee ~~HH~~		50.00	✗
2	Rear Box ~~HH~~		290.00	✗
2	Remove replace necessary parts align & etc		~~380.00~~ 200/-	
3	Remove & replace fork Assy front Rim, Fork oil seal fork oil	430·00	~~250.00~~ 80/-	
4	Putty & respray paint		~~480.00~~ 150/-	

            Sub-Total   1,450.00

            Nett Total   5,878.90

4490·80

L/S 3550/-

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion

Thank you

18/09/2019 @ 1130hrs
N/A Arrival
4 Survey 4days.

Nyan

LKK Auto

SG 98 MOTOR PTE LTD
:LG