Asher

wef

REC. BY: Marcus

REF: CTI/

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GU 3053 J

at Workshop m/s

of

Insured: XE 45165

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 9800 ~~9300~~

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

007N

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: GU 3053 J Yr Regn: 24/2/01

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or CM

Make: Mit L300 c.c 2477

Colour White A/C: Insured / Std / NI / NA

Sp.Reading 224623 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JMAJNP15VYA 001250

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185 R14

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Condor

	Front	Rear
R/Bal.	6 mm	6 mm
L/Bal.	6 mm	6 mm

D.O.A. 24/9/19 D.O.I. 24/9/19

Survey held at

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 yrs 5 mths. LTA bal 3776 Net ~~5524~~ 6024

7/10/19 confirmed M/S ₵6020 with Asher

M.V: ₵9,800
LTA: ₵3776
NETT: ₵6,024

(RED: ₵ 11,563 66%)

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: : Site Insp ($) __S + RS, __SI

: Interview ($) Photos

: Tech. Invs ($) Others

: Weekend ($)

TOTAL

Report Format :

Lump Sum / I.B.I: ($)

Not Allowed

24/9/19

L/S $6000

10 day.

FASTECH AUTO PTE LTD
BLK1 KAKI BUKIT AVE 6
#01-46,48,50 AUTOBAY
SINGAPORE 417883

VEHICLE NO:GU 3053J

QTY	PARTICULAR	AMOUNT
1 PCS	REAR WINDSCREEN RUBBER	$322.00
1 PCS	TAILGATE	$1,105.00
1 PCS	TAILGATE OUTER HANDLE	$365.00
1 PCS	TAILGATE INNER LOCK	$295.00
1 PCS	TAILGATE WEATHERSTRIP	$311.00
1 PCS	TAILGATE INNER TRIM BOARD	$345.00
1 PCS	TAILGATE REAR WIPER ARM	$105.00
1 PCS	TAILGATE REAR WIPER MOTOR	$680.00
1 PCS	REAR BUMPER	$655.00
2 PCS	REAR BUMPER SIDES @$205.00	$410.00
2 PCS	REAR BUMPER SIDE HOLDERS @$38.00	$76.00
1 PCS	REAR END PANEL OUTER	$625.00
1 PCS	REAR END PANEL INNER	$925.00
1 PCS	REAR FLOOR PANEL	$1,488.00
2 PCS	REAR FENDERS @$1405.00	$2,810.00
1 PCS	REAR FENDER OUTER RAILING N/S	$322.00
2 PCS	TAILLAMPS @$305.00	$610.00
2 PCS	TAILLAMP HOUSING PANELS @$299.00	$598.00
1 PCS	TAILLAMP INNER HOUSING PANEL N/S	$211.00
1 PCS	REAR SPARE TYRE BRACKET	$299.00
1 PCS	REAR SPARE TYRE BRACKET HOOK	$102.00
2 PCS	TAILLAMP DAMPERS @$302.00	$604.00
1 PCS	REAR LICENCE PLATE	$20.00
		$13,283.00
	LABOUR CHARGES	
	TO CHECK WIRING	$80.00
	TO DISMANTLE & REFIX REAR WINDSCREEN	$120.00
	TO DISMANTLE & REFIX TAILGATE MECHANISM	$100.00
	TO SPRAY RUST PROOFING	$180.00
	LABOUR FOR PANEL BEATING & REPLACING PARTS	$2,000.00
	TO PUTTY & SPRAY PAINTING	$1,800.00
	TOTAL	$17,563.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

5398
10%
5398.2
5058.2
6446.