AIG-LKK

ESTEEM PERFORMANCE

ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates SMG 2869 G

Not Authorised

Parts	(a) Cost / List Price Items	$	783.50
	Plus/Less 25%	$	195.88
	Total of Cost / List	$	587.63
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) **Special Nett Items**	$	200.00
Total Parts Cost		$	787.63
Labour		$	2,590.00
Total		$	3,377.63

The above total will be subjected to 7% G.S.T.

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Name of Surveyor : Kenneth

Company : LKK

Survey conducted on : 1/10/19 at 11.48am

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 01 day(s)

(c) Resurvey : Required / Not Required

(d) Excess :$

(e) Signature of surveyor : Date: 1/10/19

ESTEEM PERFORMANCE

ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. :	**SMG 2869 G**	Submit By :	**JENNY**
Make & Model :	TOYOTA PRIUS ALPHA	Year Manufacture :	2018
Chassis No :	ZVW400029112	Engine No. :	

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor	1	$200.00	S.N	X
2	Rear bumper	1	$499.60		X
3	Rear bumper clip	1	$38.90		X
4	Rear bumper side retainer LH	1	$62.70		X
5	Rear bumper side retainer RH	1	$62.70		X
6	Rear bumper reflector LH	1	$59.80		X
7	Rear bumper reflector RH	1	$59.80		X
8					
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

ESTEEM PERFORMANCE

ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SMG 2869 G** Submit By : **Carmen Lim**

Make & Model : TOYOTA PRIUS ALPHA Year of Manufacture : 2017

S/No	Labour Description	Esimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT		
	REPAIR AREA. (REAR BUMPER,TAIL DOOR,END PANEL)		
	~~	$1,000.00	X
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT		
	REPAIR AREA. (REAR BUMPER,TAIL DOOR,END PANEL)	$1,000.00	200/
3	To check wiring ~~	$50.00	X
4	To remove & refit reverse sensor ~~	$120.00	X
5	To remove & refit spare tyre, spare tyre board, carpet trim ~~	$150.00	X
	to assist work load.		
6	To tuff coat. ~~	$150.00	X
7	To conduct water leakage tests to ensure proper air and ~~	$120.00	X
	sealing		

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.