LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R   Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLK 551B

Qty	Description of Parts	Condition	Estimate By Workshop ($))	Our Adjusted ($)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER FASCIA (CONSISTENT)	DEFORMED	950.60	950.60
2	FRONT BUMPER SIDE RETAINER @$18.00 (CONSISTENT)	NECESSARY	36.00	36.00
1	FRONT BUMPER AIR GUIDE GARNISH (CONSISTENT)	DEFORMED	150.00	150.00
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	DENTED	420.30	420.30
10	FRONT BUMPER CLIPS @$3.70 (CONSISTENT)	NECESSARY	37.00	37.00
1	FRONT GRILLE (CONSISTENT)	CRACKED	350.00	350.00
1	FRONT GRILLE OUTER GARNISH (CONSISTENT)	NOT NECESSARY	301.20	-
4	FRONT GRILLE CLIPS @$3.90 (CONSISTENT)	NECESSARY	15.60	15.60
2	HEAD LAMP ASSY @$1200.30 (CONSISTENT)	CRACKED	2,400.60	1,892.00
2	HEAD LAMP LOWER BRACKET @$48.10 (CONSISTENT)	NOT NECESSARY	96.20	-
1	HORN ASSY (CONSISTENT)	NOT NECESSARY	40.30	-
	LESS 20% DISCOUNT		-959.56	-770.30
			3,838.24	3,081.20
	LABOUR			
	TO CHECK WIRING SYSTEM.		80.00	30.00
	TO TUFF COAT AFFECTED AREAS.	NOT NECESSARY	130.00	-
	TO RESPRAY AFFECTED AREAS.		580.00	200.00
	TO RENEW DAMAGED PARTS ,STRAIGHTEN & REPAIR FRONT SUPPORT PANEL & ALIGNED ALL PARTS.		550.00	300.00
			1,340.00	530.00
	GRAND TOTAL		**5,178.24**	**3,611.20**

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			**2,800.00**

Report Ref No. CC4/ASM19017960/Aga3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser