Kane | 3852

ASSIGNMENT

From: Date:
Estimated Cost:
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SLN 820J
at Workshop m/s TRANSEUROKARS
of 27A, Tanjong Pagar
Insured: SPF
Policy No:
Claims No:
Sum Insured: Excess:
(Client's Record)
Make of Veh:

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of Inspection.

Bal. or Market Value:
IDAC Accident Rport: Consistent? : Yes or No
GIA / PR Seen: Consistent? : Yes or No
Est. Repairs: days Res.: Yes or No
Lum Sum: % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Vehicle: IN / OUT
Date: Person Contacted:

Veh No: SLN 820J Yr Regn: 2017 / APR
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or
Make: MAZDA 3 1.5 AT cc 1496
Colour: BROWN A/C: Insured / Std / NI / NA
Sp Reading: 37310 T/Radio: Insured / Std / NI / NA
Eng/No:
C/No: JM6BN22A8H0151144
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 205/50R16
R:
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or FALKEN

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.	27/10/19	D.O.I.	31/10/19

Survey held at TRANSEUROKARS
Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or REAR O/S
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Repair limit 15K
	THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF $36,257.40, to $37000.00
	RECEIVED 2 7 NOV 2019
	reopen submit final
	submit $36,257.40, 27days (red:15011.20 ; 29%) Celine 03/06/2021

Date/Time File Pass to?
1) ~~28/11 Tuesday~~
Date/Time File Return to?
2)
3)

☑ : Prell. Report
☒ : Final Report

Days Of Repair: 27
Resurvey No. of Trip: —

Add Fee: ☐ Site Insp ($ ☐ Interview ($ ☐ Tech. Insp ($ ☐ Meet Insp ($

Survey Fee: 220
Transportation:
Photos:
Total: 220

Report Format: TP
Long Form / Letters