PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443
TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D   GST REG:200707743D

30-Oct-19

ESTIMATE REPAIR BILL FOR HYUNDAI I30A REGN NO: SHD 1189 S

1 pc	Front bumper	$ 811.11
1 pc	Front bumper sponge ~ missing	$ 218.03
1 pc	Front bumper reinforcement ✗	$ 636.40
1 pc	Front bumper tow cap ✗	$ 60.10
2 pcs	Front n/s & o/s headlamp @ $1531.57 ✗ o/s ✓ n/s✗	$ 3,063.14
1 pc	Bonnet grille ✗	$ 566.46
1 pc	Front bumper emblem ✗	$ 27.80
1 pc	Front bumper o/s fog lamp cover ✗	$ 25.00
2 pcs	Front n/s & o/s side bracket @ $32.51 ✗ o/s ✓ n/s✗	$ 65.02
1 pc	Front o/s fender	$ 514.02
1 pc	Front o/s fender inner shield ✗	$ 176.72
1 pc	Front o/s rim ✗	$ 246.00
		$ 6,409.80
	Less 20%	$ 1,281.96
		$ 5,127.84

LKK Auto Consultants hence notify
the Repairer of the following:
- To resurvey before & after spray painting
- To display damaged parts ... key
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: LKK
Date:

S/NETT

1 set	Front bumper clips	$ 48.00
1 pc	Front o/s fender sticker	$ 30.00
	Sundry	$ 50.00 20
	Towing Fee	$ 50.00
	To check for front o/s wheel alignment	$ 80.00 ✗
	To check wiring and forcus on front n/s & o/s headlamp	$ 80.00 20
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc.	$ 650.00 400
	To putty and spray painting on front bumper, front o/s fender	$ 400.00 360
	To apply rustproofing on the repaired and replaced panels.	$ 120.00 50
		$ 6,635.84

30/10/19 1000h
3 Pm.
PP
Before Pull photo

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)
*THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.*