LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV No.	AC2102186
INV Date	05/04/2021
Reference	CC6/CTI19021329/Apa3q2
Code	CTI

PROFESSIONAL SERVICE FEE

Vehicle No.	GBE 1765U
Insured Veh.	GBD 9767S
Claim No.	SNM19D205733
Policy No.	DMCVSN3074711903
Accident Date	02/12/2019
Inspection Date	02/12/2019

Description	**Total**
Third Party Express Settlement	400.00
Subtotal	**400.00**
GST (7%)	**28.00**
Grand Total	**428.00**

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD		Ref:	CC6/CTI19021329/Apa3q2
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date:	05/04/2021
		Code:	CTI

1.	Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	GBD 9767S	**Veh. Inspected**	GBE 1765U
	Policy No.	DMCVSN3074711903	**Coverage ($)**	0.00
	Claim No.	SNM19D205733	**Excess ($)**	0.00
	Assign From		**Assign Date**	02/12/2019

2.	Vehicle Particulars & Condition			
	Make & Model	NISSAN NV350	**c.c**	2488
	Engine No.	HIDDEN	**Year of Reg.**	2015
	Chassis No.	JN1MC2E26Z0005022	**Colour**	GREY
	Odometer	117964 KM	**Steering**	IN ORDER
	Brakes	IN ORDER	**Modification**	NIL
	General	GOOD		

3.	Conditions of Tyres			
		Size	**Make**	**Balance**
	R/H Front Tyre	195 R15C	YOKOHAMA	6 mm
	L/H Front Tyre	195 R15C	YOKOHAMA	6 mm
	R/H Rear Tyre	195 R15C	YOKOHAMA	6 mm
	L/H Rear Tyre	195 R15C	YOKOHAMA	6 mm

4.	Description of Damages
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.

5.	General Information			
	Accident Date	02/12/2019	**Inspection Date**	02/12/2019
	Survey held at	HUA MENG SPRAY PAINTING WORKSHOP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883		

5a.	Remarks
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b.	Estimate Days of Repair	
	ESTIMATED NORMAL PERIOD FOR REPAIR:	**6 Working Days**

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 1765U

Qty	Description of Parts	Condition	Estimate By Workshop ($))	Our Adjusted ($)
	REPLACEMENT OF PARTS			
1	REAR WINDSCREEN	CUT	980.10	980.10
1	REAR TAILGATE	DISTORTED	1,998.40	1,742.00
2	REAR TAILGATE HINGES @$59.60	NOT NECESSARY	119.20	-
1	REAR TAILGATE UPPER LOCK	DAMAGED	355.40	355.40
1	REAR TAILGATE LOWER LOCK	NOT NECESSARY	60.50	-
2	REAR TAILGATE SIDE UPPER LOCK @$82.30	NOT NECESSARY	164.60	-
2	REAR TAILGATE SIDE LOWER LOCK @$82.30	NOT NECESSARY	164.60	-
2	REAR TAILGATE SHOCK ABSORBER @$237.50	NOT NECESSARY	475.00	-
1	REAR TAILGATE INNER BOARD	DEFORMED	217.80	217.80
1	REAR TAILGATE WEATHER STRIP	CUT	37.70	37.70
1	REAR TAILGATE CENTRE NISSAN EMBLEM	NECESSARY	87.90	87.90
1	REAR TAILGATE HANDLE	CRACKED	589.30	511.40
1	REAR TAILGATE NV350 EMBLEM	NECESSARY	121.00	121.00
2	REAR NUMBER PLATE LAMP @$107.60	NOT NECESSARY	215.20	-
1	REAR END PANEL	DENTED	291.10	291.10
1	REAR END PANEL TOP NUMBER PLATE	NOT NECESSARY	100.20	-
1	REAR STEP PANEL	BENT	178.90	178.90
1	REAR BUMPER	DEFORMED	733.90	667.00
2	REAR BUMPER SIDE HOLDER @$24.40	NECESSARY	48.80	48.80
1	SET REAR BUMPER CLIPS	NECESSARY	66.00	30.00
2	REAR LAMP @$247.30	CRACKED	494.60	494.60
1	REAR TAILGATE CENTRE LOCK	DAMAGED	196.40	196.40
	LESS 10% DISCOUNT		-769.66	-596.01
			6,926.94	5,364.09
1	REAR TAILGATE 70KM STICKER (SN)	NECESSARY	33.00	15.00
1	REAR TAILGATE 8 PAX STICKER (SN)	NECESSARY	33.00	15.00
	LESS 10% DISCOUNT		-6.60	-
			59.40	30.00

Report Ref No. CC6/CTI19021329/Apa3q2

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Qty	Description of Parts	Condition	Estimate By Workshop ($))	Our Adjusted ($)
	SPECIAL NETT ITEMS			
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	50.00	-
1	SET REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	380.00	200.00
			430.00	200.00
	LABOUR			
	TO SUPPLY REAR WINDSCREEN SEALANT .		50.00	50.00
	REMOVE & REINSTALL REAR WINDSCREEN .		150.00	120.00
	REMOVE & REINSTALL REVERSE SENSOR .		150.00	50.00
	REMOVE & REINSTALL EXHAUST PIPE .	NOT NECESSARY	150.00	-
	REMOVE ,REPLACE & REPAIR CONSISTENT TO THE ACCIDENT .		1,600.00	800.00
	RESPRAY PAINTING .		1,400.00	1,000.00
	TUFF KOTE.		150.00	60.00
			3,650.00	2,080.00
	GRAND TOTAL		**11,066.34**	**7,674.09**

	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			**6,000.00**

Report Ref No. CC6/CTI19021329/Apa3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBE 1765U **INSPECTION**

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBE 1765U **RE-INSPECTION**

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R