All fund tran... 2528214000... ...til payme... ...ession... ...ice

REC. BY: Rasul | REF: MG | C 7782

ASSIGNMENT

From: | Date: 05/12/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMM 9537L

at Workshop m/s Tong Luck Auto

of 160 S/M Drive #07-01/06 S/M Industry

Insured:

Policy No.

Claims No.

Sum Insured: | Excess: ~~TBA~~ $1200/=

(Client's Record)

Make of Veh:

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 282K

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SMM 9537L Yr Regn: 2019 / July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: MERCEDES BENZ E300 AVG c.c 1991

Colour GREY A/C: Insured / Std / NI / NA

Sp.Reading 5158 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WDD2130832A676357

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/45R18

R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.	27/11/19	D.O.I.	05/12/19

Survey held at Tong Luck

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or O/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

RECEIVED 14 JAN 2020

Date/Time, File Pass to? ☐ : Preli. Report ☐ : Final Report

1)

Date/Time, File Return to?

2) 13/1/20 Typist

Days Of Repair: 4

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp ($) ☐ : Interview ($) ☐ : Tech. Invs ($) ☐ : Weekend ($)

Report Format :

Lump Sum / I.R.I: ($)

PP $3706-00

Survey Fee:	200
Transportation:	
___S + RS, ___SI	
Photos	
Others	11
TOTAL	211