CL

MFORTDELGRO ENGINEERING PTE LTD

PAIR ESTIMATE*

240• +
200• =
440• *

EHICLE NO : SHC 8506U **DATE**

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper x(R)			$ 553.00	
	Rear Bumper Clip 10 pcs xnn			$ 22.00	
	Rear Bumper Bracket xnn		$ 35.60	$ 71.20	
	Rear Bumper Under Cover xnn			$ 228.00	
	Rear Bumper Reflector Lamp (RH) xnn			$ 30.60	
	SUB TOTAL			**$ 904.80**	
	LESS 20%			$ 180.96	
	DISCOUNTED TOTAL			**$ 723.84**	
	Rear Bumper Reverse Sensor xnn			$ 135.70	**Nett**
	Rear Bumper Rubber Mat xnn			$ 50.00	**Nett**
				$ 185.70	
	Labour Charge				
	Panel Beating			$ 350.00	$240
	Spray Painting Charge			$ 250.00	$200
	Wiring Charge			$ 50.00	xm
	Remove/Refix Reverse Sensor			$ 80.00	xm
	TOTAL LABOUR			**$ 730.00**	
	ESTIMATE TOTAL			**$ 1,639.54**	

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Paraseran@lkkauto.com
6/12/19 1200hrs
2 repairing days
aft repair photo
(45)

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.