Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1486/2019/NS
Date	:	17-Dec-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Taufikh

4 days - ok - jb - 11 Mar 20

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Koh Long Yi Adilson
Address	:	23 Jalan Raja Udang
		#33-08
		Singapore 329216
Telephone	:	(HP) +65 82220917
Type of Claim	:	Own Damage Claims
Policy No.	:	1900010892
Vehicle No	:	**SKG 3293 J**
Model Code	:	Audi A5 SB 2.0 TFS
Model / Year	:	1/31/2019
Engine No	:	CVK 075791
Chassis No	:	WAUZZZF5XKA022277
Mileage	:	-
Date In	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	14-Dec-19
Place of Accident	:	Sentosa Gateway

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323   Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKG 3293 J

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N $	480.00	*$* *480.00*
2	To dismantle and renew front bumper, lhs front fender and lhs headlight. Re-organise crash management components. Reinstall all parts removed.(Additional $250 for renew headlight)	$	2,800.00	*$* *1,250.00*
3	To respray front bumper and lhs front fender.	$	2,200.00	*$* *1,100.00*
4	To renew lhs front rim and carry out wheel alignment.	S/N $	280.00	*$* *280.00*
5	To carry out diagnostic checks.	S/N $	192.00	*$* *192.00*
	TOTAL LABOUR CHARGES	: $	**5,952.00**	*$* *3,302.00*

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323   Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKG 3293 J

S/N	Parts Description		Damaged Parts & Prices S/Nett		Remarks
1	FRONT BUMPER	($2,660.00)	Type error	$	*2,128.00*
2	FRONT BUMPER FIXING PARTS		$	368.00	
3	FRONT BUMPER SECURING STRIP		$	32.00	
4	FRONT BUMPER GRILLE - CENTRE		$	178.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE		$	207.00	
6	FRONT BUMPER SPOILER		$	489.00	
7	FRONT BUMPER AIR GUIDE - LH		$	56.00	
8	FRONT BUMPER AIR GUIDE GRILLE - LH		$	431.00	
9	FRONT BUMPER GUIDE SECTION - LH		$	33.00	
10	FRONT PARKING AID SENSOR - OUTER / INNER		$	231.00	
11	FRONT PARKING AID SEAL RING	4	$	12.00	$ *9.60*
12	*FRONT FENDER - LH*		$	968.00	$ *774.40*
13	FRONT FENDER ATTACHMENT PARTS		$	48.00	
14	FRONT FENDER CLOSING ELEMENT - LH		$	68.00	
15	FRONT FENDER BRACKET - LH		$	32.00	
16	FRONT FENDER BRACE - LH		$	107.00	$ *85.60*
17	FRONT FENDER BRACKET		$	32.00	
18	DEFORMATION ELEMENT BRACKET - LH		$	45.00	
19	FRONT WHEEL HOUSING LINER - LH		$	256.00	
20	WHEEL HOUSING LINER ATTACHMENT PARTS		$	82.00	
	SUB TOTAL SPARE PARTS	:	**$**	**3,675.00**	$ *2,997.60*

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323   Fax : 6841 1183

Telefax

Name	:	
Surveyed Date	:	
Authorised Date	:	
Excess Cost	:	
Liability	:	
Remarks	:	

Please Note   :   This estimate is based on visual inspection of the affected vehicle.

Should we require further labour charges and spare parts in the

progress of repair, we shall inform you accordingly.

For inspection of vehicle, please refer to Ms Norah Khai at

Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo   Allan Wu
Body Repair Manager   Claims Consultant