源摩哆廠

GUAN MOTOR WORKS

Business Regn. No: 08102600E

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE FOR SJT4245K

No.	Qty			
		List Items		
1	1	Rear bumper	$	451.60
2	2	Rear bumper reflector	$	285.80
3	2	Rear bumper inner side bracket	$	112.60
4	2	Rear bumper side retainer	$	171.20
5	2	Rear bumper corner retainer	$	86.00
6	1 set	Rear bumper clips	$	30.00
7	1	Rear boot lid	$	589.10
8	1	Rear boot outer handle garnish	$	175.00
9	1	Rear boot centre "TOYOTA" logo	$	48.10
10	1	Rear boot LH "VIOS" emblem	$	55.60
11	1	Rear boot RH "E" emblem	$	45.30
12	2	Rear boot hinge	$	128.00
13	1	Rear boot top lock	$	121.35
14	1	Rear boot lower lock catch	$	41.40
15	1	Rear boot weatherstrip	$	176.80
16	2	Taillamp panel	$	257.00
17	2	Taillamp	$	665.20
18	1	Rear end panel	$	575.00
19	1	Rear end panel top garnish	$	211.40
20	1	Rear spare tyre panel	$	682.50
21	1	Rear spare tyre top board	$	139.50
22	1	Rear compartment centre foam tray	$	167.50
23	2	Rear compartment top side board	$	96.00
24	1	Rear compartment RH foam tray	$	192.36
25	1	Rear compartment LH foam tray	$	154.35
26	2	Rear fender inner side trim	$	451.00
27	1 set	Rear fender inner side trim clips	$	60.00
28	1	Rear exhaust silencer	$	811.30
			$	6,880.96
		Less 25%	$	1,720.24
		Total :	$	5,160.72

ERR Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

		Special Nett Items		
29	1 set	Reverse sensors	$	250.00
30	1 set	Reverse camera	$	550.00
31	1	Rear number plate	$	50.00
32	1	Rear bumper lower skirting	$	800.00
33	1	Rear exhaust tail chrome pipe	$	120.00
34	1 set	Rear spare tyre/end panel sealant	$	100.00
			Total : $	1,870.00

		Labour		
1		Labour Charges for remove/refit, cutting/welding and replacement of damages.	$	1,300.00

2	To putty and spray Spray Paintings charges.	$	1,200.00	900
3	To check wirings and lightings.	$	40.00	20
4	To remove, refit reverses sensors & reverse camera.	$	100.00	50
5	To remove, refit rear boot lid fittings.	$	80.00	50
6	To remove, refit rear upholstery and attachments.	$	150.00	60
7	To remove, refit rear exhaust silencer.	$	80.00	?
8	To supply and apply anti rust treatment	$	80.00	60
	Total :	$	3,030.00	
	Total Parts and Labour :	**$**	**10,060.72**	