SLS 8609

Search

	Reference No.	Entry Date	Customer	Vehicle No.	Insured Veh.	Accident Date
	CC3/AIG20002119/Fks3	06/02/2020	AIG	SLS 8609A	SGF 9992M	22/01/2020
	NBA/LIP20001320/Y	22/01/2020	LIP	SLS 8609A	SGF 9992M	22/01/2020

First Previous 1 of 1 Next Last

ONE
7/4/2020
Chancha confirmed.

REF: CC3/AIG20002119/FKS3

AIGAsia Insured's Veh No : SGF9992M
Date of Accident : 22 October 2020

TAN LIM MOTOR PTE LTD
1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Mr Ker Eng Ling

Date : 05 February 2020

Estimate To Repair SLS8609A - Honda Grace Hybrid 1.5 LX CVT
Chassis No : GM41109753

S/No	Quantity	Description		Amount	
		LIST ITEMS			
01	1 pc	o/s rear fender	S	1,134.80	
02	1 pc	o/s rear fender inner cowling	S	85.00	
03	6 ps	o/s rear fender inner cowling @ $3.50	S	21.00	
04	1 pc	o/s rear fender air vent	S	35.70	
05	1 pc	rear bumper	S	463.70	
06	1 pc	rear bumper side retainer o/s	S	13.90	
07	10 ps	rear bumper clips @ $3.50	S	35.00	$25
08	1 pc	o/s rear wheel hub cap	S	75.00	
09	1 pc	o/s rear door	S	759.60	
			S	2,623.70	
		Less 20 %	S	524.74	
			S	2,098.96	
		SPECIAL NETT ITEMS			
10	1 pc	o/s rear fender 1/4 glass sealant	S	100.00	$70
11	1 pc	rear windscreen sealant	S	40.00	
			S	140.00	$110.00
		LABOUR & MISC. CHARGES			
01		To rust-proofing of the affected areas.	S	80.00	$50
02		To transfer of door fittings and perform water seepage test.	S	100.00	$60
03		To reinstall of rear bumper parking sensor.	S	80.00	$60
04		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	S	800.00	$450
05		Putty and spray painting of the affected portion.	S	800.00	$600
06		To remove and refit rear windscreen glass.	S	120.00	$50
			S	1,980.00	1,300.00
			S	4,218.96	2,965.5

$2458.1
$1966.48

1,965.40
393.88
1,575.52

Total
ITEM: $1966.48/=
NETT: $110
Labar: $1300
Total: $3376.48
L/s: $2700/=
Supplier-tey

Rem (LKC)
5/2/2020 1110 hrs
[illegible]@lkcauto.com
[illegible]3778 (S replacing)
Dismantle required

Rem

20%
2,388

Lump Sum $2,400.00

5 days repair.

| | | |