DONE 7/4/2020 confirmed. Khancha

REF: CC3/AIG20002119/FKS3

AIGAsia Insured's Veh No : SGF9992M
Date of Accident : 22 October 2020

TAN LIM MOTOR PTE LTD
1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Mr Ker Eng Ling

Date : 05 February 2020

Estimate To Repair SLS8609A - Honda Grace Hybrid 1.5 LX CVT
Chassis No : GM41109753

S/No	Quantity	Description		Amount	
		LIST ITEMS			
01	1 pc	o/s rear fender	$	1,134.80	
02	1 pc	o/s rear fender inner cowling xnn	$	85.00	
03	6 ps	o/s rear fender inner cowling @ $3.50 xnn	$	21.00	
04	1 pc	o/s rear fender air vent 1 xnn	$	35.70	
05	1 pc	rear bumper 1 cva	$	463.70	
06	1 pc	rear bumper side retainer o/s xnn	$	13.90	
07	10 ps	rear bumper clips @ $3.50 1 nec	$	35.00	$25
08	1 pc	o/s rear wheel hub cap	$	75.00	
09	1 pc	o/s rear door	$	759.60	
			$	2,623.70	
		Less 20 %	$	524.74	
			$	2,098.96	
		SPECIAL NETT ITEMS			
10	1 pc	o/s rear fender 1/4 glass sealant nec	$	100.00	$70
11	1 pc	rear windscreen sealant nec	$	40.00	
			$	140.00	$110.00
		LABOUR & MISC. CHARGES			
01		To rust-proofing of the affected areas.	$	80.00	$50
02		To transfer of door fittings and perform water seepage test.	$	100.00	$60
03		To reinstall of rear bumper parking sensor.	$	80.00	$60
04		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	$	800.00	$450
05		Putty and spray painting of the affected portion.	$	800.00	$600
06		To remove and refit rear windscreen glass.	$	120.00	$50
			$	1,980.00	1,300.00
		Total	$	4,218.96	

$2458.1
$1966.48

1,960.40
393.88
1,575.52

ITEM: $1966.48/=
NETT: $110
Labour: $1300
Total: $3376.48
L/s: $2700/=
Sreprintay

Rem (LKK) 1/2/2020 110 hrs
Dismantle required

-20%

2,388.41

5 days 10%