TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.
78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT
TEL : 6419 3000   FAX : 6415 3723

YOUR REF NO :
CLAIM TYPE : OWN DAMAGE
ACCIDENT DATE : 13/01/2020

[handwritten: 13/2/2020. Not Authorise Recovery B4 pain]

ESTIMATE

NO	: QUOT202001-000038(00)
DATE	: 12/02/2020
POLICY NO	: 999995580
VEH REG NO	: **GBF4508X**
MAKE/MODEL	: MERCEDES BENZ CITAN 108 CDI L 5MT 5DR
CHASSIS NO	: WDF4156032U191735
ENGINE NO	: K9KE628D159240
REG. DATE	: 0

[handwritten: 3-4 days, fax 6256 4315]

Estimate Repair Cost to Vehicle No : GBF4508X

	Description	Quantity	Unit Price S$	Amount S$
	PARTS			
1	Support Panel	1	480.00	480.00
2	Front grille	1	175.00	175.00
3	Front grille support	1	120.00	120.00
4	Front grille centre logo	1	58.00	58.00
5	Headlamp assy - RH / LH	2	285.00	570.00
6	Front bumper	1	880.00	880.00
7	Front bumper reinforcement	1	450.00	450.00
8	Front bumper reinforcement cover	1	285.00	285.00
				3,018.00
			Add 10%	301.80
				3,319.80
	SPECIAL NET			
9	Front number plate	1	40.00	40.00
				40.00
	LABOUR			
10	To remove and refit air-co condenser, radiator and refill air-con gas	1	150.00	150.00
11	To check and rectify wiring system	1	80.00	80.00
12	To panel beat and repair front chassis frame, including replacement of parts and align where necessary, to refit and adjust the same	1	800.00	800.00
13	To putty and spray paint on affected areas	1	800.00	800.00
				1,830.00

[handwritten: Front reinforcement bracket $58/-]

TOTAL	S$ 5,189.80
ADD GST @ 7%	363.29
GRAND TOTAL	S$ 5,553.09

SINGAPORE DOLLAR FIVE THOUSAND FIVE HUNDRED FIFTY-THREE AND CENTS NINE ONLY

[handwritten calculations:
$1,851.00
10% 185.10 als w/com
$2,036.10

XS $2,696.10
*   1,400.00*
7% $1,296.10
*   90.73*
* $1,386.83]*

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE