Repair Estimate

VAG Singapore Pte Ltd
48 Toh Guan Road East
#05-123, Enterprise Hub
Singapore 608586

Tel: 6267 9916
Fax: 6267 9313
www.avantage.sg

Steve (LKK)
8322 8813
stevechm@lkkauto.com

WL RL
3 dy
L/S
Ry & Ry

Date : 11-Feb-2020
Vehicle Num : SGZ1527X
Make/Model : Honda Stream 1.8
Chassis No : RN61035742

S/N	PARTS	QTY	PRICE	TOTAL
1	Rear bumper cover / DD	1	$ 740.00	$ 740.00
2	LH parking sensor / BR	1	$ 30.00	$ 30.00
3	Tow eye cap / CRY	1	$ 35.00	$ 35.00
	TOTAL PARTS			$ 805.00
	TOTAL AMOUNT			$ 805.00
	MISCELLANEOUS ITEM			
1	*Sundries*		$ 30.00	$ 30.00
	LABOUR			
1	Removal and refitting of rear bumper, transfering of wire sets		$ 300.00	$ 250 300.00
2	Surface preparation, putty and spray paint of rear bumper and tailgate		$ 600.00	$ 250 600.00
3	Parking sensor testing and calibration		$ 90.00	$ 30 90.00
4	Vehicle diagnostics and clearing of fault codes after repair		$ 150.00	$ X 150.00
	TOTAL			$ 1,975.00
	GST 7%			$ 138.25
	GRAND TOTAL			$ 2,113.25

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: