S. REC. BY: Rafan | REF: SMO | 700B

PRS

ASSIGNMENT

COE expiry: 2029/JUN

From: | Date: 28/2/2020

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLC 2671S

at Workshop m/s Gold Autoworks

of 48 Toh Guan Road # 01-119

Insured:

Policy No.

Claims No.

Sum Insured: | Excess:

(Client's Record)

Make of Veh: 4pm-6pm

Simon @ 8199 9149

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 90K

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS / up

Vehicle: IN / OUT

Date: | Person Contacted:

Veh No: SLC 2671S | Yr Regn: 2009 / FEB

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: MERCEDES BENZ C180K | c.c 1796

Colour BLACK | A/C: Insured / Std / NI / NA

Sp.Reading 129813 | T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WDD2040462A233155

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45ZR17

R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.	05/02/2020	D.O.I.	28/02/2020

Survey held at GOLD AUTO

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or N/S FRT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Lump Sum $2200/- (Red: 2242.65 : 50%)
	9442.65

Date/Time, File Pass to? ☐ : Preli. Report

1) 22/5 Typist ☑ : Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: ($ 2200)

Days Of Repair: 4

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Survey Fee:	
Transportation:	
___S + RS.___SI	
Photos	
Others	
TOTAL	