FUJITSU

ASS. REC. BY: TGLim | REF: AIG CCA/AIG 20005014/Bha 3 | NIC

ASSIGNMENT

From: | Date: 8/4/2020

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGS 7761H

at Workshop m/s Jeam Auto pro

of 160 Sin Ming Dr, # 01-14

Insured:

Policy No.

Claims No.

Sum Insured: | Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 43,000/-

IDAC Accident Rport: | Consistent? : Yes or No

GIA / PR Seen: | Consistent? : Yes or No

Est. Repairs: 3 days | Res.: Yes or No

Lum Sum: % | 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WP

Vehicle: IN / OUT

Date: | Person Contacted:

Veh No: SGS 7761H | Yr Regn: 23/3/2007

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Honda Accord 2.0 | c.c 1998

Colour Brown | A/C: Insured / Std / NI / NA

Sp.Reading 194339 | T/Radio: Insured / Std / NI / NA

Eng/No: K20A6043728

C/No: CL73203215

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45/17

R: 225/45/17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	7 mm	R/Bal.	7
L/Bal.	7 mm	L/Bal.	7

D.O.A. 30/3/2020 | D.O.I. 8/4/2020

Survey held at Jeam AutoPro

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to co

Date / Time	Action / Instruction
	L/S 2658/2 TGLim 24/4/2020
	MV 43,000/2
	PV 35,026/2
	NV 9376/2

TGLim 8/4/202

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: ($)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Survey Fee:

Transportation: S + RS S

Photos

Others

TOTAL