Not Authorised
d/s $3000/
4 days

Page No. 1

VEHICLE NO SKE 4073G HYUNDAI ELANTRA

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S$)	SURVEYOR'S ADJUSTMENT
	PARTS (LIST ITEMS)			
1	Rear bumper	495.40	D/J 1124.60	✓
2	Rear bumper side retainer @$75	65.00	O/Sheet 150.00	50
1	Rear bumper reinforcement	415.00	CNE 578.00	✓
6	Rear bumper reinforcement brackets @45.20		〃 271.20	X
1	Rear bumper inner foam		〃 142.00	X
2	Rear bumper reflectors @$78.50	68.50	O/Sgcr 157.00	50
2	Rear bumper brackets @ $98.20		〃 196.40	X
1	Rear end panel	453.80	DD 689.00	✓
1	Rear end panel top garnish		〃 276.50	X
1	Rear spare tyre panel	REPAIR	〃 0.00	X
1	RHS Rear fender		R 752.00	X
1	RHS Rear fender inner trim		〃 298.60	X
1	RHS Rear fender inner shield		〃 198.00	X
1	Rear windscreen moulding		〃 67.30	X
1	Bootlid		R 1245.00	X
2	Bootlid hinge	REFIX	〃 0.00	X
1	Boot edge weatherstrip		〃 172.00	X
1	Bootlid logo (centre badge)		NEW 48.00	✓
1	Bootlid "ELANTRA" emblem	48.00	NEW 78.00	✓
1	Bootlid "HYUNDAI" emblem	52.00	NEW 98.00	✓
4	Bootlid rubber stopper @12.00		〃 48.00	X
1	Bootlid lock		〃 228.40	X
1	Bootlid lock catch		〃 75.20	X
1	Bootlid inner trim	REFIX	〃 0.00	X
1	Bootlid reflector RHS		〃 346.20	X
1	Bootlid keyless lock actuator		〃 242.50	X
1	RHS Taillamp	385.00	CNG 652.50	✓ 20307
			8134.40	
		less 20%	1626.88	20% 50%
			6507.52	
	SPECIAL NETT ITEMS			
1set	Rear Bumper clips		NEW 80.00	50
1	Reverse sensor		〃 280.00	X
1	Rear number plate w/base		〃 75.00	X
1set	RHS Rear fender inner trim clips		〃 60.00	X
1set	RHS Rear fender inner shield clips		〃 60.00	X
1set	Bootlid inner trim clips		〃 60.00	X
1	Rear windscreen sealant		〃 100.00	X
1	Rear end panel sealant		NEW 100.00	50
1	Rear spare tyre panel insulator		〃 120.00	X
		TOTAL PARTS	7442.52	

VEHICLE NO SKE 4073G HYUNDAI ELANTRA

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & components to commence repairs; panel beat & reshape the affected areas; replace damaged parts	1400.00	800
2	To supply paint materials, expandable items & putty, respray paint on parts replaced and repaired areas	1000.00	900
3	To remove, check and refix wiring at rear damaged areas	100.00	30
4	To remove and refix/replace inner trims,garnish and rear fittings etc. so as to facilitate repairs	250.00	80
5	To remove and refix rear bootlid components	100.00	X
6	To remove and replace reverse sensors and check for proper function	100.00	50
7	To remove and refix rear windscreen	140.00	X
8	To perform anti-rust treatment on affected areas	180.00	30
	Labour Total :	3270.00	
	TOTAL (PARTS & LABOUR):	10712.52	

3270

NOTE: The parts listed in this preliminary estimate will be checked for damage after the vehicle is disassembled (dismantle). Additional damaged parts (if any) will be submitted as supplemantary parts

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P - 2030.7
SOL
P - 1015.35
S.N - 100.00
L - 1890.00
3005.35