Kenneth
96910663

Not Authorised
Wing &
Pending After Rain
6 days

Sin Motor Repairs
Block 176, #05-07, Sin Ming Drive, Sin Ming Auto Care
Singapore 575721
Tel: 64533908, 64596902 Fax: 64536602

22/7/2020

ESTIMATION CLAIM REF. 101/SM/2020

THE INSURED : MR LIM ENG SIONG
MOBILE NO : 90088329

VEHICLE NO. SKQ3928J
DATE OF ACCIDENT : 21/07/2020 - 12.28PM
ALONG CTE - AUSTRALIA SCHOOL
MODEL : TOYOTA VIOS - 06/2007
CHASIS NO. MR053HY9305001899

NAME OF INSURANCE: NTUC INCOME INSURANCE CO-OPERATIVE LTD
POLICY NO. 5091503182-03
THIRD PARTY INSURANCE: INDIA INTERNATIONAL INSURANCE
AGAINST YOUR INSURED VEHICLE NO. GBA8235H

1)	REAR BUMPER	Rp	496.04
2)	REAR BOOT	Rp	653.91
3)	REAR TAILLAMP - 2 PCS*242.58	CRP	485.16
4)	EMBLEM E	Rp	44.53
5)	EMBLEM G	Rp	54.16
6)	TOYOTO LOGO	Rp	48.31
7)	OUTER HANDLE	CM	159.21
8)	INNER LOCK TOP	Dr	86.48
9)	INNER LOCK LOWER	Dr	28.99
10)	REAR BUMPER RELECTOR - 2PCS*81.63		163.26 ?
11)	REAR SIDE RETAINER - 2PCS *72.84	Dr	145.68
12)	REAR END PANEL	Rp	421.62
13)	REAR BOOT RUBBER	Dr/Rep	160.18 50%
14)	REAR BUMPER SENSOR	Rep/Chrm	90.00
	SUB-TOTAL:		3037.53
	LESS 25%		-759.38
	G-TOTAL: NETT:		2278.15

LABOUR CHARGES FOR KNOCKING, DISMANTLING AND RE-INSTALLATION OF REAR BUMPER / BOOT COVER/ END PANEL / SENSOR/ INNER LOCK/ HANDLE AND ETC 800.00 700

LABOUR CHARGES FOR SPRAY PAINTING ON REAR BUMPER/ BOOT/END PANEL AND TOUCH UP/POLISH ON NECESSARY PARTS. 850.00 800

G-TOTAL: $3,928.15

LKK Auto Consultants hereby notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Scanned with CamScanner