ASS. REC. BY: TGLim | REF: CC4/AIG2000772 3/Bea3 | Asker

ASSIGNMENT

From: | Date: 23/7/2020

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMC 8312 C

at Workshop m/s: Secon Auto Pro

of 100 Sungei Ang Dr #01-14

Insured:

Policy No.

Claims No.

Sum Insured: | Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 105,000/-

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: | Person Contacted: | Vehicle: IN / OUT

Veh No: SMC 8312C Yr Regn: 25/7/2018

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Mercedes Benz CLA 180 Coupe SC 1625 A/C: Insured / Std / NI / NA

Colour: White T/Radio: Insured / Std / NI / NA

Sp.Reading: 14247

Eng/No: 270910316706 14

C/No: WDD1173422N681563

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Harder / Jammed / Leaked / Burnt or

Brake: Harder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/40R18 R: 225/40R18 TURANZA

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	5 mm	R/Bal.	5 mm
L/Bal.	5 mm	L/Bal.	5 mm
D.O.A.	26/7/2020	D.O.I.	28/7/2020

Survey held at: Secon Autopro

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	NV 105,000/-
	PV 55,541/-
	NV 49,459/-

TGLim 19/8/2020

Date/Time, File Pass to? 1) ☐ : Preli. Report ☐ : Final Report

Date/Time, File Return to? 2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($) ☐ : Interview ($) ☐ : Tech. Invs ($) ☐ : Weekend ($)

Survey Fee:

Transportation: S+RS SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (=)