LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 263S

Qty	Description of Parts	Condition	Estimate By Workshop ($))	Our Adjusted ($)
	REPLACEMENT OF PARTS			
1	BUMPER COVER FRT	BUCKLED	747.20	747.20
1	BUMPER SPOILER FRT	SERVICEABLE	344.70	-
1	BUMPER RETAINER FRT LH	SERVICEABLE	101.40	-
1	HEADLAMP LH	SERVICEABLE	743.60	-
1	FENDER PANEL FRT LH	BENT	437.10	437.10
1	WHEELARCH FRT LH	SERVICEABLE	191.40	-
1	RADIATOR GRILLE	SERVICEABLE	969.90	-
1	RADIATOR GRILLE FRAME	SERVICEABLE	686.00	-
1	AIR CLEANER BOX	SERVICEABLE	464.20	-
1	AIR CLEANER HOSE	SERVICEABLE	175.85	-
1	AIR CLEANER LOWER	SERVICEABLE	271.26	-
	LESS 10% DISCOUNT		-513.26	-118.43
			4,619.35	1,065.87
	SPECIAL NETT ITEMS			
1	BUMPER CLIP FRT (SN)	NECESSARY	75.00	75.00
1	BUMPER RETAINER CLIP FRT LH (SN)	NOT NECESSARY	65.00	-
1	BUMPER SPOILER CLIP (SN)	NOT NECESSARY	60.00	-
1	WHEELARCH CLIP FRT LH (SN)	NOT NECESSARY	65.00	-
1	SET RADIATOR GRILLE SCREW (SN)	SERVICEABLE	55.00	-
1	SET RADIATOR GRILLE FRAME CLIP (SN)	NOT NECESSARY	60.00	-
1	FRONT LEFT TYRE RIM (SN)	SERVICEABLE	380.00	-
			760.00	75.00
	LABOUR			
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.		2,000.00	400.00
	TO TRANSFER OF FRONT FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH, COVER AND OTHER TO ENABLE REPAIR.	NOT NECESSARY	380.00	-

Report Ref No. CS/TP20008165/Ksf3e2

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Qty	Description of Parts	Condition	Estimate By Workshop ($))	Our Adjusted ($)
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		2,000.00	440.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	10.00
	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS.		250.00	30.00
			5,140.00	880.00
	GRAND TOTAL		**10,519.35**	**2,020.87**

	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			**1,600.00**

Report Ref No. CS/TP20008165/Ksf3e2

KSC

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.