LIM TAN MOTOR

ESTIMATE TO REPAIR

SURVEYOR NAME	:
DATE OF SURVEY	: 07.09.20 LKK
TIME OF SURVEY	:

VEHICLE NO. : PC 990 L
MAKE : TOYOTA
MODEL : HIACE HIROOF AUTO 14 SEATER
YEAR : 2011
CHASSIS NO : JTFST22P800011583

DATE : 2-Sep-20
DATE OF ACCIDENT : 1-Sep-20
THIRD PARTY REF SJW 2026 Z
THIRD PARTY REF FWD Singapore Pte Ltd FWD Singapore Pte Ltd

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount	
1 pc	rear bumper				$ Rep 396.80	✓
1 pc	rear bumper retainer				$ D/T 48.70	✓
1 pc	tail lamp lower ganish				$ Rel 88.90	✓
					$ 534.40	
	less 25 %				$ 133.60	
					$ 400.80	
					$ Sen 200.00	✓
1 pc	rear bumper sensor	S.Nett		(Bill)	$ 600.00	?
1 pc	co's logo	S.Nett			$ 450.00	200d
	To putty & spray paint.				$ 300.00	250d
	labour charges.				$ 1,950.80	
TG/VL	TOTAL					
	Not Authorised 1/Prep & Resurvey After Paint 2-3days					
					$ -	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Lim Tan Motor Pte Ltd
Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721
Tel: 65-64520893 Fax: 65-64569127 Email: edmund@LTM.sg
Co. Reg No. 199307277D GST Reg No. M2-0019086-0
This document must not be reproduced, in whole or in part, or disclosed to third party or parties without prior written consent of Lim Tan Motor Pte Ltd

Scanned with CamScanner