LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No.	AC2008071
INV Date	02/12/2020
Reference	CC4/FCI20009689/Aes3q2
Code	FCI2

PROFESSIONAL SERVICE FEE

Vehicle No.	SMU 983Z
Insured Veh.	SHC 8816A
Claim No.	D20003519MFSH
Policy No.	D-20094922MFSH
Accident Date	31/08/2020
Inspection Date	10/09/2020

Description	**Total**
Survey Inspection	338.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	**338.00**
GST (7%)	**23.66**
Grand Total	**361.66**

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Ref : CC4/FCI20009689/Aes3q2

Date : 02-12-2020

Code : FCI2

1.	Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	SHC 8816A	**Veh. Inspected**	SMU 983Z
	Policy No.	D-20094922MFSH	**Coverage ($)**	0.00
	Claim No.	D20003519MFSH	**Excess ($)**	0.00
	Assign From	CHRIS LIM	**Assign Date**	10/09/2020

2.	Vehicle Particulars & Condition			
	Make & Model	HYUNDAI ACCENT	**c.c**	1368
	Engine No.	HIDDEN	**Year of Reg.**	2020
	Chassis No.	KMHCU41BTKU481321	**Colour**	GREY
	Odometer	2283	**Steering**	IN ORDER
	Brakes	IN ORDER	**Modification**	STANDARD ALLOY RIM
	General	GOOD		

3.	Conditions of Tyres			
		Size	**Make**	**Balance**
	R/H Front Tyre	175/70 R14	KUMHO	6 mm
	L/H Front Tyre	175/70 R14	KUMHO	6 mm
	R/H Rear Tyre	175/70 R14	KUMHO	6 mm
	L/H Rear Tyre	175/70 R14	KUMHO	6 mm

4.	Description of Damages
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.

5.	General Information			
	Accident Date	31/08/2020	**Inspection Date**	10/09/2020
	Survey held at	CAS GARAGE PTE LTD NO. 1 KAKI BUKIT AVE 6, #02-22 AUTOBAY 417883 KAKI BUKIT		

5a.	Remarks
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b.	Estimate Days of Repair	
	ESTIMATED NORMAL PERIOD FOR REPAIR:	**3 Working Days**

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMU 983Z

Qty	Description of Parts	Condition	Estimate By Workshop ($))	Our Adjusted ($)
	REPLACEMENT OF PARTS			
1	REAR END PANEL	TO REPAIR SEE LABOUR	608.70	-
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	192.50	-
1	BOOTLID	TO REPAIR SEE LABOUR	1,198.60	-
1	BOOTLID INNER TRIM	NOT NECESSARY	285.10	-
2	BOOTLID HINGE @$145.80	NOT NECESSARY	291.60	-
2	BOOTLID OUTER STOPPER @$40.50	NOT NECESSARY	81.00	-
2	BOOTLID INNER STOPPER @$38.50	NOT NECESSARY	77.00	-
1	BOOTLID INNER TRIM	NOT NECESSARY	105.60	-
1	BOOTLID LOGO	NECESSARY	85.60	85.60
1	BOOTLID "ACCENT" EMBLEM	NECESSARY	79.50	79.50
1	BOOTLID WEATHERSTRIP	NOT NECESSARY	192.60	-
1	BOOTLID INNER LOCK	NOT NECESSARY	185.90	-
1	BOOTLID OUTER GARNISH	NOT NECESSARY	236.70	-
2	BOOTLID NUMBER PLATE LAMP @$80.90	NOT NECESSARY	161.80	-
1	REAR BUMPER	DEFORMED	679.80	483.00
1	REAR BUMPER REFLECTORS	NOT NECESSARY	154.60	-
2	REAR BUMPER SIDE RETAINERS @$75.90	NOT NECESSARY	151.80	-
1	REAR BUMPER REINFORCEMENT	CRACKED	698.90	390.80
2	REAR REINFORCEMENT BRACKETS @$69.70	NOT NECESSARY	139.40	-
2	TAILLAMP @$495.20	N/S CRACKED	990.40	395.00
2	TAILLAMP INNER SEALER @$38.50	NECESSARY (1 PC ONLY)	77.00	38.50
	LESS 20% DISCOUNT		-1,334.82	-294.48
			5,339.28	1,177.92
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
1	SET REAR NUMBER PLATE WITH CASING (SN)	NOT NECESSARY	50.00	-
1	SET BOOTLID INNER TRIM CLIPS (SN)	NOT NECESSARY	30.00	-
1	SET END PANEL TOP GARNISH CLIPS (SN)	NOT NECESSARY	30.00	-

Report Ref No. CC4/FCI20009689/Aes3q2

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Qty	Description of Parts	Condition	Estimate By Workshop ($))	Our Adjusted ($)
1	SET REVERSE SENSORS (SN)	DAMAGED	250.00	200.00
1	SET END PANEL TOP GARNISH CLIPS (SN)	NOT NECESSARY	30.00	-
2	END PANEL SEALANTS (SN)	NOT NECESSARY	80.00	-
2	SET TAILLAMP CLIPS @$30.00 (SN)	NECESSARY	60.00	20.00
			560.00	250.00
	LABOUR			
	TO RENEW DAMAGED PARTS,REPLACE,BEAT,WELD,REALIGN AND ALIGNE ALL PARTS.INCLUSIVE OF THE REPAIR OF REAR END PANEL AND BOOTLID.		1,200.00	300.00
	TO RESPRAY AFFECTED AREAS.		1,200.00	400.00
	TO TUFFCOAT AFFECTED AREA.	NOT NECESSARY	200.00	-
	TO REMOVE/REFIT INTERIOR UPHOLSTERY.		150.00	30.00
	LABOUR TO APPLY SEALANT TO THE AFFECTED AREAS.	NOT NECESSARY	150.00	-
	TO REMOVE/REFIT WIRING CHECKS ON TAILLAMPS.		120.00	30.00
	TO REMOVE/REPLACE REVERSE SENSORS AND DISTANCE SETTLING.		150.00	50.00
	TO REMOVE AND REPLACE/REFIT BOOTLID MECHANISM.	NOT NECESSARY	150.00	-
			3,320.00	810.00
	GRAND TOTAL		**9,219.28**	**2,237.92**

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			**1,750.00**

Report Ref No. CC4/FCI20009689/Aes3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMU 983Z **INSPECTION**

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMU 983Z **RE-INSPECTION**

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R