SME 2218X

Hi Victor ,

When the vehicle was sent in for repairs and when parts were dismantled, the sill panel was found to have sustained more serious damages than initially thought.

Please view resurvey photos on the sill panel which are already uploaded onto the mesiner system and also view the revised repair cost and let us have your opinion / approval.