LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805   Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

		Our File No:	CC3/TMI20010455/KTD3E2
		Date:	29/10/2020

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	ML000125
Claimant Vehicle No :	SHC5411D	**Insured Vehicle No :**	SLP8756Z
Date of Loss:	26/09/2020	Nature of Claim:	TP Claim No: M2004759

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	**SHC5411D**		
Make & Model:	RENAULT LATITUDE, 2.0 D dCi (A)	Engine No:	M9R8839C002047
Reg. Date:	04/11/2014 (Man. Year: 2014)	Chassis No:	VF1ABL15AUC279614
Colour:	Metallic White/Red	Odometer:	426519 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S$):	**Market Value/New Car Price**		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R14	Rear Tyre Size:	215/60 R14
Front Left Side:	Sailun 9 mm	Rear Left Side:	Sailun 8 mm
Front Right Side:	Sailun 9 mm	Rear Right Side:	Sailun 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,638.94	3,269.12	4,369.82	57.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,160.00	1,105.00	2,055.00	65.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S$)	**10,798.94**	**4,374.12**	**6,424.82**	**59.49**
Approved Total (Overridden) (S$)		**3,500.00**		
(S$)	10,798.94	3,500.00	7,298.94	67.59
+ GST 7.00/7.00% (S$)	755.93	245.00	510.93	67.59
Nett Amount (S$)	**11,554.87**	**3,745.00**	**7,809.87**	**67.59**

INSPECTION

Date of Assignment:	30/09/2020		
Date Inspected:	29/09/2020	Inspected At:	Trans-Cab Services Pte Ltd (HQ)
			2 Ang Mo Kio Street 63
			Singapore 569111
Estimated Period of Repair:	2.5 days		

Adjuster: KENNETH KONG   **Manager:**   DENISE TAY KWEE CHENG

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 27 Oct 2020)	
Parts: 143	RENAULT LATITUDE 2.0 D dCi (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code: (Unsubmitted, no print-code for SHC5411D)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*BUMPER COVER REAR	Buckled	561.70 FL	-	*561.70 FL
2	1		*BUMPER LOWER REAR	Dented / Cut	411.90 FL	-	*411.90 FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	98.10 FL	-	*- FL
4	1		*BUMPER BRACKET SIDE REAR	Serviceable	82.10 FL	-	*- FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	59.80 FL	-	*- FL
6	1		*BUMPER RETAINER LH REAR	Serviceable	54.20 FL	-	*- FL
7	1		*BUMPER BEAM REAR	Bent	547.80 FL	-	*547.80 FL
8	1		*BUMPER BEAM BRACKET LH REAR	Repair	114.50 FL	-	*- FL
9	1		*BUMPER BEAM BRACKET RH REAR	Repair	114.50 FL	-	*- FL
10	1		*BOOT REAR	Dented / Buckled	1,677.20 FL	-	*1,677.20 FL
11	1		*BOOT WEATHERSTRIP	Serviceable	178.20 FL	-	*- FL
12	1		*BOOT HINGE	Repair	254.20 FL	-	*- FL
13	1		*BOOT LOCK	Repair	246.60 FL	-	*- FL
14	1		*BOOT BADGE RENAULT	Necessary	82.40 FL	-	*82.40 FL
15	1		*BOOT BADGE	Necessary	95.80 FL	-	*95.80 FL
16	1		*TAILLAMP LH	Serviceable	401.40 FL	-	*- FL
17	1		*TAILLAMP RH	Serviceable	401.40 FL	-	*- FL
18	1		*OUTER PANEL REAR (END PANEL)	Repair	745.80 FL	-	*- FL
19	1		*OUTER PANEL REAR (END PANEL)TRIM	Serviceable	404.56 FL	-	*- FL
20	1		*SET PARKING AID	Serviceable	700.00 FS	-	*- FS
21	1		*SET REAR BUMPER CLIP	Necessary	90.00 FS	-	*75.00 FS
22	1		*SET BUMPER BRACKET CTR CLIP	Not Necessary	65.00 FS	-	*- FS
23	1		*SET BUMPER RETAINER CLIP RR	Not Necessary	75.00 FS	-	*- FS
24	1		*SET BUMPER BRACKET SIDE CLIP RR	Not Necessary	65.00 FS	-	*- FS
25	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	80.00 FS	-	*- FS
26	1		*SET BUMPER LOWER REAR CLIP	Necessary	90.00 FS	-	*65.00 FS
27	1		*BOOT STICKER TRANS-CAB	Necessary	80.00 FS	-	*30.00 FS
28	1		*BOOT STICKER 6555-3333	Necessary	80.00 FS	-	*30.00 FS
29	1		*SET TAILLAMP CLIP	Not Necessary	55.00 FS	-	*- FS
30	1		*REAR BUMPER PROTECTOR	Necessary	180.00 FS	-	*30.00 FS
31	1		*SET REAR LICENCE PLATE WITH HOLDER	Serviceable	140.00 FS	-	*- FS
32	1		*SET REAR END PANEL TRIM CLIP	Not Necessary	60.00 FS	-	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

	Repairer's	Reference
Sub Total (S$)	8,292.16	3,606.80
- List Item Discount on L Items 10.00/10.00% (S$)	653.22	337.68
Total Parts (S$)	7,638.94	3,269.12

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
	Labour Items			
1	**PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.**	New	1,200.00	400.00
2	**TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS**	New	250.00	30.00
3	**PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION**	New	1,200.00	600.00
4	**TO REINSTALL REAR BUMPER PARKING SENSOR**	New	170.00	60.00
5	**TO CHECK ELECTRICAL LIGHTING CONCERNED**	New	170.00	15.00
6	**TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST**	New	170.00	0.00
	Gross Labour Cost (S$)		**3,160.00**	**1,105.00**

Report was unsubmitted during this print-out.

< END OF ESTIMATES >