LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC2105905

INV Date 20/08/2021

Reference CC4/FCI20011593/Kes3q2

Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. GBD 153Y

Insured Veh. SHC 7174A

Claim No. D20004281MFSH

Policy No. D-20094921MFSH

Accident Date 20/10/2020

Inspection Date 05/07/2021

Description	**Total**
Survey Inspection	197.00
Digital Photographs	
Transportation	
Subtotal	**197.00**
GST (7%)	**13.79**
Grand Total	**210.79**

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Ref: CC4/FCI20011593/Kes3q2
Date: 20/08/2021
Code: FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 7174A	**Veh. Inspected**	GBD 153Y
Policy No.	D-20094921MFSH	**Coverage ($)**	0.00
Claim No.	D20004281MFSH	**Excess ($)**	0.00
Assign From	ERIC	**Assign Date**	26/10/2020

2. Vehicle Particulars & Condition

Make & Model	NISSAN NV350 (M)	**c.c**	2488
Engine No.	HIDDEN	**Year of Reg.**	2014
Chassis No.	JN1MC2E26Z0001626	**Colour**	WHITE
Odometer	330816 KM	**Steering**	IN ORDER
Brakes	IN ORDER	**Modification**	NIL
General	GOOD		

3. Conditions of Tyres

	Size	**Make**	**Balance**
R/H Front Tyre	195R15X8	HANKOOK	7 mm
L/H Front Tyre	195R15X8	HANKOOK	7 mm
R/H Rear Tyre	195R15X8	HANKOOK	7 mm
L/H Rear Tyre	195R15X8	HANKOOK	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	20/10/2020	**Inspection Date**	05/07/2021
Survey held at	CITY AUTO PTE LTD BLK 8, SIN MING IND. ESTATE #01-60/62 Sector C SINGAPORE 575643.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBD 153Y

Qty	Description of Parts	Condition	Estimate By Workshop ($))	Our Adjusted ($)
	REPLACEMENT OF PARTS			
1	REAR SIDE PANEL -RH (N)	TO REPAIR SEE LABOUR	1,793.40	-
1	REAR BUMPER (N)	BUCKLED / DENTED	800.50	800.50
1	REAR BUMPER RETAINER (N)	NOT NECESSARY	147.00	-
	LESS 10% DISCOUNT		-274.09	-80.05
			2,466.81	720.45
	SPECIAL NETT ITEMS			
1	COMPANY LOGO (SN)	NECESSARY	280.00	80.00
			280.00	80.00
	LABOUR			
	TO KNOCK JACKOUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW ACCIDENT PARTS.INCLUSIVE OF THE REPAIR OF REAR SIDE PANEL -RH .		800.00	500.00
	SPRAY PAINTING ON AFFECTED & REPLACE PARTS.		700.00	400.00
			1,500.00	900.00
	GRAND TOTAL		**4,246.81**	**1,700.45**

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			**1,350.00**

Report Ref No. CC4/FCI20011593/Kes3q2

KSC

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBD 153Y **INSPECTION**

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R