ASS. Rec. By: GQ

REF: CS3/AIG20009162/Gqf3-1

PRS

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / MS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s GOLD AUTOWERKZ

of

Insured:

Policy No. 1800042163

Claims No. 5905216335SG

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SGZ 76L Yr Regn: 29 Jul/2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: TOYOTA HARRIER c.c 1986

Colour Black A/C: Insured / Std / NI / NA

Sp.Reading 63446 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: ZSU600078503 *

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 255/45R20

R: 255/45R20

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or FALKEN

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.		D.O.I.	01-09-2020

Survey held at W/S 3:15pm

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Yes/No BI Involved
	Submit DAR.
09/12/20	Submit LS $4400, 6 days (Red $1970, 31%)

Date/Time, File Pass to?

1) 09/12 Typist

Date/Time, File Return to?

2)

☐ : Preli. Report

☐ : Final Report

Days Of Repair: 6

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Insp ($)

☐ : Weekend ($)

Survey Fee:

Transportation: ___$ + RS.___SI

Photos

Others

TOTAL

Report Format: MER-TP

Lump Sum Value: 4400