LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBL 9271M

Qty	Description of Parts	Condition	Estimate By Workshop ($))	Our Adjusted ($)
	REPLACEMENT OF PARTS			
1	WINDSHIELD	DENTED / CUT	120.00	120.00
1	FRONT COVER	SERVICEABLE	180.00	-
1	FRONT SIDE FAIRING (L)	MTG CRACKED	320.00	320.00
1	FRONT SIDE PLASTIC COVER (L)	DENTED / CUT	150.00	150.00
1	INNER SIDE COVER (L)	CRACKED	225.00	225.00
1	HANDLE BAR	TO REPAIR SEE LABOUR	130.00	-
1	SET HANDLE BALANCER	DENTED	50.00	50.00
1	BRAKE LEVER (L)	DENTED	75.00	75.00
2	FRONT FORK INNER TUBE (L)	DISTORTED / JAMMED	420.00	420.00
1	FRONT MUDGUARD (L)	DENTED / CUT	180.00	180.00
1	FENDER PLASTIC COVER	CUT	110.00	110.00
1	HEAD LIGHT	SERVICEABLE	380.00	-
1	SIGNAL LIGHT (L)	CRACKED	200.00	200.00
1	MIRROR (L)	DENTED	80.00	80.00
1	BOTTOM COVER (L)	SERVICEABLE	230.00	-
1	FLOOR BOARD	SERVICEABLE	250.00	-
1	BOTTOM SIDE BOARD	CRACKED	280.00	280.00
1	BELTING COVER	DENTED / CUT	265.00	265.00
1	AIR CLEANER BOX	DENTED / CUT	350.00	350.00
1	BOX LOCK	MISSING	25.00	25.00
1	SIDE BOARD (L)	CUT	280.00	280.00
1	SIDE STAND	TO REPAIR SEE LABOUR	95.00	-
	LESS 10% DISCOUNT		-	-313.00
			4,395.00	2,817.00
	SPECIAL NETT ITEMS			
1	SET FORK OIL SEAL & FORK OIL (SN) (50%)	NECESSARY	70.00	35.00
			70.00	35.00

Report Ref No. CS/SMO20012939/Ktd3e2

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Qty	Description of Parts	Condition	Estimate By Workshop ($))	Our Adjusted ($)
	LABOUR			
	TOWING.		50.00	30.00
	LABOUR. INCLUSIVE OF THE REPAIR OF HANDLE BAR AND SIDE STAND.		350.00	180.00
			400.00	210.00
	GRAND TOTAL		**4,865.00**	**3,062.00**

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			**2,450.00**

Report Ref No. CS/SMO20012939/Ktd3e2

KSC

KONG SENG CHEONG

Licensed Appraiser